# 

**DECEMBER 1978 • \$1.00** 

#### **ELECTRONIC TECHNICIAN/DEALER**

LEADING THE CONSUMER AND INDUSTRIAL SERVICE MARKETS



KOWR2505 664-X2-47938A4M -676-RAY KOWECK 27734 DENMAR

AA APR79 AS MI 48093

## STATIC PROFITS? TUNE TO PTS

Tune In a clearer profit with four new profit-makers from PTS, and you'll discover four ways to higher profits with PTS.



#### **REPLACEMENT BALUNS**

A new profit-maker from PTS that will more than pay for itself after you sell the first two baluns. Selection of seven replacements (five models) will replace most baluns found in TV sets, antenna systems, MATV or CATV systems.

Dealer Net. \$9.75.



#### **PTS 8001 COMPONENT ANALYZER**

This component test instrument works in or out of circuit. Simple hook-up to any standard oscilliscope. High, medium and low range switch for matching impedance.

Dealer Net \$54.95.



#### PTS DG-I DIGITAL POWER SUPPLY

External power supply for substituting voltages in televisions, stereos, radios, computers, micro-processors, appliances, CBs and many other electronic units.

Dealer Net. \$114.95.



## PTS DG-4 VOLTAGE CONTROL CENTER/DIGITAL POWER SUPPLY

Independently produces four variable DC supply voltages. Excellent for substituting critical control voltages for TV electronic/varactor tuners, and many other electronic products.

Dealer Net \$178.50.

### TUNE ON TO MORE PROFIT, THE PTS WAY.

Now available from PTS stocking distributors or at any of the PTS' 42 company-owned Servicenters. Check the Servicenter Guide on the opposite page.



PTS ELECTRONICS, INC.

## **PTS** SERVICENTER **GUIDE**

MIDWEST

216-845-4480
KANSAS CITY, KS 66106
119A Merriam Lane, P.O. 6149
913-831-1222
MINNEAPOLIS, MN 55408
815-W. Lake St., P.O. 8458
618-824-2333
ST. LOUIS, MO 63130 8456 Page Blvd., P.O. 24256 314-428-1299

DETROIT, MI 48235 13707 W. 8-Mile Rd. 313-862-1783 GRAND RAPIDS, MI 49501 Walker Northwest P.O. 1435

P O. 1435 616-454-2754 CINCINNATI, OH 45216 8172 Vine St., P O. 16057 513-821-2298 MILWAUKEE, WI 53218 7211 Fond du Lac 414-464-0789 COLUMBUS, OH 43227 4005A E Livingston 614-237-3820 INDIANAPOLIS, IN 46202 257

406 N. Pennsylvania Ave 317-631-1551 DAVENPORT, IA 52803 2024 E. River Dr 2024 E River Dr 319-323-3975 OMAHA, NE 68132 5008 Dodge Street

402-558-1800 CHICAGO, IL 60659

SOUTH

ATLANTA, GA 30318 1240 Techwood Drive N.W P O 93887 404-873-1787

404-873-1787

JACKSONVILLE, FL 32210

918 Blanding Blvd., P. O. 7923

904-389-9952

WASHINGTON, DC

Silver Spring, MD 20910

8880 Brookville Rd

301-565-0025

CHARLOTTE, NC 28225

725 Seigle Ave. P. O. 5512

726 Seigle Ave . P O. 5512 704-332-8007 BIRMINGHAM, AL 35201 210 N 9th St., P.O 1801 205-323-2657

205-323-2657 MEMPHIS, TN 38118 3614 Lamar Ave., P.O. 18053 901-365-1918 NORFOLK, VA 23504 3118 E. Princess Anne Rd. 804-625-2030 NEW ORLEANS METALE LA 70004

Metalrie, LA 70004 3920A Airline Hwy , P O 303 504-837-7569 TAMPA, FL 33690 2703 S Macdill, P O 14301 av 2.830.5591

813-839-5521 NASHVILLE, TN 37214 615-885-0688

PACIFIC

BLOMINGTON, IN 47401 4351D Auburn BIVJ., P.O. 41354 5233 S. Hwy. 37. P.O. 272 812-824-9331 SAN DIEGO, CA 92105 918-482-6220 912-824-9331 SAN DIEGO, CA 92105 CLEVELAND, OH 44134 5111 University Ave. P. O. 5794 714-280-7070 TANCES 1218 100 ANGEL 114-280-7070 LOS ANGELES, CA 90023 4184 Pacific Way 213-266-3728 PORTLAND, OR 97213 5220 N.E. Sandy Blvd P.O. 13096 503-282-9636 SEATTLE, WA 98188 988 Industry Dr. (Bldg. 28) P.O. 88831 - Tukwila Branch

NORTHEAST

206-575-3060

SPRINGFIELD, MA Westfield MA 01085 300 Union St., P.O. 238 413-562-5205 PHILADELPHIA Upper Darby, PA 19082 1742-44 State Rd., P.O. 207 215-352-6609

215-352-6609 PITTSBURGM, PA 15202 Riverview Ave. W., P.O. 4 412-761-7648 E. PATERSON, NJ 07407 158 Markel St., P.O. 421 201-791-6380 8UFFALO, NY 14214 299 Parkside Ave 716-837-1656

BOSTON CHICAGO, IL 60659 Arlington, MA 02174 5744 N. Western Ave. 1167 Massachusetts Ave., P.O. 37 312-728-1800 617-648-7110

8ALTIMORE, MD 21215 Reisterstown Rd., P.O. 2 301-358-1186

MOUNTAIN

DENVER
Arvada, CO 80001
4958 Allison St., P.O. 672
303-423-7080
SALT LAKE CITY, UT 84106 Wilmington Ave P.O. 6218 801-484-1451

PHOENIX, AZ 85009 2916 West McDowell R vell Bd 602-278-1218

SOUTHWEST

LONGVIEW, TX 75601 110 Mopac Rd., P.O. 7332 214-753-4334 OKLAHOMA CITY, OK 73147 4509 N.W. 10th, P.O. 74917 405-947-2013 HOUSTON, TX 77207 4326 Telephone Rd., F., 713-644-6793 P.O. 26616



Circle No. 122 on Reader Inquiry Card

## INDUSTRY REPORT

#### Moch Named Head of Warranty Watchdog Committee

The Consumer Electronic Council, a group comprised of large warranty servicers and three national associations-NARDA, NATESA, and NESDA-has named Frank J. Moch head of its warranty watchdog commit-

Moch, the executive director of NATESA, was elected at a reorganization meeting of the council held recently in Chicago. The purpose of the special council is to acquaint manufacturers with specific implementation problems designated by the council as "contrary to the interests of the set purchasers and all elements of the home electronics industry."

According to a statement from the council, 17 specific warranty problems have already been identified, "six of which are particularly onerous." Moch said each alleged violator will be privately contacted in an effort to gain warranty problem modifications.

The council has already sent large warranty service organizations across the United States a questionnaire on the specific warranty practices of 10 television receiver manufacturers. The manufacturers on which data is being collected are Admiral, GE, Panasonic, Quasar, RCA, Sony, Sylvania, Zenith, MGA, and Sharp.

#### JVC Unveils Capacitive Pickup Video Disc System

A grooveless, capacitive pickup video disc system, capable of playing onehour of color television programming per side, has been announced by Victor Company of Japan (JVC).

According to JVC, the player is connectable to any "ordinary" color television receiver. It plays a 12-inch plastic disc that may be recorded with color television programming or pulse code modulated stereo.

The basic features of the JVC system

Picture and sound informationincluding PCM stereo-are recorded as pits on the disc surface via laser beam. For playback, information and tracking signals are simultaneously picked up electronically as capacitance variations between the disc surface and an electrode on the tracking stylus.

The tracking stylus, JVC says, is located in a cantilever arm which is servo controlled to track the imaginary grooves and to correct for the time base



error of the rotating disc via an electrotracking system.

According to JVC spokesman engineering studies indicated a system for both home and industrial use would be the most advantageous. "In other words, we wanted a system which our industrial and domestic consumers would welcome.'

#### FCC Seeks More Data on AM Stereo

/The FCC says it wants more data plus some persuasion of the "need" for AM stereo before it makes any hard and fast dicisions concerning competing systems and authorization.

Citing "great interest" for AM stereo on the part of some manufacturers and broadcasters, the commission noted a similar lack of interest on the part of the

Going so far as to question the need for AM stereo, the FCC requested more data on the price impact on the public plus, it said, many technical standards remain unresolved. Among the deficiencies noted were the impact of the reduction in AM bandwidth and channel spacing under international law, the effects on listeners who depend solely on skywaves, and receiver compatibility.

The FCC's chief engineer, Raymond Spence, asked the question who wants AM stereo except perhaps manufacturers and broadcasters?

#### IHF Speeds Work on Technical **Standards**

The Institute of High Fidelity, an organization consisting of manufacturers of stereo components, says it is taking steps to speed the development of its technical standards program.

IHF President Jerry Kalov, president of Jensen Sound Laboratories, says, because of the growing need "for more such industry standards" the IHF Board of Directors has activated standards committees for turntables, cassette recorders, and speakers. This, he said, is considered one of the most valuable programs for the development of comprehensive high fidelity standards.

One of the committees has already met, according to Kalov, and has set initial goals for the development of standards for turntables. A first order of busi-



#### ELECTRONIC TECHNICIAN/DEALER

LEADING THE CONSUMER AND INDUSTRIAL SERVICE MARKETS

**DECEMBER 1978, VOL. 100, NO. 12** 

RICHARD W. LAY Editor

WALTER H. SCHWARTZ Managing Editor

ALFRED A. MENEGUS Publisher

> DAVID J. HAGELIN Associate Publisher

TOM GRENEY **Publishing Director** 

> JOHN PASZAK Graphic Design

KATHY TARNOWSKI Production Manager

LILLIE PEARSON Circulation Fulfillment



On the cover: With the colors of the approaching holiday season on our cover, the staff of ET/D extends to one and all best wishes for the coming year.

### FEATURES

They're popping up all over the place	
Microprocessor technology  ET/D's continuing series on consumer applications	

Zenith's systems III A 100 percent modular, chassisless TV

An alphabetized reference for the past year

ET/D's 1978 subject reference index

### DEPARTMENTS

INDUSTRY REPORT	1
FROM THE EDITOR'S DESK	6
LETTERS	8
NEWSLINE	9
SERVICE SEMINAR	10
BULLETIN BOARD	38
TEST INSTRUMENT REPORT	40
DEALERS SHOWCASE	42
NEW PRODUCTS	44
CLASSIFIED ADS	46
ADVERTISING INDEX	48
READERS SERVICE	49
TEKFAX	51

HBJ A HARCOURT BRACE JOVANOVICH PUBLICATION

SABP (ABC)





12

20

28

32

HARCOURT BRACE JOVANOVICH PUBLICATIONS. Robert L. Edgell, Chairman, Richard Moeller, President, Arland Hirman, Treasurer, Lars Fladmark, Senior Vice President, Joe Bilderhach, Vice President, James Gherna, Vice President, George Glenn, Vice President, Thomas Greney, Vice President, Ezra Plncus, Vice President, Harry Ramaley, Vice President, Lols Sanders, Vice President, Flore Resident, Flore Res

ELECTRONIC TECHNICIAN/DEALER (USPS 172360) is published monthly by Harcourt Brace Jovanovich Publications. Corporate offices: 757 Third Avenue, New York, New York 10017. Advertising offices: 757 Third Avenue, New York, New York 10017 and 43 East Ohio Street, Chicago, Illinois 60611. Editorial offices: 43 East Ohio Street, Chicago, Illinois 60611. Accounting, Advertising Production and Circulation offices: 1 East First Street, Duluth, Minnesota 55802, Usbscription rates: one year, 59, two years, \$15, three years, 519, in the United States and Canada. All other countries: one year, 520, two years, 535, three years, 545. Single coples: 51 in the United States and Canada: all other countries: 53. Application to mail at Controlled Circulation postage rates is pending at Dansville, New York 14437. Copyright © 1978 by Harcourt Brace Jovanovich, Inc. All rights reserved. No part of this publication may be transmitted or reproduced in any form or by any means, electronic or mechanical, including photocopy, recording or any information storage and retrieval system, without permission in writing from the publisher. ELECTRONIC TECHNICIAN/DEALER is a registered trademark of Harcourt Brace Jovanovich, Inc.

POSTMASTER: Send Form 3579 to ELECTRONIC TECHNICIAN/DEALER, P.O. Box 6016, Duluth, MN 55806.

## AMERICA'S LARGEST SUPPLIER

of **ORIGINAL** Japanese Semi-Conductors for CB, TV and Stereo Repair

We carry only genuine replacement parts

IYPE	25-UP	10-24	1-9	TYPE	25-UP	10-24	1-9	TYPE	25-UP	10-24	1-9	TYPE	25-UP	10-24	1-9
2SA 102	.20	.27	.30	2SC 696	1.00	1.20	1.30	2SD 234	.60	.70	.80	TA 7205P	1.60	1.80	2.00
2SA 234	.45	.53	.59	2SC 710	.20	.27	.30	2SD 235	.60	.70	.80	TA 7310P	1.30	1.45	1.60
2SA 473	.45	.53	.59	2SC 711	.20	.27	.30	2SD 261	.35	.40	.45	TBA 810SH	1.90	2.10	2.40
2SA 484	1.50	1.75	1.95	2SC 730	3.00	3.20	3.40	2SD 287	2.50	2.70	2.90	TC 5080P TC 5081P	5.00 3.00	5.20 3.20	5.80 3.40
2SA 495	.30	35	40	2SC 732	.20	.27	.30	2SD 313 2SD 315	.60 .60	.70 .70	.80	TC 5082P	3.40	3.55	3.90
2SA 497	1.00	1 20	1 30	2SC 735	.20	1.80	.30	2SD 315 2SD 325	.60	.70	.80	UHIC 002	4.20	4.40	4.90
2SA 509 2SA 561	.30	35 35	40	2SC 756 2SC 756A	1.50	1.80	2.00 2.00	2SD 323	1.80	2.00	2.25	UHIC 004	4.20	4.40	4.90
2SA 561	30	35	40	2SC 781	1.90	2.10	2.40	2SD 525	.90	1.10	1.20	UHIC 005	4.20	4.40	4.90
2SA 564A	20	27	30	2SC 784	.30	.35	.40	2SD 526	.60	.70	.80	UPC 20C	2.10	2.50	2.80
2SA 634	40	45	50	2SC 799	2.00	2.20	2.50				-	UPC 563	1.90	2.10	2.40
2SA 643	30	40	45	2SC 828	.20	.27	.30		FET			UPC 575C2	1.30	1.45	1.60
2SA 673	35	40	45	2SC 839	.30	.35	.40					UPC 576 UPC 592HZ	1.90 .70	2.10	2.40 .90
2SA 678	35	40	45	2SC 867	3.20	3.40	3.70	2SK 19BL	.45	.55	.60 90	UPC 1001	1.90	2.10	2.40
2SA 682	.80	9C	1 00	2SC 867A	3.20	3.40	3.70	2SK 23	70	.80	.50	UPC 1008C	4.20	4.40	4.90
2SA 683	30	35	40	2SC 897	2.00	2.20	2.50	2SK 30 2SK 33	.60	.70	.80	UPC 1020H	1.90	2.10	2.40
2SA 684	.35	40	45	2SC 930	.20	.27	.30	2SK 55	.60	.70	.80	UPC 1025H	1.90	2.10	2.40
2SA 695	.40	53 64	59 70	2SC 945 2SC 983	.20	.27	.30 70	3SK 22Y	1.40	1.60	1.80	UPC 1154	2.00	2.20	2.50
2SA 699A 2SA 706	.85	1 0(	1 10	2SC 983 2SC 959	1 10	1.20	1 30	35K 39	90	1 10	1.20	UPC 1155	2.00	2.20	2.50
2SA 706 2SA 719	30	35	40	2SC 1000BL	35	40	45	35K_40	90	1 10	1.20	UPC 1156	1.90	2.10	2.40
2SA 720	30	3:	40	2SC 1014	50	64	70	35K 11	1.0	1 45	1.60	UPC 14305	3.00	3.20	3.40
2SA 733	.20	27	<b>A</b> 0	2SC 1018	60	70	.80	35K 45	1.30	1.45	1.60	UPD 861	8.00	8.40	9.50
2SA 747	4.20	4 40	190	2SC 1030C	1.80	2,10	2 40	35K, 48	3.40	1 55	3.90	UPD 857	8.00	8.40	9.50
2SA 818	.70	80	90	2SC 1061	70	.80	.90	3SK 49	1.30	1 45	1.60	UPD 858	6.00	6.30	7.00
2SA 841	20	2:	30	2SC 1079	3.40	3.55	3.90					PLL 01A PLL 02A	3.00 5.00	4.20 5.30	4.60 5.90
				2SC 1096	.45	55	.60		IC			PLL 02A	7.60	8.00	8.80
	2SB			2SC 1098	.50	.64	70	AN 2140	1.30	1.70	1.90	PEE USA	7.00	8.00	0.00
400.00	20	25	40	2SC 1111	2.10	2.50 90	2.80 1.00	AN 214Q AN 239	4.20	4 40	4.90		DIODI	ES	
2SB 22 2SB 54	30 20	35 l 27	.30	2SC 1124 2SC 1172B	.80 3.20	3 60	3.95	AN 247	2.50	2 70	5 00				
2SB 54 2SB 75	35	40	.45	2SC 1172B	50	55	60	AN 274	1.50	1 75	1 95	1S 84	.45	.55	60
2SB 175	20	2"	.30	2SC 1226	50	55	60	AN 313	3.00	3.20	3.40	15 332	35	.40	.45
2SB 186	20	.27	.30	25C 1226A	.50	-55	60	AN 315	1.80	2 00	25	1S 953	16	.18	.20
2SB 324	30	.35	.40	2SC 1239	2.20	2.70	2.90	BA 511A	1.80	2 00	2.25	1S 1007	.35	.40	.45
2SB 337	.70	.80	.90	2SC 1306	1.30	1.45	1.60	BA 521	1.90	2 10	2.40	1S 1209	35	.40	.45
2SB 405	30	.35	.40	2SC 1307	1.90	2.10	2.40	HA 1151	1.50	1.75	1.95	1S 1211 1S 1555	35 .20	.22	.45
2SB 407	.80	90	1.00	2SC 1318	35	.40	.45	HA 1156	1.60	1.80	2.00 2.50	1S 1588	.20	.22	.25
2SB 434	.80	.90	1.00	2SC 1383	30	.35	.40	HA 1306W HA 1322	2.50	2.20	3.00	15 1885	16	.18	.20
2SB 435	90	1 10	1.20	2SC 1384	35	40	45	HA 1322	2.50	2 70	3.00	1S 2076	.20	.22	.25
2SB 463 2SB 473	.90	1 10 . 90	1.20	2SC 1419 2SC 1675	60 20	.70 27	.30	HA 1339A	2 50	2.70	3.00	1S 2093	.35	.40	.45
2SB 474	.70	80	.90	2SC 1678	1.10	1.25	1.40	HA 1366	2.50	2 70	2.90	15 2473	16	.18	.20
2SB 492	.60	70	.80	2SC 1728	70	.80	.90	HA 1366W	2.50	2.70	2.90	1N 34	12	.13	15
2SB 507	.80	90	1.00	2SC 1730	.45	.53	.59	HA 1366WR	2.50	2.70	2.90	1N 60	.12	.13	15
2SB 528D	.70	80	.90	2SC 1760	.70	.80	.90	LA 4031P	1.80	2.00	2.25	10D 1	.30	.35	.40
2SB 595	1.10	1 40	1.50	2SC 1816	1.50	1.75	1.95	LA 4032P	1.80	2.00	2.25	10D 10	.45	.55	.60
2SB-596	1 10	1.40	1.50	2SC 1856	.50	.64	.70	LA 4400	1.90	2.10	2.40	V06B	.30	.35	.40
				2SC 1908	.30	.35	.40	LA 4400Y	2.00	2.20	2.50 2.50		ZENE	35	
	2SC			2SC 1909	1.80	2.00	2.25	LA 4420 M51513L	2.00	2.20	2.50		EFIVE		
2SC 281	.30	.35	.40	2SC 1945 2SC 1957	4.50	5.00	5.60 .80	STK 011	3.80	4.00	4.40	WZ 071	20	22	25
2SC 281 2SC 372	.20	27	.40	2SC 1937 2SC 1970	2.10	2.50	2.80	STK 013	7.60	8.00	8.80	WZ 075	20	22	25
2SC 372	20	27	30	2SC 1978	5.40	6.00	6.60	STK 015	4.20	4.40	4.90	WZ 090	20	22	25
2SC 380	20	.27	30	2SC 2028	.50	.64	.70	STK 435	4.50	5.00	5.60	WZ 120	20	22	25
2SC 394	20	.27	.30	2SC 2029	1.50	1.80	2.00	TA 7045M	2.00	2.20	2.50	WZ 192	20	22	25
2SC 458	20	27	.30	2SC 2076	.50	.64	.70	TA 7060P	70	.80	.90				
2SC 495	45	55	60	2SC 2091	.90	1.10	1.20	TA 7061P	.90	1 10	1.20		MIS	О.	
2SC 509	35	40	.45	2SC 2092	1.80	2.00	2.25	TA 7062P	1 10	1.25	1.40				
2SC 515A	80	90	1.00	2SC 2166	1.40	1.60	1.80	TA 7089P	2.00	2.20	2.50	SG 613	5 20	5 40	5 95
2SC 517	2 50	2 70	3.00		2SE			TA 7202P	2.50	2 70	2.90 2.90	78LO5	90	1 00	1 10
2SC 535	30	35 40	.40	2SD 72	100	64	70	TA 7203P TA 7204P	2.50	2 70	2.50	MPS U31	1 50	1 70	1 90
2SC 634A	35														

Minimum order \$5.00. Add \$1.00 postage and handling. Ask for our complete price list when ordering. Overseas buyers, Manufacturers. Distributors or Dealer orders welcome. All parts are guaranteed against factory defects for one year. C.O.D. orders are welcome. 48-hour delivery.

### ORDER TOLL FREE



ness will be development of a glossary of terms, the separation of such terms into groups, the development of standard test conditions, and development of a set of measurement standards for the various groups.

## Zenith Reports Improved Financial Results

Zenith Radio Corporation has reported improved third quarter financial results for the period ending Sept. 30.

According to Zenith's consolidated statements of income, net sales were up 12.2 per cent to \$276.6 million during the three months period while net income showed a profit of \$6.4 million—or 34 cents per share, compared with a 69 cents per share loss for the corresponding period a year earlier.

For the nine months period, sales were up slightly to \$703.4 million while earnings showed a per share increase of 46 cents, to 70 cents per share, on 18.8 million shares outstanding.

## Winter CES to Feature Audio Merchandising

Next month's Winter Consumer Electronics Show, Jan. 6-9 in Las Vegas, will feature expanded emphasis on retail merchandising programs of consumer electronics products...especially in the highly competitive audio field.

According to Jack Wayman, Senior

Vice President of CES, about half of the 31-scheduled hours of showtime will be devoted to "consumer electronics product knowledge, retail store management and sales development."

Each of the four mornings of the show—starting Saturday Jan., 6—will be devoted to two separate retail and merchandising conferences. Starting off on the 6th will be Personal Communications at 8:30 a.m., followed by the Telephone Devices conference at 10:30.

The following days' conferences will be audio systems and auto sound; television, projection TV and video systems; and personal computers, TV games, calculators and watches.

CES also reports that for the benefit of attendees a special "retail idea center" will be on the convention floor and will feature 100 of the most outstanding retail merchandising techniques. This includes theme promotions, retail advertising campaigns, direct mail, community relations, store design and product display.

Also, according to sopkesmen for the show, a CES retail resource center will offer attendees an opportunity to consult with 15 exhibitors who provide nation-wide retail store services such as financing, store design and lighting, freight bill auditing service, retail management services, merchandising aids, and retail sales training. £700



Richard W. Lay, Editor (Chicago)

Walter H. Schwartz, Managing Editor (Duluth)

Alfred A. Menegus, Publisher (New York)

David Hagelin, Assoc. Publisher (Chicago)

Tom Greney, Group Vice President (Chicago)

John Paszak, Graphic Design

Kathy Tarnowski, Production Manager

Karen Cranmer, Prod. Supervisor

Lillie Pearson, Circulation Supervisor

Gene Bailey, Reader Service

Ed Schultheis, Promotion Director

Dawn Anderson, Classified Ad Mgr.

Please submit editorial manuscripts to: Editor, ET/D, 43 East Ohio St. Chicago, III., 60611

#### **ADVERTISING SALES**

Please send advertising material to: ET/D, Production Mgr. 1 East First Street Duluth, Minn. 55802 (218) 727-8511

East Region Alfred A. Menegus 757 Third Avenue New York, N.Y. 10017 (212) 888-4382

Midwest Region
David J. Hagelin and
Thomas P. Kavooras, Jr.
43 East Ohio Street
Chicago, Ill. 60611
(312) 467-0670

Southern & Western Region Chuck Cummings 613 N. O'Connor Irving, TX 75061 (214) 253-8678

HBJ

### HARCOURT BRACE JOVANOVICH PUBLICATIONS

Robert L. Edgell, Chairman
Richard Moeller, President
Lars Fladmark, Senfor Vice President
Arland Hirman, Treasurer
Joe Bilderbach, Vice President
James T. Gherna, Vice President
George A. Glenn, Vice President
Thomas Greney, Vice President
Ezra Pincus, Vice President
Harry D. Ramaley, Vice President
Lois Sanders, Vice President



## ATTENTION SERVICE DEALERS

#### Buy Directly ●

Top Line Solid State Replacements, Original Japanese Transistors and Integrated Circuits

#### PARTIAL LIST \* MONTHLY SPECIALS

Part	Your	Part	Your	Part	Your
Number	Cost	Number	Cost	Number	Cost
AN 214 AN 247 TA 7205 2SA 495 2SA 643	2.50 1.80 .35	2SB 474 2SC 756A 2SC 799 2SC 1096 2SC 1358	1.80 1.95 .55	2SC 1383 2SD 72 2SD 2°2 2SK 23A 121-831	.30 .70 2.50 .70 4.50

Free gift with every \$25 purchase!


#### Send for our complete list of Japanese parts and prices

- Our Professional Replacement parts are top quality and replace over 130,000 industry types at a substantial savings to you over most other replacement lines.
- To order, just send us the ECG, SK, GE, or other part number and we will promptly ship
  you the premium PR direct replacement, plus a free PR replacement guide.
  Remember—these are first quality parts—no culls, no seconds! 2 year warranty on all
  parts.
- Orders over \$25.00 shipped free, under \$25 add \$1 UPS. C.O.D. orders are welcome.
   To approximate the cost of a replacement part order, deduct 40% from dealer cost of ECG or other types. All orders shipped within 24 hours.

Write or Call-Toll Free 800-526-4463

DEVCO

P.O. Box 270, Garwood, NJ 07027 • (201) 688-0300



# FROM THE EDITOR'S DESK



I suppose I could start this editorial with the traditional saying that as the end of another year approaches, it seems a good time for all of us to pause and reflect on our accomplishments during the past 12 months.

I could, but won't ... simply because none of us in this industry has very much time for reflecting.

What we will recall about 1978 though, as the years go by, is that if it is at all possible to pin any kind of a label on it, insofar as the consumer and home entertainment electronics service industry is concerned, it should rightfully be known as the year of the digital IC.

Already completed as we entered 1978 was the transformation of the major analog signal processing circuitry—sound, video, chroma, from transistors to integrated circuits. In most cases on-board voltage regulators were already in place to help confuse the uninitiated.

The new year brought the wholesale influx of electronic digital tuning into America's living rooms, including late this year, digitally synthesized tuning from RCA and Zenith's on-circuit-board electronic tuning system.

Just a very few years ago (1973) we witnessed the last of the electron tube television sets roll off the assembly line to be followed by transistorized versions. We now see the advance of the digital IC into the frequency (horizontal and vertical) control sections of the home TV receiver in the form of more counters and dividers.

Even a new commercially viable system for processing video and color information in the receiver (Magnavox's comb filter) is with us. And, already the micro-processor is upon us. Programmable microwave ovens; programmable stereo components; programmable home blenders, etc., etc.

Get the picture?

Over the last year ET/D has had the priviledge of trying to keep track of the accelerating pace of change in our industry—and passing what we have learned on to you.

Really—what it all boils down to is an educational crisis for most of us associated with consumer electronics.

Where can the modern serviceshop of today and the proficient technician, get the kind and quality education he needs to continually upgrade his electronic skills.


This is an area that is now clearly emerging as one of the very most important facing the independent electronic serviceshop. We at ET/D will be looking for the answers to these questions in the new year.

Merry Christmas and Happy New Year.

Sincerely,

# Get your fastening act together with Mallory-Richco.

Clamps, clips, wire sacdles, spacers, cable hangers, circuit board supports, guides and dozens of other accessories. Your Mallory distributor has them. Packaged the way you want them. See him soon. Or contact Mallory Distributor Products Company, a division of P. R. Mallory & Co. Inc., Box 1284, Indianapolis, Indiana 46206. (317) 856-3731.



MALLORY

## LETTER.

#### HELP WANTED

I'd appreciate any help you or your readers can provide in getting service info for a Sears Model 562.40291400 Color TV. It was not listed in Sam's current index, and the local Sears store could not get it for me.

Thanks. Marc W. Scharf Audio Video Service 5109 Algonquin Trail Kukomo, IN 46901

I am in need of a schematic for a MIKADO Model 1224 AM-FM-Stereo and have had no success in obtaining one. I wrote to an address in San Francisco buy my letter was returned marked "out of business."

Very truly. Frank Neal 3647 Viaorilla Lompoc, CA 93436

I have been a subscriber to your magazine for years. I need a little help now! My own AM-FM-SW radio has a broken FM-AM-MB-SW switch. I cannot get a part for it. The radio is a YORK Model-BIE-124 Can anyone help me?

Thank you. Leslie Vargas 8921 Roosevelt Blvd. Philadelphia, PA 19152

I need the address of Lavoie Laboratories that used to be in Morganville, New Jersey and also the operating and service manual on a Lavoie Oscolloscope Model LA-545 which is not exactly like a Tektronix 545.

Thanks. Rejean Mathieu 660 13th Ave. P.O. Box 1601 Sennetere, Quebec, Canada J0Y-2M0

I need a schematic for an AM/FM/8 track stereo system. I cannot get any information through the store where it was purchased. It is an Electra made by Electra Radio Corp., Model No. 8TR-400 Series A. Any help would be appreciated.

Stanley E. Johnson 4201 Winegar Rd. Bancroft, MI 48414

In your next edition of ETID magazine would you please print the following message to your readers. I need service literature and a schematic for a B&K Model 1050 video and audio generator and for a New London Instruments Co. Model 901A Transconductance Analyzer. Both need repair. Any help would be appreciated.

Ris Electronics Co. 1542 Averitt Road Greenwood, IN 46142

I have a color TV made by Division of Sparten's Industries Inc., N.Y., N.Y. 10001, distributed by KORVETT'S, Model #1869. The number of the chassis 1013AH. I have tried several ways to obtain information. Your column has been helpful before. I hope someone can put me on the track of a schematic. Fred Berberich 131 Washington Ave.

Tappan, NY 10983

#### **NEW TUNERS**

NOT universal or customized. NOT seconds, culls, dogs, or oddballs. Only \$24.95 for ANY new tuner. Over 5,000 in stock including Philco TT192.

CALL TOLL FREE 1-800-433-7124 **TEXAS TUNER SUPPLY** 4210 N.E. 28th St., Ft. Worth, TX 76117

Circle No. 125 on Reader Inquiry Card

#### Original Japanese Replacement Parts for TV, Stereo and CB

9				, , , , , , , , , , ,	
25-UP 10-24 1-9	25-UP 10-24 1-9	25-UP 10-24 1-9	25-UP 10-24 1-9	25-UP 10-24 1-9	25-UP 10-24 1-9
2SA102 29 34 39 2SA473 A5 .55 60 2SA484 185 2.05 2.35 2SA497 90 1.15 1.25 2SA599 30 .35 40 2SA562 25 30 .35 2SA634 35 .40 .45 2SA636 80 .85 90 2SA673 30 .40 .45 2SA678 40 .50 .55 2SA689 A0 .50 .55 2SA699 A0 .50 .55 2SA720 .30 .35 .40 2SA720 .30 .35 .40 2SA733 .25 .27 .30 2SA747 4.15 4.35 4.85 2SA696 .50 .50 .55 2SA696 .50 .50 .55 2SA699 A0 .50 .55 2SA699 A0 .50 .55 2SA699 A0 .50 .55 2SA699 A0 .50 .55 2SA747 .15 4.35 4.85 2SB186 .20 .27 .30 2SB174 .70 .85 .35 .40 2SB174 .70 .85 .35 .40 2SB186 .20 .27 .30 2SB1874 .70 .85 .35 .40 2SB1877 .70 .85 .55 2SC183 .70 .70 .85 .55 2SC184 .70 .70 .85 .55 2SC184 .70 .70 .85 .55 2SC1874 .70 .80 .90 2SC3877 .70 .70 .70 .75 .75 2SC1872 .70 .70 .70 .75 2SC3877 .70 .70 .70 .70 .75 2SC3877 .70 .70 .70 .75 2SC3877 .70 .70 .70 .75 2SC3877 .70 .70 .70 .70 .75 2SC3877 .70 .70 .70 .75 2SC3878 .70 .70 .70 .70 .75 2SC388 .70 .70 .70 .70 .75 2SC388 .70 .70 .70 .70 .75 2SC388 .70 .70 .70 .70 .70 .75 2SC388 .70 .70 .70 .70 .75 2SC388 .70 .70 .70 .70 .70 .70 .75 2SC388 .70 .70 .70 .70 .70 .70 .70 .70 .70 .70	2SC460	2SC1114  3.40  3.60  3.80  2SC1116A  3.20  3.48  3.80  2SC1116A  3.20  3.48  3.80  2SC11124  80  3.85  95  2SC11127  80  3.85  95  2SC1162  70  75  85  2SC1162  70  75  85  2SC1162  70  1.50  3.85  2SC11728  3.10  3.50  3.85  2SC11728  3.10  3.50  3.85  2SC11728  3.10  3.50  3.85  2SC1177  10 90  12.40  13.80  2SC1266  50  60  70  2SC1226  50  60  70  2SC1239  2.10  2.65  2.85  2SC1306  1.25  1.65  1.85  2SC1306  1.25  1.65  1.85  2SC1308  30  .40  .45  2SC1384  30  .40  .45  2SC1384  30  .40  .45  2SC1384  30  .40  .45  2SC1384  30  .40  .45  2SC1424  2.75  2.85  2.85  2SC1426  2.75  2.85  2.85  2SC1426  2.55  2.85  2SC1426  3.00  .55  5.85  2SC1678  2.50  3.5  3.5  2SC1678  3.50  3.5  3.50  2SC1727  3.50  3.5  3.50  2SC1727  3.50  3.5  3.50  3.5  3.50	2SC2072 3.55 3.75 3.95 2SC2076 4.8 6.0 6.65 2SC2076 1.8 1.0 1.15 2SC2092 1.75 1.95 2.20 2SC2098 1.75 1.95 2.20 2SC2098 1.75 1.95 2.20 2SC2098 1.75 1.95 2.20 2SC2098 1.75 1.75 1.95 2SD180 1.55 1.75 1.95 2SD180 1.55 1.75 1.95 2SD180 1.55 1.76 1.95 2SD180 1.55 1.76 1.95 2SD180 1.55 1.76 1.95 2SD180 1.55 1.76 1.95 2SD181 2.95 3.20 3.45 2SD218 2.95 3.20 3.45 2SD2218 2.95 3.20 3.40 2SD2218 2.95 3.20 3.40 2SD2218 3.00 .55 3.40 2SD2218 3.00 .65 7.75 2SD226 5.00 7.0 8.0 2SD325 5.00 .65 7.75 2SD326 7.0 8.0 9.90 2SD325 5.00 .65 7.5 2SD326 5.00 7.0 8.0 2SD325 7.0 8.0 9.90 2SD325 8.0 9.5 9.5 9.5 9.5 9.5 9.5 9.5 9.5 9.5 9.5	AN2477 2.40 2.60 2.90 AN273 4.20 4.60 4.50 AN373 4.20 4.20 4.20 AN373 4.20 4.20 AN373 4.20 4.20 AN373 4.20 AN37	TA7089P 1.95 2.15 2.45 TA7092 1.40 4.90 5.40 TA7120P 1.45 1.65 1.85 TA7139P 1.55 1.75 1.95 TA7139P 1.50 1.75 1.95 TA7120P 1.85 2.15 2.46 TA7204P 1.85 2.16 2.85 TA7204P 1.95 2.16 2.46 TA7205P 1.96 2.10 2.85 TA7204P 1.95 2.10 2.46 TA7205P 1.96 0.00 6.20 TA7309P 1.95 2.10 1.0 1.55 TA7310P 1.95 2.60 6.00 6.20 TA7309P 4.40 4.0 4.80 TA730P 4.00 6.00 6.20 TA7509P 4.00 4.00 5.60 TC5081P 2.90 3.10 3.30 TC5082P 2.90 3.10 3.30 TC5082P 2.90 3.10 3.30 TC5082P 2.90 3.10 3.30 UHIC001 4.90 5.10 5.60 UHIC002 4.90 5.10 5.60 UHIC003 4.90 5.10 5.60 UHIC004 4.90 5.10 5.60 UHIC006 4.90 5.10 5.60 UHIC007 4.90 5.10 5.60 UHIC008 4.90 5.10 5.60 UHIC007 4.90 5.10 5.60 UHIC007 4.90 5.10 5.60 UHIC008 4.90 5.10 5.60 UHIC007 4.90 5.10 5.60 UHIC008 4.90 5.1

PRICES MAY CHANGE WITHOUT NOTICE **COD ORDERS WELCOMED** 

Minimum order \$10.00 - N.J. Residents add 5% Sales Tax. We pay postage for prepaid orders of \$50.00 or more, Under \$50.00, add \$1.00, Canada \$1.50, Quantity Discount Prices - Ask for our complete price list Manufacturer inquiries welcome - All parts guaranteed.

TOLL FREE TELEPHONE

Nationwide 800/631-1250

Local 201/748-5089

HOURS: Mon. - Fri. 8 to 5:30 Sat. 8 to 1



IMMEDIATE DELIVERY WITHIN 48 HOURS ON ALL TRANSISTORS IN STOCK

> NEW-TONE ELECTRONICS INTERNATIONAL P. O. Box 1738, Bloomfield, N. J. 07003 New Jersey Phone: 201/748-6171

## NEWSLINE

SEARS SLAPPED WITH TV DUMPING FINES. Sears, Roebuck & Company has been fined \$5.5 million by the U.S. Treasury Department for allegedly selling imported Japanese-made TVs in this country for less than they sold for in Japan. Sears, however, is paying the fines under protest and will seek recovery. The levy is part of a \$43 million total assessed against a number of U.S. and Japanese companies for alleged dumping activities between 1971 and 1973. The case is the outgrowth of Zenith Radio Corporation protests against unfair market practices.

"HIS MASTER'S VOICE." The world's most famous 94-year-old dog-Nipper-is back. The focal point of a new RCA \$8-million marketing program, Nipper will again be used in conjunction with RCA advertising programs for its consumer electronics, service company, commercial communications, solid state, and distributor products divisions. The famous fox terrier was originally painted in 1890 listening to a gramophone by British artist Francis Barraud.

REVISED NESDA CONVENTION DATES. Revised dates for the 1979 convention of the National Electronics Service Dealers Association (NESDA) convention have been announced by President Bob Villont. According to Villont, industry conflicts necessitated a change for the convention in Tucson, Az. to August 13-19. Originally the meeting had been scheduled for August 20-26. The headquarters hotel for the event will be Tucson's Mariott Hotel.

ISCET BACK WITH NESDA. In another statement, NESDA Executive Vice President Charles Porter revealed that "effective immediately" the operational headquarters for the International Society of Certified Electronic Technicians (ISCET) is once again back in NESDA headquarters in Indianapolis. ISCET affairs had been directed from Ames, Ia., since August of last year after moving out of the NESDA headquarters. "The move is in accord with the expressions of concern we have received from the majority of the members of both organizations," Porter said.

CONSUMER ELECTRONICS IMPORTS UP. The Electronic Industries Association reports increases in United States imports for most categories of consumer electronics products during the third quarter of 1978. Here's a brief rundown: Color TV, up 14.2% to 787,187; Mono TV, up 28.4% to 1,727,245; phonos and phono combinations up 12.6% to 1.2-million; record players up 34.4% to 2.8-million; audio tape/player combos up 27.2% to 3.9-million; and Video tapes up 153.6% to 137,295 units. The EIA also states that the total exports of television, radios and tape equipment increased during the third quarter but activity was low. For instance color television exports in the third quarter were only 118,365.


COLOR TV HITS QUARTER, NINE MONTH HIGHS. Imports pushed total new set supply to a record high for any quarter, according to Television Digest. The share produced by domestic factories increased, aided substantially by Japanese owned plants, while the U.S. factory share of b & w fell to 5.6%, down from 12.5% a year earlier, TV Digest said.

## SERVICE SEMINAR

#### ADMIRAL


#### Chassis TL6-No sound.

Could be wrong value of R205 (should be 82k ohm) which could take out Q201, cause R207 to change value (should be 6.8k ohms) and possibly damage IC201.



#### Chassis M55-IC600.


When replacing IC600 (56A55-1) horizontal processor/vertical countdown chip, be sure the keyway is facing the *rear* of the chassis. Reversal of this chip can cause a second failure. Prior to turning power on, check Q800 (horizontal driver). If Q800 is shorted, it could be the cause of IC600 failing.



#### **GENERAL ELECTRIC**

Chassis 19QB—Drive lines in raster—then horizontal output transistor shorts.


Replacement does not correct—shorts again. Check C234:0047mfd 1200v probably open—replace.



#### ZENITH

### Module 9-121-01C—Heat sinks require proper positioning for continued reliability.

Whenever you service or replace a 9-121-01B, C, D video output module, be sure that the heat sinks of the 3 output transistors are positioned away from the thick film device and peaking coils as shown in the illustration below. If the heat sinks come in close proximity with the peaking coils, an arcover may occur which could cause failure of driver transistor Q1207 (121-1019). Therefore, always check and reposition if necessary, (1) the thick film device which should be perpendicular to the printed circuit panel, (2) the transistor heat sinks which should be midway between the thick film and peaking coils.



#### Neck-mounted video output modules.

Whenever replacing the CRT for whatever reason on any chassis utilizing the neck-mounted 9-121-01 or 9-155 series video output module, always first make an ohmmeter check of the video driver transistor (121-1019). (Refer to the previous illustration.) If the collector to emitter is shorted or has very low resistance, replace it or the entire module first, before proceeding with the CRT replacement. **ETID** 



## ALL THE MOST WANTED FEATURES AT A MOST WANTED PRICE...

BIG ½" HIGH LCD DISPLAY
USE INDOORS OR OUT
200 HOUR 9V BATTERY LIFE
AUTO ZERO, POLARITY,
OVERBANGE INDICATION




Removable cover stores test lead set furnished as part of the unit.



Available accessories include AC acapter, paddec viny carrying case.



X10 DCV probe adapter available for protecting input up to 10KV.



**\$74.95** 

100 mV DC F.S. SENSITIVITY
19 RANGES AND FUNCTIONS

Here is the handfull of accuracy you've been waiting for. Handsomely encased. Compact. Efficient. Only 8 ounces. Hickok's exciting, new LX 303, 31/2 digit Mini-Multimeter with high quality components, one year guarantee and rugged Cycolac® case offers features previously found only in expensive units. . .at a price under \$75.00! So why wait any longer? The amazing LX 303 is here. NOW! Another American made test equipment breakthrough from Hickok, The Value Innovator, Order today!

#### SPECIFICATIONS:

DC VOLTS (5 RANGES):  $\tilde{c}$ .1mV to 1000V; Accuracy  $\pm 0.5\%$  rdg  $\pm 0.5\%$  f.s.; Input imped: 10M  $\Omega$ ; Max. input 1kV except 500V or 200mV range. AC VOLTS (40Hz to 5kHz): 0.1V to 600V; Accuracy:  $\pm 1.0\%$  rdg  $\pm 0.5\%$  f.s. (-2cB max. at 5kHz); Max. input: 600V.

RESISTANCE (6 LOW POWER RANGES): 0.10 to 20MΩ; Accuracy:  $\pm 0.5\%$  dg  $\pm 0.5\%$  s, ( $\pm 1.5\%$  dg on 20MΩ range); input protected to 20MAC all ranges.

DC CURRENT (6 RANGES): 01nA to 100mA; Accuracy: ±1.0% rdg ±0.3% f.s. DIMENSIONS AND WEIG +3: 5-7/8" x 3-3/6" x 1-3/4", 8 oz.; POWER: 9V sattery (nct included) or Hickok AC adapter; READ RATE: 3/sec. Circle No. 114 on Reader Inquiry Card

See your nearby Hickok distributor. Call toll free 800-321-4664 (outside of Ohio) for your local distributor's name.

## HICKOK

#### the value innovator

INSTRUMENTATION & CONTROLS DIVISION THE HEXOF ELECTRICAL INSTRUMENT CO. 10514 Oupont Avenue • Cieveland, Ohio 44108 (216) 541-8060 • WX: 810-421-8286

# Phase locked loops revisited

Where frequencies abound

Working around in these circuits can be a joy or a nightmare, depending on your own level of understanding.

#### By Bernard B. Daien

The phrase "phase locked loop" has been popping up in recent electronic literature. These articles convey the impression that phase locked loops are something new, different, and require new methods of troubleshooting.

Nothing could be further from the truth, since phase locked loops were used prior to World War II, later in the horizontal AFC of black and white TVs, and more recently in the color AFPC circuitry which synchronizes the color oscillator to the color burst signal in color TV sets. They have been in constant use for forty years!

The phase locked loop consists of three circuits: A phase detector, low pass filter, and voltage (or current) controlled oscillator. The phase detector compares the frequency and phase of the incoming signal to that of the controlled oscillator. If the two frequencies, or phases, differ, the phase detector generates an output signal which is applied to the controlled oscillator, correcting its frequency so that lock-in occurs. The low pass filter is used to clean out the unwanted frequencies which appear in the output of the phase detector. That's it. From this starting point we can make the phase locked loop "stand up and do tricks" ... if you want to know just how we use the phase locked loop in more sophisticated ways, read on.

#### The buzz words

Let's start by defining the words used to describe phase locked loops, and the




Fig 1-Basic Phase Locked Loop Block Diagram




Fig 2-PLL used as FM/PM Detector

abbreviations for those words. Phase Detector, (PD). This compares the two signals and produces an error voltage which is dependent upon their relative frequencies and phase differences (providing there is sufficient signal input amplitude so that output is not dependent upon input level). This is sometimes called a "Phase Comparator." There are many different circuits which can perform this function.

Voltage Controlled Oscillator, (VCO). This is an oscillator the frequency of which is determined by the applied control voltage. Most of these oscillators are variations of the astable (free running) multivibrator, and their output is not sinusoidal. (NOTE: although the term "voltage controlled" is generally employed, the fact is that many

integrated circuit VCOs are actually Current Controlled Oscillators (CCO). Since Integrated circuits are frequently solid state devices using bipolar transistors, a current is used to control circuit characteristics since bipolar transistors are current operated devices.)

Low Pass Filter, (LPF). This filter removes any of the two input frequencies that appear in the output of the phase detector, along with much of the noise, and the intermodulation and harmonic distortion products generated in the phase detector. The object is to permit only the DC and low frequency components to pass on to the phase locked loop circuitry.

Free Running Frequency, (f<sub>o</sub>). This is the frequency at which the VCO runs when not locked ... sometimes called the "Center Frequency."

Capture Range. This is the range of frequencies over which the phase locked loop can "pull in" and lock onto a signal. This refers to both plus and minus frequencies, as in bandwidth of a circuit. The term "Lock-In Range" is sometimes used, but it is different because it refers to the frequency plus or minus, and thus is one half of the




Fig 3A-Phase locked loop running at lower frequency than input or output frequencies.




Fig 3B-Phase Locked Loop with output frequency higher than input frequency.




Fig 4-Use of PLL with programmable divider (counter), and prescaler, to generate several frequencies from one crystal oscillator.

Capture Range. It's like double side-band versus single side-band. One is one half of the bandwidth of the other.

Lock Range. (NOTE "Lock-In" Range, Above). This is the range of frequencies over which the loop will remain locked once lock-in has been achieved. It is also called the "Hold-In Range" and "Tracking Range."

... and last, but not least, Phase Locked Loop, hereafter referred to as PLL ... and by now you have a good idea of what it is, but not all the nice little tricks it can do.

#### The basic PLL

Refer to Figure 1. The input signal is called the "reference signal," because it really is. Think about the color burst in a color TV, which is the reference onto which we lock the color oscillator, in exact phase, in the color AFPC.

The output of the VCO is also fed into the phase detector. Whether the signals are out-of-phase ... or in-phase, determines the polarity of the error output signal from the phase detector, exactly the same as in the phase detector of a horizontal AFC phase detector in a TV set. Since the two frequencies may be different to start

with, there will be several frequencies in the output of the phase detector ... the two input frequencies, and the various sum and difference frequencies.

#### **Active filters**

We solve this problem just the way we do in the output of any "detector" ... with a low pass filter. Ideally this filter would remove all the spurious (unwanted) frequencies in the output, but leave the desired error output signal, which is a slowly varying DC voltage. Unfortunately this filter has several side effects in the system which must be considered. For one, if the filter has too long a time constant, the PLL will not be able to respond quickly enough to enable lock-in over a wide range of frequencies. If the time constant is too short, unwanted frequencies will upset the system. One method is to use two RC filters, with different time constants, just as in the horizontal AFC in TV, where the time constant must be right in

order to prevent the classic "pie crust"

sections we get into rapidly increasing

phase shift, which is undesirable. Today

we have active filters available to us

effect shown in TV service texts.

Unfortunately, as we add RC filter

(refer to any good Operational Amplifier Handbook for reference), and active filters are able to give us the desired frequency bandpass characteristic with acceptable phase shift. Thus the low pass filter may be on the printed circuit board in the form of an integrated circuit operational amplifier, or even be part of one of the PLL ICs internally, and thus not be readily apparent, but it is there, it is essential, and it is critical!

#### Some applications

So far we haven't discussed anything you really didn't know already, except the buzz words are different. As we proceed you will note that the entire PPL follows this same pattern. Let's get along then. Figure 1 shows the output of the low pass filter directly feeding the VCO, but of course you realize that it may be desirable in some cases to put a DC amplifier between the phase detector and VCO in order to boost the voltage level. Again, an active filter is preferred because it can give us the desired bandpass, with gain, while a passive filter always has a loss. The varying DC error signal from the low pass filter causes the oscillator frequency to vary, exactly the same way as the output of the color phase detector causes the reactance tube to vary the frequency of the color oscillator in a color TV. When the reference frequency is higher than the oscillator frequency, we get one polarity or error signal output from the phase detector, when the reference frequency is lower than the oscillator's we get the opposite polarity of error signal. Thus the output of the phase detector can be used as an FM detector, or a PM detector! Refer to Figure 2 now ... the only difference is in where we take off the output, and what we use it for. Figure 2 is a basic FM/PM detector.

I can just hear you saying, "So what? We have plenty of FM detectors now ... Foster Seeley, Ratio, Quadrature, etc. Why more?" All of the above use tuned circuits, which employ coils, which often need shielding ... to prevent stray coupling. Coils cost money, shielding costs money, and both take up room. The PLL is small, cheap, light, and needs no shielding. And the trend today is toward more ICs and fewer discreet components. Enough said!

#### **Derived frequencies**

Which brings us to the last of the three blocks in Figure 1 ... the VCO. Since the VCO is really a specialized multivibrator, it has some limitations. For example, it does not run at very high frequencies. Therefore, we need to devise ways to

obtain the desired frequencies. Several alternate solutions are available, each with certain advantages and disadvantages. Figure 3A shows a PLL configuration which can handle a reference frequency four times higher than either the VCO or the Phase Detector.

All we did was divide the input frequency by four, the PLL then easily handled the lower frequency, and the output is multiplied back to the desired frequency with a multiply-by-four circuit. The frequency dividers and multipliers are standard digital ICs. Remember, the PLL is a non-sinusoidal circuit, so digital IC output waveforms are perfectly acceptable. Any cleanup of the waveform can be accomplished with very simple filtering at the output of the PLL. (Harmonic distortion only requires that a filter be capable of eliminating the second, and higher harmonics, thus the filter need not be particularly selective. with the nearest undesired frequency being twice the desired frequency.)

All we did in Figure 3A was introduce frequency dividers, and multipliers, which are nothing new to you. But we also made the point that by using frequency dividers and multipliers we are able to extend the useful range of frequencies of the PLL so that we can use the PLL for almost any frequency from ultra low frequencies in instrumentation, to audio in electronic musical instruments, right on up to UHF. Of course, we do not need to multiply and divide in the same ratio, we can use any multiplier on the input or output, or any divider, or even use multipliers and dividers inside the PLL's "closed loop," as we will now demonstrate with the aid of Figure 3B.


#### Frequency synthesis

We have added a frequency divider in the feedback loop between the output of the VCO and the phase detector. As a result, the VCO can run, for example, at 400 kHz. The 400 kHz, divided by 4, is presented to the phase detector as 100 kHz, and compared to the 100 kHz reference frequency. If the reference frequency is stable, (a crystal oscillator). the output will have the stability of the stable reference input, since it is phased locked to it. By now you are seeing the basis of a frequency synthesizer, which enables us to generate many frequencies from just one stable crystal. In order to change the output frequency, while preserving the stability of the reference, all we need do is change the dividers (or multipliers) in the loop, or ahead of the loop, or following the loop.

There are available ICs which incorporate four flip-flops, each flip-flop dividing by two ... (thus the IC is capable of dividing by 15) ... and such ICs are also "programmable" ... which means that we can choose what number they will divide by, up to a maximum of 15. The reason the count is limited to 15 is that we actually use sixteen different states, starting with "zero" as the first

it, it's a little hard to achieve "odd" multiplications and divisions using the frequency doublers and triplers that are used in transmitters, for example.

Specifically, how would you go about generating a 1.4 mHz signal from a 100 kHz frequency standard type crystal, without the convenience of the phase locked loop? Notice that the fixed divider is labled "Prescaler" ... another buzz



state ... thus 0 through 15 equals 16 different output states. Some of these ICs have a built-in limit of ten counts ... 0 through 9.

The IC programmable counters that go up to 9 are called "Programmable Decade Counters." The ones that go up through 15 are "Programmable Hexadecimal Counters." In either case we can select any count (division) up to the maximum of the IC. Now we need to add a few more buzz words: N. This is the number we divide by. Thus to say "divide by 5," we write "N=5," (when talking about dividers). Modulus. The same as N. If we divide by 5, then N=5, and the modulus is 5.

#### **Inserting prescalers**

Sometimes we also use a fixed divider, or multiplier ahead of a programmable divider, as, for example, in Figure 4. Notice that the programmable divider has a modulus of 7, and the fixed divider a modulus of 2, for a total division of 14, which provides an output frequency of 1.4 mHz, with the same accuracy as that of the reference. Now if you think about

word, for a fixed modulus circuit that "precedes" a programmable (variable) divider. Generally we can tell if the circuit is a "Prescaler" because the modulus of a prescaler is often shown as "P=2" instead of "N=2." Some prescalers give you a choice of prescaling modulus, such as P=2 or P=6 ... sort of semi-programmable, like the difference between a variable resistor, and an adjustable resistor. The programmable divider can be set for any value of N between, say 1 and 9, for a decade counter, while a two modulus prescaler would permit the choice of only two divider ratios. The programming is accomplished with electrical signals, not by mechanical switching, although electromechanical switches can be used to provide the electrical signals if desired (toggle switches, relays, push buttons, etc.)

Prescalers are used for a variety of reasons ... they do not have to be programmable, hence can trade off that feature for speed, permitting very high frequency inputs and, since the output is a much lower frequency, the rest of the

## The last time you saw a really new bench/portable DMM was 1972.

That's the year our 8000A was introduced. Its custom LSI and solid owner benefits quickly established it as the world's leading DMM.

Now, look at the new 8010A and 8012A: single-chip CMOS designs for problem-solving in the eighties!

RAZOR-SHARP LCD for large, no-strain answers at first glance in any light.

TOUCH AND HOLD probe option, so you can thread your way through a component jungle and capture the reading you need.

FUNCTION POWER: 22 ranges of AC and DC volts and current, six ranges of resistance, and three ranges of conductance — the missing function on other bench multi-

CONDUCTANCE RANGES for noise-free leakage measurements to 10,000 M $\Omega$ . A valuable function for bench-testing boards and components, conductance also measures transistor beta (using a bias resistor) and light intensity (by using a photocell).

OVERLOAD-PROTECTED like no other DMM, including rejection of 6000V transients and up to 600V applied to the current ter-

HONEST AC ANSWERS derived from a Fluke hybrid true rms converter. You'll even see the difference on your AC line between the correct value and what your average-responding meter reads. And 50 kHz bandwidth won't let any significant distortion products go unmeasured. Plus, 10 times the basic response you may be limited to now!

SPECS YOU EXPECT from Fluke - like ±0.1% on DC for one year. Both models available with rechargeable batteries, and backed by the same solid warranty and worldwide service that helped make the 8000A the industry standard.

LEADERSHIP HAS TO BE EARNED. And we're committed to keeping the price of your confidence as realistic as possible. Like \$239 for the 8010A with a 10A current range, and \$299 for the 8012A with two extra-low ohms ranges that allow measurements from  $0.001\Omega$  to  $10.000 \text{ M}\Omega$  — making it the widest range ohmmeter available!

Contact one of the more than 100 Fluke offices and representatives, worldwide, or CALL (800) 426-0361 TOLL FREE. In the U.S., and all countries outside Europe, write: John Fluke Mfg. Co., Inc., P.O. Box 43210, Mountlake Terrace, WA 98043, U.S.A.

In Europe, contact Fluke (Nederland) B.V., P.O. Box 5053, Tilburg, The Netherlands. Telephone: (013) 673973. Telex: 52237.

Prices U.S. only.

· Alaska, Hawaii, Washington residents — please call (206)




TUNER SERVICE



CORPORATION

## SAME DAY SERVICE



## ONE YEAR GUARANTEE

The Company of Independent Professionals

## Better Quality — Personal Attention — Faster Service



TSC PROVIDES YOU WITH A COMPLETE SERVICE FOR ALL YOUR TELEVISION TUNER REQUIREMENTS

TUNER REPAIRS

EXACT REPLACEMENT

UNIVERSAL REPLACEMENT



## **MODULES**

## **SUBSTITUNER**

000011
HEADQUARTERSALABAMAARKANSASCALIFORNIA
FLORIDA
GEORGIAILLINOIS
INDIANA
KENTUCKY. LOUISIANA MASSACHUSETTS MISSOURI. NEVADA NEW JERSEY
NEW YORK

NORTH CAROLINA.....

TENNESSEE.....

CANADA.....

OREGON....PENNSYLVANIA..

TEXAS.

	BLOOMINGTON, INDIANA 47401
	BIRMINGHAM, ALABAMA 35212
	LITTLE ROCK, ARKANSAS 72204
	MODESTO, CALIF. 95351
	NATIONAL CITY, CALIF. 92050
	NORTH HOLLYWOOD, CALIF. 91601.
	SAN MATEO, CALIF. 94402
	TAMPA, FLORIDA 33606
	FT. LAUDERDALE, FLORIDA 33309
	ATLANTA, GEORGIA 30310
	URBANA, ILLINOIS 61801
	SKOKIE, ILLINOIS 60076
	INDIANAPOLIS, INDIANA 46204
	SOUTH BEND, INDIANA 46619
٠	LOUISVILLE, KENTUCKY 40217
	SHREVEPORT, LOUISIANA 71104
	SPRINGFIELD, MASS. 01109
٠	ST. LOUIS. MISSOURI 63132
	LAS VEGAS, NEVADA 89102
	JERSEY CITY, NEW JERSEY 07307.
	ROCHESTER, NEW YORK 14606
	GREENSBORO, N. CAROLINA 27405.
	CLEVELAND, OHIO 44109
	PORTLAND, OREGON 97210
6	
	MEMPHIS, TENNESSEE 38111
	DALLAS, TEXAS 75218ST. LAURENT, QUEBEC H4N-2L7
	CALGARY, ALBERTA T2H-1Y3
	CALGANT, ALDENIA 120-113

537 South Walnut Street	Tel.	812 / 334-0411
5623 1st Avenue N	Tel.	205 / 592-9150
4200-C Asher Avenue	Tel.	501 / 661-0393
123 Phoenix Avenue	Tel.	209 / 521-8051
117 East 8th Street	Tel.	714 / 477-8746
. 10654 Magnolia Boulevard	Tel.	213 / 769-2720
600 South Amphiett Boulevard		
1505 Cypress Street	Tel.	813 / 253-0324
3516 N.W. 10th Avenue	Tel.	305 / 566-4882
646 Evans Street S.W	Tel.	404 / 758-2232
908 East Main Street	Tel.	217 / 384-2052
5110 West Brown Street	Tel.	312 / 675-0230
112 West St. Clair Street	Tel.	317 / 632-3493
2010 Western Avenue	· · · Tel.	219 / 288-8918
#7 Dahlem Center, 826 Eastern Parkway	Tel.	502 / 634-0498
2423 Southern Avenue	Tel.	318 / 221-3027
144 Boston Road	Tel.	413 / 788-8206
9577 Page Avenue		
1114 South Casino Center Blvd	Tel.	702 / 384-4235
1139 Pennsylvania Avenue	Tel.	509 / 393-0999
454 Central Avenue	Tel. :	201 / 792-3730
25 Howard Road		
2914 East Market Street	Tel. 9	919 / 273-6276
4525 Pearl Road		
1732 N.W. 25th Ave., P.O. Box 10141		
.515 Grant Avenue		
3158 Barron Avenue		
11540 Garland Road		
305 Decarie Boulevard		
P.O. Box 5823, Station "A"	· · · Tel.	103 / 243-0971

If you want to branch out into the TV Tuner Repair Business write to the Bloomington Headquarters about a franchise.

Circle No. 128 on Reader Inquiry Card

circuitry does not need to run at the higher speed. The combination of prescalers and programmable dividers gives us great flexibility in generating many frequencies from one crystal.

#### **Practical applications**

We are now going to examine the frequency synthesizer used in a 40 channel Citizens Band transceiver, but first, to better understand the system, let's look at Figure 3B again. What would happen if we changed the ratio, N=4, in the divider? Let's make a chart:

N=1, output frequency = 100 kHz. N=2, output frequency = 200 kHz. N=3, output frequency = 300 kHz.

As you can see, the output changes in 100 KHz jumps, as the divider ratio is changed. Notice that the reference frequency is also 100 KHz. Is it coincidence? To check, we'll now look at what would happen if we substitute a reference frequency of 10 KHz. The output becomes a 40 KHz for N=4. Again we'll make a chart for various values of N:

N=1, output frequency = 10 kHz. N=2, output frequency = 20 kHz.

N=3, output frequency = 30 kHz... as you can see, the divider ratio, N causes the output to be multiples of the reference frequency. (There are some circuits that use special prescalers to enable changing the output in steps less than the reference frequency, and these can be spotted by the fact that the prescaler has two ratios, called a "Two Modulus Prescaler," one modulus being P, and the other P + 1, (one more than P). We will confine ourselves to the more common circuitry which does not use the Two Modulus Prescaler.)

#### A basic synthesizer

In the light of the above, we will proceed to the frequency synthesizer, not only for conceptual purposes ... but also with the aim of doing some analysis ... (see, you're not only using the buzz words, you're even going to do some sharp circuit analyzing). On to Figure 5, the basic synthesizer circuit right out of a commercial CB transceiver.

We can pick up the reference signal at the input to the phase detector, and notice that it's 10 kHz, which probably indicates that our output is going to change in 10 KHz steps ... and we're right, since CB channels are in multiples of 10 kHz. So far, so good. The reference frequency is derived from a 5.120 MHz crystal, divided by N=512, which gives us 10 KHz. (Ten KHz would be a very low frequency for a low temperature coefficient crystal, and it

would be a very thick, heavy, expensive crystal, so 5 MHz is a good choice for a crystal with reference to stability and cost.)

The phase detector error signal passes through a low pass filter, and on to a 31.740 MHz VCO. The output of the VCO goes to a mixer, along with the 5.120 MHz from the crystal, yielding a difference frequency of 26.620 MHz, just the right frequency for the *receiver* tuner mixer oscillator frequency for CB channel 10. Since CH 10 has a transmitter frequency of 27.075 mHz, and our receiver has an IF frequency of 455 KHz, then 26.620 + .455 = 27.075. Knowing this we are in a good position to start trouble shooting our PLL frequency synthesizer!

#### **Checking frequencies**

Let's see, we know the crystal oscillator should be 5.120 ... and we will need a frequency counter to check it. Assuming you are able to get hold of one (and you'll need it to service PLLs which are nothing but a bunch of frequencies), it's a snap. Of course you should check to see if the output of the "divide by 512" is really 10 kHz. Then set the switch to "Receive" and the Channel Selector to Channel 10, and look for 31.740 input into the "Offset Mixer" and 26.620 out of the Offset Mixer. If you lose the signal, or get an incorrect frequency, you have a well localized fault. By now you have the idea, and it's no more difficult than signal tracing through all the conversions in a color TV set, what with the video IF, sound IF, local oscillator, and color oscillator, etc.

Back to the synthesizer. The VCO output also goes to the "Synthesizer Mixer" where it is mixed with the "High Frequency Oscillator." This oscillator has two crystals, and depending upon which one is used, the output is either 30.820, or 31.275 MHz. Since the crystals are marked "Receive" and "Transmit" and are 455 KHz apart, we can assume that this oscillator is used to shift the frequency of the receiver mixer oscillator 455 KHz away from the transmitter frequency, thus generating the 455 KHz receiver IF frequency. The Synthesizer Mixer output is the difference between the 30.820 and 31.740 inputs, or 920 KHz.

This 920 KHz is the input to a programmable divider, with N=92 for CB channel 10, thus the onput of the divider is ... you guess it ... 10 KHz. The 10 KHz so derived is fed into the phase detector, which compares it to the 10 kHz from the "divide by 512" circuitry. The PLL adjusts the VCO frequency

until the two are locked in phase, which means the VCO output has to be 31.740 kHz

#### **Transmit mode**

If we throw the switch to "Transmit," the 31.275 crystal is switched into the circuit and feeds the Synthesizer Mixer. Since we still have the Channel Selector set for Channel 10, the programmable divider is still at N = 92 ... therefore if the input to the phase detector is to remain at 10 kHz (as it must to be phase locked), the input to the programmable divider must remain at 920 KHz. The only way this can happen is if the VCO output shifts from 31.740 to 32.195. Let's check that out. If the VCO shifts to 32.195, it will mix with the 31.275 in the Synthesizer mixer, and the difference will be 920 KHz ... correct! But there is another requirement ... the output of the Offset Mixer must now be a 27.075, the transmit frequency for channel 10. Let's see if it is. The inputs to the Offset Mixer are now 32.195 and 5.120. The difference frequency is 27.075 ... again, correct!

Of course, by now, you know that if we change channels by changing the programmable divider to N=91, instead of N=92, the output will change exactly 10 KHz, because that's our reference frequency. It was obviously chosen because the CB channels are spaced multiples of 10 kHz ... but for purposes of exercise, the table below lists some of the channels, their transmit frequencies, the required modulus (N) in the programmable divider, and the feedback frequency into the programmable divider. You should try checking them ... grab a pencil and a piece of paper and prove to yourself that you now understand how a PLL frequency synthesizer works! You do!

Channel	Transmit	N =	Feedback
	Frequency		Frequency
1	26.965	81	810 kHz
10	27.075	92	920
20	27.205	105	1050
30	27.305	115	1150
40	27.405	125	1250

Note: If the above do not seem in uniform order, it is because not all adjacent channel assignments are separated by 10 kHz. Some are spaced 20 kHz, some 30 kHz, and in the case of Channel 23, is actually higher in frequency than channels 24 and 25 (put in reverse order!).

#### Troubleshooting hints

To check the VCO, use a substitute bias box for the phase detector error output signal. Varying the bias should vary the VCO's frequency if it is operating properly. A quick check of the presence or absence of signals is in order early in the troubleshooting process. And, of course, so is a check for the proper supply voltages.

Oscillation, due to defective grounds or bypass capacitors will really throw you ... so be sure to check for spurious oscillations with a scope.

To check the phase detector, vary the VCO frequency with a subsitute bias source. The error voltage out of the phase detector should vary as the VCO frequency varies.

A defective capacitor or resistor can

cause the VCO center frequency to shift, (remember the VCO is a multivibrator, and the center frequency is determined by rc time constants).

A signal that is too weak can cause the PLL to lose lock, or fail to track. Usually a defective IC, or transistor is at fault. Be especially wary of replacement parts. For example, a crystal oscillator may run out of frequency limits if the oscillator transistor is changed, even using a replacement with the same "2Nxxx" number. The reason is that there is a 3 to 1 spread on beta (current gain) specifications. Changing the gain causes a shift in the transistor's effective

capacitances, which causes the circuit to run out of frequency specs. The remedy is to get a replacement part from the distributor, or else to vary the bias on the transistor until the frequency is within limits. Of course if the transistor itself has the wrong junction capacitances to begin with, no amount of fiddling will fix it. Many manufacturers use specially selected parts in critical circuits, and in such cases the transistor substitution books are worse than useless!

Finally, with the cost of frequency counters down to the level of other service instruments, get one before you try to guess at the frequency. You just can't do it! Reminds me of the fellow who says he doesn't need a color bar generator to converge sets. He does OK if you don't mind color fringes on peoples' teeth. £770



Circle No. 121 on Reader Inquiry Card

#### TUNER SERVICE

All overhauls guaranteed two full years.
Give us a try · you'll like the
way we do business.
Call TOLL FREE 800-433-7124
In Texas call 817-834-8201
TEXAS TUNER SERVICE
4210 N.E. 28th St., Ft. Worth, TX 76117

Circle No. 126 on Reader Inquiry Card

## Everything you've dreamed of in a scope...including a sensible price.



See them at your VIZ distributor.

Whether it be for servicing or scientific research, the new WO-527A 15MHz 5" triggered-sweep oscilloscope is designed for a wide range of applications. With its host of useful functions and its advanced solid-state integrated circuits, it's hard to believe it's so reasonably priced.

- Easy-to-use pushbutton controls
- Triggered or automatic sweep; ac or dc triggered
- Unique trigger level control with LED polarity indicators
- 10mV to 20V/cm in 11 ranges
- · 19 calibrated sweep ranges
- · Preset, automatic TV sync separation circuits
- · Built-in calibrated time-base
- Special line selector for TV line-by-line display
- 10 times sweep magnifier

VIZ Test Instruments Group of VIZ Mfg. Co.

335 E. Price St., Philadelphia, PA 19144

Formerly

© VIZ 6883A

# Only eight TV tubes can make a warehouse out of your backroom.



Limited warranty. Labor not included.

To offer fast replacement for 385 different TV tubes, you'd have to open a warehouse. Or, you could open eight Sylvania picture tube cartons.

Our eight Universal Color Bright tubes are designed as direct replacements for 385 bonded safety plate picture tubes. And they're designed so well that they're offered with a five-year limited warranty.\*

Call your Sylvania distributor to stock up on Color Bright tubes. Then, you won't have to wait days for your customer's new tube to be delivered.

You can order a Color Bright for immediate delivery right from your own backroom.

SYLVANIA
Circle No. 112 on Reader Inquiry Card

Electronic Components

GIB

## Microprocessor technology

What goes on inside

Come with us as we take you on a journey through the maze of pathways and channels to be found inside of those—up to now—mysterious 40-pin chips.

#### By Steven K. Roberts

That conventional-looking blender brought into your shop yesterday for repair (ah, gravy money, this!) rests on the bench with its innards exposed. Hello? What is this PC board with two 40-pin Large Scale Integrated Circuits?

Good morning. You have just come face-to-face with third-generation microcomputer technology. Last night, while you were probably sleeping peacefully, it popped into your business environment. You are reading the continuation of ET/D's ongoing attempt to give it a proper introduction.

In the first article of our series on microprocessors ("Micros on Your Bench?" August, 1978, p. 26), we discussed some of the rationale behind the use of "intelligent hardware" in consumer electronics equipment, and briefly related the principle of instruction execution as the basis of the micro's decision making capability. We highlighted the fact that these devices, along with the rest of the new technology, are making inroads into the marketplace with such rapidity that the service technician interested in survival would do well to pay close attention. We are now ready to present some of the meat of the subject; by creating a hypothetical piece of stereo equipment that could be belly-up on your bench next month, we will methodically strip the microprocessor of its mystery and, ideally, give you a firm basis from which

to begin the interesting task of catching up with current developments.

#### Why a micro?

In addition to the design and production economics discussed in our first article. there are some other compelling justifications for the use of a microprocessor in many pieces of equipment. The ability to easily perform logical and arithmetic operations on data derived from the outside world, then control certain aspects of that world as a function of those operations, suggests the use of the device in any environment where the tasks to be performed are not so trivial that they can be cost-effectively accomplished with simple hardware. The easy availability of micro's in a variety of configurations at very low cost is pushing the tradeoff to lower and lower levels of complexity (indeed, the example of the blender was not a joke-Hamilton Beach has just introduced a \$69.95 blender controlled by a TMS1000 4-bit chip from Texas Instruments, Inc.). It is precisely this lowering of price, coupled with the innate ability to handle information flexibly, that is causing the processors to appear in so many seemingly unlikely places.

Let's generate a stereo cassette deck in our imaginations, and see if we can justify *not* using a microprocessor to control it.

#### The ET/D Compusette 80

The basic objective of a stereo cassette deck is the faithful reproduction of two channels of sound, with appropriate audio response characteristics for the intended application. In order to fulfill this objective, we need a method of handling the tape, some means for controlling its movement, signal processing electronics, a means of controlling that, and a method of interconnection with the remainder of

the stereo system. In addition, we can add optional features such as the ability to index and search a tape, automatic recording of radio programs, frequency response optimization for the type of tape in use, and so on. Let's take a closer look at some of these types of operations.

At the "gut level" of the deck, we need to worry about the physical handling of the tape. Proper tension must be maintained on the active surface, it must be free of vibration, and the speed must be tightly controlled. These interacting types of functions involve some rather complex relationships which are beyond the scope of this article, but the system concept is as shown in Figure 1. The mechanical reality of reels, capstan, and tape is both sensed and driven by three motors (servos), each with some associated electronics. In order to correlate the operation of the three independent circuits, a CONTROL UNIT receives the signals X, Y, and Z from the servo drivers, as well as a group of mode signals (M) from the rest of the system, expressing desired speeds. The interrelationships necessary to produce accurate speed (or tension) control information from the various inputs can be implemented with traditional analog circuitry (if we don't mind drift, high cost, complex design, and thermal sensitivity) or with a digital system.

#### Closed loop control

The key point here, whatever the means of solution, is *closed-loop control*. If we simply tell the motors to go in some direction at some speed, and then assume that it happens, we are performing open-loop control. If external factors (reel friction, temperature, humidity, physical orientation of the machine, etc.) happen to affect the speed and thus the system performance, we would have no way of




Fig. 1 Motor control system, showing a control unit which generates drive signals as functions of sense signals x, y, z, and the mode controls m. This is an example of closed loop control.




Fig. 2 The ET/D COMPUSETTE 80 from the microprocessor's viewpoint.




Fig. 3 Display logic for the tape counter, shown as separate functional units for clarity. Most of this is available in a single IC.

knowing it. However, if we design circuitry to monitor the operation of the motors (by factors such as current consumption and phase lag—or with built-in tachometers) and then use that information to constantly trim the control signals that we give them, then we have a closed-loop system. In any kind of critical application, such as industrial control, that is the *only* way it is done, for without some built-in monitoring, catastrophic failure could result from relatively minor changes.

This level of closed-loop control raises some new problems. In order to produce a stable, accurate system, the means of deriving drive signals from the sense signals must be very carefully defined. If we simply say, "if it slows down, increase the current," and vice versa, we may well find upon turning it on that the speed will oscillate wildly around the desired speed. This is called underdamping. The means of attaining "critical damping" in the transfer functions of the control system is one of the most interesting applications of the field of calculus.

Fortunately, we don't have to design it right now, just understand enough of the underlying concepts to render it repairable. Attention to a few aspects of system theory can divest the microprocessor in our cassette deck of

its "mysterious black box" status.

#### Inputs and outputs

Even if tape motion control were the only task to be performed in the ET/D COMPUSETTE 80, we might well find that the kind of quality we want could justify a microprocessor. In fact, the sampling rates necessary to achieve critical damping might even call for a little analog help as it stands. But there's much more.

Take a look at Figure 2. Here we have all the inputs and outputs of the system, from the processor's standpoint. The group called "Operator Controls" consists mostly of switch closures, including a small numeric keyboard to allow entry of cueing points on the tape or the stop/start times for automatic recording. Amplifier gain, mixing levels, and the like are conventionally controlled with pots (next year's model will use digital signal processing throughout, but let's keep this one simple). Groups of signals are shown which interact with the motors and amplifiers; these are for the various internal control functions described above. A digital display (4 digits) is provided to show the tape count, and miscellaneous other displays exist to advise the operator of mode, status, and error conditions (Edison would roll over in his grave!). Additionally, there is a line coming in from an optical sensor which is activated by the beginning or the end of the tape (BOT or EOT) as represented by clear leader, and another from a tape motion sensor which we will use to trigger the tape counter.

Now we start to see where a single hardware unit called a microprocessor can simplify a design. Instead of a maze of specialized control functions made out of levers, cams, switches, and other dedicated pieces of hardware, we have one general purpose controller which does virtually everything. In the design of the program, we can include such statements as: IF BOT/EOT OR STOP OR PAUSE OR COUNT-PRESENT OR ERROR OR STOPTIME THEN HALT TAPE MOTION. This single statement (actually, about ten machine code instructions) can eliminate a lot of mechanical hardware.

#### **Counting and searching**

Let's dive into the actual implementation of a control function by designing the logic necessary to handle the tape counter. The display itself is something like that shown in Figure 3, although in a production unit it would be further integrated into one or two chips. Each digit of the display has associated with it a latch (to hold the 4-bit Binary Coded Decimal-BCD-value we wish to display), a decoder (to convert the four bits into seven segment signals), and a driver (to provide current to the light-emitting diodes—LED's—in the display as the decoder dictates). The data for the latches comes directly from the data bus of the microprocessor, and it is stored for the use of the display whenever the device address decoder issues the commands LOSTROBE or HISTROBE. This is a standard type of bus structure, and we will go much deeper into its ramifications in a future article. It is basically a universal method of passing data to and from an assortment of logical devices in a system, under control of the computer.

The data for the display is formatted as shown in the lower part of Figure 3. Two data bytes (eight-bit chunks) each contain two 4-bit binary coded decimal values. When these are strobed into the latches, the 4 digits are immediately decoded and displayed. From the standpoint of the microprocessor, this is accomplished by an instruction such as "OUT LODISP,A"—assuming that the data for the LO two digits started out in the A register. The instruction causes the processor to place the data in A on the data bus, then create the signal LOSTROBE via the address decoder.

#### **Identifying functions**

Now, what functions do we want our counter to perform? It is a simple matter to simply keep track of the tape's position—all that is involved there is the increment of the counter whenever a pulse is received from the tape motion detector (on one of the reels) if the tape

is moving forward, or the decrement of the counter if the tape is moving in reverse. But why stop there? Since we have the counter's value in system memory at all times and control of tape motion is so easy (and, after all, this is a computerized deck and should have some fancy features!) we might as well allow the use to enter a PRESET stop point which will allow searching of the tape to a specific spot. Finding a certain piece of information has classically been a pain with cassettes, and here is our chance to solve the problem. All that is necessary is the storage of the value of the counter at which the user wants the tape to stop. If the SEARCH function is enabled, every time the counter is changed, the program will check to see if it is within 5 counts of the PRESET value. If not, the tape continues at Fast-Forward or Rewind speed, but if so, it is slowed to a lower rate (CREEPING) so its inertia will not cause it to overshoot the mark. Then, when the COUNTER and the PRESET are exactly equal, the tape is stopped. Nice feature.

Figure 4 shows the flowchart of the software necessary to perform these functions. It is a semi-formal expression of the verbal description given above, and represents the complete "procedural" design of the counter sybsystem.

#### Language

In order to make it happen in the microprocessor, we need to express the procedure in terms that can be directly understood by the hardware. The process of programming occurs at a number of different levels, ranging from direct "machine-code" commands written in a mnemonic fashion to a very high level "interpreting" or "compiling" language, allowing expression of the program in something approaching English. The high level languages require a very complex translation program (the necessary end result, after all, is still machine code), and usually a large development system, but the simplicity of their use generally justifies these expensive investments. We're here, however, to learn about the microprocessor, and expression of a program in a few English sentences gives few clues about what goes on inside.

Take a moment to examine the listing in Figure 5. This is a program written in assembly language, which is merely a means of allowing expression of a machine code program in a fashion less cumbersome than thousands of 1's and 0's. Each line of the program (such as


COUNT: CALL INCR in line #7) will, after processing by another program called an Assembler, result in a single machine instruction, consisting of 1, 2, 3, or 4 bytes (in the case of line 7, the actual machine instruction which will be "seen" by the microprocessor is "CD3F00"). The assembler allows not only the convenience of naming instructions with abbreviations that are easy to remember (ADD, SUB, CALL, etc.) but also enables the use of named locations within the program. Without this, the programmer would be required to remember the physical location in memory of each piece of data he might be interested in referencing and each location he might want to jump to. For example, in the first line of the program (line #7), the word COUNT is the label; it represents the starting point of all the code immediately following. When we want the machine to perform that section of the program, we tell it in some fashion to go to COUNT. The fact that COUNT may actually be at address 0000 is of no interest to us humans, but that address is what the computer sees after the program has been digested by the assembler.

Further examining the first line, we note that the instruction at COUNT is CALL INCR. The actual instruction here is CALL, and it directs the computer to go perform the instructions starting at the label INCR(line 40), but to come right back when it encounters a return (RET) (line 49) instruction. When it returns, it simply continues with the instruction following the CALL. "INCR" is called a subroutine, and it is a handy way of providing a section of code that can be used by many other parts of the program. A CALL is distinguished from a JUMP (JP) only by the fact that the latter does not imply a return to the next instruction. A JUMP is a straightforward transfer of execution.

We have seen that the computer will begin executing this program when it is somehow directed to go to COUNT. Where might that direction have come from?

#### The executive

The microprocessor is always in one of two major modes: it is executing instructions as fast as it can, or it is in a HALT state, doing absolutely nothing. Normally, in a machine such as the ET/D COMPUSETTE 80, the processor will be spending most of its time in a section of the program called a *wait loop*, in which it is continually testing various external conditions for something which justifies further action. Thousands of



# "I don't compromise the quality of my service... or the quality of the parts I use."

Your reputation is our reputation

Tube Products Department · Owensboro, Kentucky 42301

GENERAL & ELECTRIC

times a second, it will be asking such questions as:

Has anybody depressed a pushbutton? It is the end of the tape? Is there any kind of error? Do the motors need help? Is there a pulse from the reel sensor? Has anybody depressed a pushbutton? Is it the end of the tape? Is there.

This "loop" continues forever, or until any of the questions receives a "yes" answer. The one that interests us now is the motion pulse from the reel sensor.

In order to give the machine some reference for the control of the tape counter, we associate a slotted disc with the supply reel hub, and monitor it with an optical sensor. The output of this sensor (an LED—Phototransistor pair) is connected to one of the input ports of the microprocessor. Thus, once each revolution of the hub, the processor will be able to detect the passage of some amount of tape (which varies as a function of the tape's depth on the reel, but is repeatable). Whenever this occurs, the processor is directed, by means of the "yes" response to the

question in the loop, to perform the subroutine called COUNT. The instruction would be a CALL, since after the completion of COUNT, we want the machine to return to the wait loop, often referred to as the executive.

#### Counting.....

Most introductory texts on the subject of microprocessors start with binary arithmetic, spend many pages on the rudiments of logic, then laboriously spell out the "instruction set" of the computer. That approach, frankly, is boring. How can you learn if you don't have a framework in mind into which you can fit new information? As long as the stuff being taught is distant and abstract, it stands little chance of being absorbed with any degree of efficiency.

Ah, but we have a cassette deck. It is pretty clear that we want to replace the mechanical counter of traditional designs with an electronic one, and that we are interested in stopping the tape when it reaches some user-defined value. It so happens that we are using a small computer to do this.

Arrive here upon each detection of a reel pulse ent (FWD) or Decreme (REV) Tape Search Mode Yes Add (FWD) or subtract (REV) 5 to or from Compare Counter value to Preset Yes Creeping? counter and compare to preset NO Exi Exit Same? Same? Yes Yes Slow the tape Stop the tape to creeping speed Clear Search Set Creeping Flag and Creeping Flags Flow Chart of Counter Operations Exit Exit

Fig. 4 Flowchart of tape counter operations. The processor arrives here on each detection of a reel pulse, and follows the arrows to take care of display and search functions

And so, the reels turn forward, and a pulse is detected by the executive: the microprocessor suddenly finds itself at COUNT, being told by the first instruction to CALL INCR. Dutifully, it performs the CALL, and finds itself at INCR.

Once there (find the label INCR at line 40 of Figure 5), the processor is immediately directed to "LD A,(LOBITS)". As before, the instruction itself is in the second column (the first being for the labels), and in this case it is a LD, or LOAD. The LOAD instruction is simple—merely a copy of a piece of data from one place to another. The destination and source are given, in that order, in the third column, and are known as the operands of the instruction. Thus, the machine is being directed to move the data in (LOBITS) to A.

Well, if it's not one thing, it's another—we just have to take this a step at a time. "A" is a register—and the most important one of all, since it is the accumulator. Most of the machine's logical and arithmetic operations focus on A. In addition to A, there are registers called B, C, D, E, H, & L. Each of them is a byte, or an eight bit quantity, and they are physically located on the microprocessor chip. A large group of LOAD instructions is devoted to all possible combinations of data transfers between them, such as LD B,E.

#### Memory

But (LOBITS) is not a register, it is a memory location—one which is arbitrarily defined and named by the program. Like COUNT and INCR, it can be found referenced by a label (line 73), but it consists only of one statement: LOBITS: DEFB 0. DEFB stands for "Define Byte", and the purpose of that line of code (which is never executed, since it is data, not part of the program) is to set aside one eight bit location in memory for the purpose of counting tape; there is a second, called HIBITS (line 74), and together they represent the present value of the tape counter.

Thus, execution of LD A, (LOBITS) will result in the value of LOBITS being placed in register A, the Accumulator. The moment this occurs, the processor moves on to the next instruction, which tells it to LOAD register pair HL with the address of INCVAL.

Registers H and L, as well as B & C and D & E, can be treated as a 16-bit pair. Unlike the others, however, the HL pair is used for a very wide variety of addressing purposes. If the programmer wishes to load the contents of some random location in memory (and one of

65,536 locations), he needs to specify a full 16 bit address. This is generally done by loading the register pair HL with that address, then performing the instruction LD A,(HL). The parentheses here, as in the instruction at line 40, instruct the processor to fetch the data located at the address specified by the named contents of the operand. In the first LOAD instruction we talked about, the specified address was defined by the name "LOBITS", and in the case of the instruction at line 42, the address is "INCVAL" since that is what the register pair HL was loaded with in line 41.

**Subroutines** 

The existence of INCVAL (and of TSTVAL, SETVAL, and SLOVAL) is the result of the fact that cassette drives can rewind as well as fast-forward. The function being performed here is merely the increment of the counter, but if the deck were in reverse instead, we would have to decrement it. This could be accomplished by an entirely separate subroutine, called when the executive perceives a pulse during rewind, but that would have been wasteful. Instead, whenever a motion command is given in the motor control part of the program, the variables mentioned above are set to the appropriate values for the code in the COUNT program (see lines 76-79). Obviously, since we are assuming forward motion at this point, INCVAL is equal to 1. the ADD instruction at line 42 merely adds this 1 in memory to the value of A, which still contains the value from LOBITS.

Now, since this is a 4 digit counter (as far as the human user is concerned), and the microprocessor uses 8 bit data quantities, we have a slight tactical problem. Each digit for the display is expressed as a 4 bit value (in BCD), so it takes two of the processor's bytes (LOBITS and HIBITS) to represent them. The only problem is that people like decimal and machines like binary; this results in the need to do some conversion. The good news is that it's easy. We simply split the counter in half and use LOBITS for the right two digits and HIBITS for the left LOBITS for the right two digits and HIBITS for the left two. An eight bit value can be used to express any number in the range 0-255, but we will not allow it to go over 100.

#### **Making decisions**

So, after one is added to the value of the counter's low two digits, we first need to make sure that they are still under 100. The next instruction sets us up to do just that: INC HL increments the present

16-bit address in HL by one, causing it to point at TSTVAL. Then, the CP A,(HL) instruction in line 44 directs the machine to COMPARE the value of A with the value of TSTVAL, which was set to 100 at the same time that INCVAL was set to one. And here, at last, we have our first real example of a conditional test.

A computer would be quite useless if it could not make decisions, and a moment's thought about the manner in which decisions could be made reveals that it is pretty well limited to conditional JUMPs, CALLs, and RETURNs. Let's look at the next instruction (line 45).

JP Z,CARRY . . . . JUMP if ZERO to CARRY. ZERO is one of four special bits called conditional flags, which are manipulated by the internal logic of the microprocessor as certain instructions are performed. Some instructions, like the LOAD group, have no effect on the flags, but others, like the COMPARE, exist largely because of them. The COMPARE instruction affects them very strongly; in fact, their conditions after its execution can be used to detect all possible relationships between A and whatever it was that was compared with it. The most commonly used flag after a

		0001		<<< ET	/D COMPUSETTE 8	0 - COUNTER CONTROL LOGIC >>>	
		0002	1		by Steven K. I	Roberts	
		0004	1		CYBERTRONICS.	INC	
		0005	:		25 August, 19	78	
0000'	CD3P00'	0007	COUNT:	CALL	INCR	:Arrive here when reel pulse - go bump counter :Check for SEARCH operation in progress	
0009,	3A7D00'	0008		LD RRA	A, (SEARCH)		
0007	DO	0010		RET	NC	: (If no Carry flag, return to executive)	
	1 F	0011		RHA		;Check next bit for CREEP mode	
000C'	DA2500' 2A7E00'	0012		JP 1.D	C, CREEP	: If set, then tape im already within 5 counts	
0000	118500'	0014		LD	HL, (LOBITS) DE, SLOVAL	: (Rotate A right - bit U goes to Carry fleg); (If no Carry fleg, return to executive); (Check next bit for CREEP mode; (If set, then tape is already within 5 counts if lace complete counter value in H and L shood D and E with either *5 or 5.  ;Add the 16-bit quantities; (Get the present stop point in DE; Compare PRESET value with counter */- 5.  if nor that close vet, return a secretive.	
00121	19	0015		ADD	HL, DE	:Add the 16-bit quantities	
0013	CD3900,	0016		CALL	DE, (PRESET) COMPAR	Get the preset stop point in DE	
001A1	C0	0018		RET	NZ	; If not that close yet, return to executive	
001D,	3E01 D304	0019		LD	A,SLOW SPEED,A	:If not that close yet, return to executive :Otherwise, load A with the CREEP command :And physically command the tape to slow down	
001F'	3603	0021		LD	A.3	:Now set the CREEP Flag	
0021'	327D00'	0022		LD	(SEARCH), A		
00241	C9 2A7E00'	0023	CREEP:	RET	HL (LOBITS)	and return to executive	
00281	ED588000'	0025	- FEET	LD	DE, (PRESET)	:Arrive here if CREEP in progress - :Have we reached setpoint yet?	
002C'	CD3900'	0026		CALL	COMPAR	· (Use the 16 bit COMPARE utility)	
0030'	€0 3€02	0027		RET	NZ A,STOP	If not, return to the executive Otherwise, load A with the STOP command	
0032'	D304	0029		OUT	SPEED, A	; and issue it. ;Clear A (Exclusive OR A with itself)	
		0030		LD	A (SEARCH),A	Clear A (Exclusive OR A with itself); Use it to reset the SEARCH mode	
0036'	C9	0032		RET		Exit to executive	
0039' 003A'	7 D	0033	COMPAR:	LD CP	A,L	·Comparison utility	
00 1B 1	CO	0035		RET	A.E.	if D & E equal H & L.; then return with ZERO flag set	
003C'	C0 7C	0036		LD	A,H		
003E,	BA C9	0037		CP RET	A,D	; (otherwise, ZERO is reset)	
		0039	3				
003E'	3A7E00' 218200'	0040	INCR;	LD	A, (LOBITS) HL, INCVAL	Get low-order counter value into A	
00451	86	0042		ADD	A. (HL)	Point to increment value profit to increment value padd *1 or -1, depending on tape direction paint to fest value (next location in mex) than it reached 100 (or -1)?  If so, go carry into the next digits potentially adjust accumulator for display	
0.046	23	0043		INC	161.	(Point to Test value (next location in mex)	
00471	CA5200'	0044		CP JP	A, (HL) Z, CARRY	:Ham it reached 100 (or -1)?	
00481	327E00'	0046		LD	(LOBITS),A	Otherwise, store new value	
004E'	27	0017		DAA	LODISP.A	Decimally Adjust Accumulator for display Display it	
00511	C9	0049		RET			
00571	3A8400 '	0050	CARRY:	LD	A. (SETVAL)	Return to calling program Place 0 (or 99) in counter value.	
0055	327E00'	0051		LD	(LOBITS),A	; depending on tape direction	
00591	D308	0053		OUT	LODISP,A	Dimplay it Now the same with high bits -	
00581	1875001	0054		LD	A, (HIBITS) HL, INCVAL	:Now the same with high bits - :Point to Increment value	
005E'	96	0056		LD ADD	A, (HL)	:Point to increment value :Add +l or -l as before :Point to Test value	
0062	23	0057		INC	HL	Point to Test value	
CROME	MCO CDOS ZE	0 ASSEMI	BLER ver	sion 02	1.12	PAGE 0002	
0063	BE	0058		CP	A. (HL)	Test for over- or under-flow	
0064	CA6E00'	0059		JP UD	Z,WRAP (HIBITS),A	ilf so, go "wrap around" the counter iStore new value, otherwise	
006A *	27	0061		DAA		; Ad just	
006B'	D309	0062		OUT	HIDISP, A	:Display new value	
OOAF!	3A8400'	0064	WRAP:	LD	A. (SETVAL)	:Get the wrap value (either 0000 or 9999)	
0071'	327E00'	0065		LD	(LOBITS) .A (HIBITS) .A	:Get the wrap value (mither 0000 or 9999) :Store 2 digits low : and 2 digits high	
0074'	27	0066		LD		:Convert to decimal	
0078' 007A'	D308	0068		OUT	LODISP, A	and display both on the seven segment	
007A'	0109	0069		OUT	HIDISP, A	; LED's	
		0071	:				
007D'	0.0	0072	SEARCH:	DEFB	0	¡Search mode and creep flags	
007F	00	0074	LOBITS:	DEFB	0	High-order counter value	
0000	0000	0075	PRESET:	DEFW	0	absocat stop point	
00824	00	0076	INCVAL:	DEFB	0	Increment value: FWD -> 1 REV -> -3   Ovf1 test value: FWD -> 100 REV -> -1	
00844	00	0076	SETVAL:	DEFB	0	:Count set value: PWD -> 0 REV -> 99	
0085	0.0	0079	SLOVAL:	DEFB	0	#Slow test value: FWD -> 5 REV -> -5	
	(0001)	0081	SLOW:	EQU	1	Slow tape command	
	(0002)	0082	STOP: SPEED:	EQU	2	1Stop tape command	
	(0004)		SPEED: LODISP:		8	Speed control port  Low display port	
	(0009)	0085	HIDISPI	EQU	9	High display port	
	1000011	0086	1	END	COUNT	rEnd Statement (for Assembler age only)	
2084		2001		E14(2)		the province from Wagemerial day Aural	
3086 '	(0000-)						
	s am Length						

Fig. 5 Program listing for counter control functions, using Z-80 Assembly language. Location COUNT at the top corresponds to the top of the flowchart in Figure 4.

### I'VE GOT A SECRET.



DID YOU KNOW THAT WE ARE "THE" MODULE REBUILDERS?

M.E.S. WILL GIVE YOU A HIGHER GUARANTEED PROFIT RETURN. PLUS, WE'LL THROW IN THAT WORKMANSHIP WE'RE BECOMING FAMOUS FOR!

## WE...Specialize in all MAGNAVOX & G.E. MODULES.

- SERVICE ALL MAGNAVOX REMOTE CONTROLS, INCLUDING THE STAR.
- FINAL CHECK ALL MODULES ON AN OPERATING CHASSIS.
- USE ONLY FACTORY SPECS PARTS FOR REPAIRS.
- HAVE BEEN IN TV SERVICING FOR 20 YEARS.
- ARE FACTORY TRAINED, CET'S & STATE LICENSED.
- GIVE YOU A 1 YEAR LIMITED GUARANTEE.

SEND YOUR MODULES NOW..! 48 HOURS IN SHOP SERVICE

## RELY ON THE MODULE REBUILDER



MODULAR ELECTRONICS SERVICES, LTD

4024 W. 10th St Indianapolis, IN 46222 (317) 243-8347

Circle No. 118 on Reader Inquiry Card 26 / ET/D - December 1978 COMPARE is Z (ZERO), and it means, if set, that the two values compared were equal.

Well! If the counter's low digits equal 100 after one was added, go to a routine called CARRY!

Let's assume for now that they have not made it to 100 yet. The next instruction (line 46). which is where the processor goes if they are NOT equal, is another LOAD. The new value of LOBITS is returned to memory.

OUT LODISP,A—OUTPUT to the port called LODISP the contents of A. LODISP is defined near the end of the code (find the label at line 84) with an EQU, or EQUATE statement. That merely means that wherever the assembler encounters the word LODISP, it should substitute an 8 (note the "D308" at the beginning of line 48—D3 means OUTPUT and 08 is the

port number). Thus, the two 4-bit digits from A suddenly appear on the data bus of Figure 3, and the signal LOSTROBE is produced by the decoder. The data in the display changes.

The next instruction is RET, or RETURN. Since we arrived in INCR as a result of a CALL instruction, the RETURN signifies the end of the procedure. The processor immediately returns to the second instruction of COUNT, and proceeds as directed. The total elapsed time since arrival at INCR is 48.5 microseconds.

#### The comment field

That should give you a pretty good idea of how instruction execution progresses through a program. The code in Figure 5 is a complete procedure for the function we have been talking about, shown in the flowchart. (It isn't 100% guaranteed—it was written for this article and not debugged on a system. But what could possibly go wrong? Designs always work the first time. Who was Murphy, anyway?)

We recommend that you continue to study Figure 5, pretending that you are the processor. (It's not a bad life-just dull). When you encounter instruction types that we haven't talked about, look at the comment field to the right of the listing. Try letting the value of LOBITS reach 100. Try letting the value of HIBITS reach 100. Notice the use of the low two bits of SEARCH to govern what happens after INCR is performed. Try writing a program to let the user scan the tape by loading a value called INTERVAL, which is used to switch from fast-forward to Play for a few seconds every time it expires.

The ET/D COMPUSETTE 80 is a fictitious piece of equipment, but the techniques used therein are very real (no pun intended). Using a fraction of the normal amount of hardware and some fairly straightforward software, we can outperform most of the competition at a lower price. Considering the incentives of consumer marketing economics, I think that can be treated as a prediction of things to come.

#### Future subjects

Next in this series we will demonstrate methods of interface between a microprocessor and the rest of the world. Later issues will treat hardware, software, new developments and suggestions for getting hands on experience with a system. This is the only real way to get familiar with a new technology—get hands as well as head into it—suddenly it all clicks, and you're a wizard. £770

#### WANT TO CUT OUT A NEW CAREER IN LAND MOBILE SERVICE?

WE CAN HELP YOU SWITCH

. . . by providing professional HOME STUDY

training for you and your technicians. MTI has been providing specialized training in land mobile servicing for 18 years. We would like to help you also. For more Information, cut out this coupon.

NO SALESMAN WILL CALL!

Name \_\_\_\_\_\_Address \_\_\_\_\_\_

City\_\_\_\_\_\_
State/Zip \_\_\_\_\_\_



Mobile Training Institute
Box 735, Camp Hill, PA 17011

Circle No. 116 on Reader Inquiry Card



THE Source for Antennas and Accessories

JFD ELECTRONICS CORPORATION

A Unimax Group, Inc. Subsidiary Industry Drive, Oxford, North Carolina 27565

27565 Phone: 919/693-3141 Circle No. 115 on Reader Inquiry Card

## Zenith for '79

A no chassis television set.

Here's a most innovative method of assembling a television set.

#### By Walter H. Schwartz

The new series of Zenith TV sets introduced late in 1978's "J" line, the System III Series, makes up approximately 60% of the 1979 line. The System III "Triple Plus" sets number 43 of some 70 "K" line models. The remainder of the line uses a modular vertical chassis very similar to that of the past several years.

The "Triple Plus" all modular sets do not have a conventional chassis and have no assigned chassis number. The modules are self-contained circuit blocks, identified by M-numbers and part numbers, and are connected together by a cabling harness. Everything plugs in-the modules, the power transformer, the filter capacitors, the yoke, the filter choke everything. The only components that are part of the wiring harness are the volume and picture controls. (See Fig. 1 for typical module interconnect.) The "Triple Plus" set. I keep wanting to say chassis, is made up of six to nine modules, the M1 module or IF section; the M2 module, luminance and chroma; the M3 module, horizontal sweep system; the M4 module, power supply; the M5 module, video output; a 9-157 module, secondary controls; and in some sets, an M9 module, Zoom and a remote receiver and its power supply.

#### The M1 module

The M1 module contains the tuners, VHF and UHF, the sync-AGC, audio, and master scan oscillator circuits. This module has several interesting circuit features. Having the turners on the

same module board as the IF, eliminates the interconnecting cable and combined with the SWIF (Surface Wave Integrated Filter), also eliminates any service problems on a tuner-IF matching network. The SWIF sets the basic IF bandpass; the only other IF tuning is a "Maximum Gain Coil" at the output of the IF gain block, tuned to the picture carrier. A "De-Q-ing" transistor circuit driven by the AGC allows maximum video carrier gain at low signal levels for more contrast and less snow. Stronger signals "walk" the bandpass for a more conventional IF response. (Fig. 2)

The synchronous video detector IC includes AFC circuitry and also has noise processing circuitry formerly included in the sync-AGC IC. The new sync-AGC IC incorporates the master scan and horizontal APC circuits on its chip. (Fig. 3). The horizontal APC output is applied to the master scan oscillator, so-called because it does not operate at either the horizontal or vertical rate, but at 503.5 khz and is divided by 32 to produce the horizontal rate and an additional 262.5 times to produce the vertical rate.

#### The M2 module

The M2 module contains the luminance. chroma, and the vertical sweep system. The luminance and chroma systems are quite similar to previous systems, except that they operate on a 12 volt supply. The biggest difference here, from a service standpoint, is lower amplitude color difference outputs. The luminance channel has a lumped constant delay line, made up of discrete coils and capacitors instead of the distributed constant line previously used, to reduce susceptibility to magnetic fields. Also, this module uses thick film circuits for a number of the resistances, as do several other modules

The vertical section accepts the

503khz signal from the M1 module and with appropriate supply voltages provides vertical deflection and horizontal drive to the pre-driver, and blanking to the luminance circuits. (Fig. 4) The vertical countdown IC divides by 16 and then by 2 to produce the horizontal signal via a buffer, for the pre-driver to supply horizontal drive. The divide by 16 stage also drives logic circuitry which provides a pulse to trigger a ramp generator, which in turn drives a differential amplifier, then an output stage and, finally, the vertical windings of the yoke. The logic circuitry also decides if the signal has the standard 525 lines. If not, the ramp generator is not triggered by the countdown circuitry and some of the noise immunity and interlace advantages can be lost. This can happen on some cable or closed circuit systems. The countdown system, of course, eliminates the vertical hold control.


#### **Horizontal** sweep

The M3 module contains the pre-driver, the driver, the horizontal output stage, the sweep transformer, and high voltage and focus voltage supplies. The same module is used for all models, the 2kv difference in high voltage (30kv in 25 V models, 28 kv in 19V models) is produced by different yoke inductances.

The horizontal sweep transformer is completely new. The "Triumph" sweep transformer incorporates voltage multiplication and all voltage dividers within it; no tripler is used. (Fig. 5)

#### **Power supply**

The heavy power supply components are mounted on a small sub chassis, the nearest thing to a chassis in these sets. The components mounted here include the Voltage Regulating Transformer, its tuning capacitor, the filter choke and filter capacitors. The small components,



such as rectifiers, regulator, and line fuse, mount on the M4 module.

#### ZOOM

The M9 module accomplishes six functions:

- 1. It expands the horizontal scan 50%.
- 2. It expands the vertical scan 50%.
- 3. It provides an increase in blanking.
- 4. It enhances color and contrast.
- 5. It turns on the ZOOM light.
- 6. It prevents an increase in high voltage.

Since it is used with in-line tubes, no convergence correction is needed.

The horizontal scan is increased by changing the tuning of the yoke, resulting in increased yoke current. (Fig. 6)) The vertical is expanded by effectively changing the vertical size by shunting the resistors in series with the size control. One set of relay contacts and a diode switching network increases

the blanking level, enhances the picture and turns on the ZOOM lite. (Fig. 7) A capacitor is switched in to load the sweep and prevent the high voltage from rising.

This capacitor consists of four units in parallel so that if one opens the voltage cannot rise excessively. These capacitors also form part of the zoom horizontal blanking circuit (Fig. 8).

#### **Tuning systems**

Several control schemes are used to tune the varactor tuners which are on the M1 modules. The simplest is an 18 position switch which has been used for some time in Zenith manual only systems, as has been the 14 position push button system.

The Space Command 1200 remote is used with the all modular sets. This is a 14 position all electronic sequential system, not a random access system as

used by several other manufacturers. It utilizes a 7 function electronic transmitter. The functions are: On-Off, Volume Hi-Lo, Channel Hi-Lo, Zoom, and Mute.

#### Service tips

Occasionally a lockout condition (mistuning) may occur and produce very confusing symptoms.

Lock-outs usually fall into one of three categories: AFC lock-outs, AGC lock-outs and APC lock-outs (for synchronous detector systems). An AFC lock-out can be identified if the condition occurs only when the AFC switch is in the "On" position. An AGC lock-out is usually caused by a sudden RF overload condition. If the condition can be cured by attenuating the antenna signal or by adjustment of the AGC delay control, the symptoms are indictative of AGC lock-out. Faulty

IF and/or AGC modules should be suspected in this case. APC lock-outs usually occur in combination with either AFC or AGC lock-outs since those conditions produce IF signals outside the range of synchronous detector lock. Under these conditions there is a considerable degree of video distortion and usually considerable audio distortion. An APC lock-out is suspected if the condition can be cured after fine-tuning the tuner with the AFC off, or by slightly detuning the IF oscillator coil. APC lock-outs are usually due to either a faulty 221-97 IC or a leaky APC filter capacitor in the IF module. APC lock-outs and video distortion can also be caused by non-standard modulators and amplifiers in cable antenna systems and some video games.

Since most problems involving lock-outs have been AFC lockouts, it is helpful to understand the mechanism involved in the condition. If, when the AFC turns on, the IF picture carrier (pix) is in a "positive" (+) region of the AFC curve, the "positive" AFC voltage will force the tuner to tune the IF carriers higher in frequency. Alternately, if when the AFC turns on, the IF picture carrier (pix) or sound carrier is in a negative" (-) region of the AFC curve, the "negative" AFC voltage wil force the tuner to tune the IF carriers lower in frequency. However, if, when the AFC turns on, the carriers are outside of the AFC pull-in range they will be forced further outside of the synchronous dectector hold-in range. Although this describes a lock-out from the "smear" side, a similar lock-out can occur from the "moire" side of detuning.

Fig. 2-If system and "DE-Q-ing" circuit (Courtesy Zenith Radio Corp.)


This last condition of AFC lock-out can occur if either the tuner is fine-tuned too far from the nominal tuning point, or the AFC turns on before the tuner has stablized to within the AFC pull-in range. The tuner must have a "positive" AFC voltage to be pulled higher in frequency toward its perfect tuning point. However, the picture carrier is in the "negative" region of the AFC response. This causes the AFC to provide a "negative" control voltage to the tuner, forcing the tuner lower in frequency toward a lock-out condition. The sensitivity or tendency to lock-out can be higher on certain channels (Ch. 5 normally) that have a higher sensitivity to AFC. The sensitivity can be lowered on problem sets by adding a 220 ohm resistor in series with the amplified AFC

voltage from the tuner control center to the tuning package.

Most AFC lock-out conditions involve the timing of the AFC turn on to tuner frequency stabilization. If the tuner has not drifted or stabilized in frequency to within the AFC pull-in range at the instant the AFC is manually or automatically turned on, an AFC lock-out condition will exist. This AFC turn on timing is controlled by the R-C time constant of the AFC defeat circuit (Fig. 9).

The output impedance of the IF AFC defeat circuit together with the 47 microfarad capacitor on the AFC defeat switch determines this time constant.

In order for the AFC to turn on, the voltage on pin 14 of the 221-97 IC must increase to greater than 4 volts.






Fig. 4-Vertical countdown system.

Typically, when the AFC is on, this voltage is at approximately 8 volts. When the tuner is switched between channels (operating the interchannel AFC defeat switch), or when the TV receiver is turned off, the 47 microfarad capacitor is discharged to zero volts. When channel changing is completed or when the TV receiver is turned on, the AFC is still defeated (turned off) for the time it takes to charge the capacitor to 4 volts or greater through the resistance of the IF AFC defeat circuit to B+. This time delay is optimized to allow the tuners to stabilize to within the AFC pull-in range.

If the AFC defeat time delay circuit malfunctions, or is bypassed, or if the tuner takes an unusually long time to stabilize, the TV receiver will have a tendency to AFC lock-out on highly AFC sensitive channels. AFC lock-outs generally occur in this manner under one or two conditions: changing channels or power on-off-on.

If the inter-channel AFC defeat switch




Fig. 5-Horizontal Sweep transformer,

is inoperative, is not connected to the AFC defeat line, or is not present, the AFC will tend to lock-out on channel change. Some mechanical VHF tuners and all mechanical UHF tuners have no inter-channel AFC defeat switch. On some mechanical VHF tuners, the switch is wired to the AFC output lead instead of the AFC defeat lead. Early synchronous detector receivers include an audio muting function connected by diodes to the inter-channel AFC defeat circuit. If a diode fails in the circuit, the conditions will exist for AFC lock-out.

If the TV receiver is turned "off" and then "on" quickly, the AFC defeat 47 microfarad capacitor does not have time to discharge. Under this condition the AFC will remain "on" while the tuner is still stabilizing, producing a tendency for




Fig. 6-Horizontal expansion

68K 1304 TO ZOOM LIGHT RRK **≶**13κ 56K TO ZOOM BLANKING 13 K CIRCUITRY ZOOM BLANKING 100 TRANSISTOR CR9156 CR9153 CR9155 VERT. SIZE 820 ZOOM BLANKING 3 K PICTURE 4 CONTROL

Fig. 7-Vertical expansion, zoom, etc.

a lock-out

A rare condition that could cause AFC lock-out occurs when the antenna signal is suddenly removed and then re-connected. If the IF or AFC system tends to be regenerative at maximum IF gain, the AFC may lock-out. This condition can be checked by noting the AFC output voltage with a strong signal and properly tuned receiver, and then removing the signal entirely. If the AFC output voltage changes enough (greater than ±1 v), the AFC may lock-out when the signal is reapplied.

Most lock-outs are aggravated if the tuner has drifed into, or is fine-tuned into "smear" before the AFC is turned on. This extends the time for the tuner to stabilize in frequency. It should be noted that in a receiver incorporating the 150-190-01 synchronous detector IF module, because of the extended tuning range before color drop-out and "moire," it is difficult to determine the extent of detuning of the tuner.

Thus, even though the receiver is detuned into smear to a point where color is still present, the tuning may be outside of the 1.5 Mhz to 2 Mhz AFC pull-in range.

Another problem which produces obscure or/and intermittent symptoms involves the remote on-off triac. These can cause occasional troubles over a long period of time. When the triac becomes intermittent it can cause side flutter, kick the circuit breaker and then heal for a period of time. The trick here is to confirm a history of flutter. ET/D




Fig. 8-High Voltage Reduction Circuit.





Fig. 9-AFC defeat circuitry.

## ET/D 1978 subject reference index

To make the articles easier to find in the back issues, we have coded the listings in the following manner: first the subject, then a letter code in parenthesis indicating the department in which the item appeared, and finally a number code indicating, first, the month of publication, and secondly, the page in the magazine. The departmental letter code used is as follows: (NP) New Products; (NI) News of Industry; (TR) Test Instrument Report; and (DS) Dealer Showcase. Feature articles are indicated by the absence of a letter code.

	_
	1
ANTENNAS (Including Systems & Accessories)	
MATV Amplifiers	
TV Antenna Development3/20	)
AUTO ELECTRONICS (Radios, Tape Players & Security	
Devices)	
Car Radio Tuners3/30	)
BUSINESS MANAGEMENT	
Getting More Business	š
Independent Electronic Service8/14	ŀ
Pricing For Profit10/26	ò
Servicing Audio Components	
COMMUNICATIONS ELECTRONICS (Including CB)	
CB Signal Characteristics	,
DIGITAL ELECTRONICS	
Digital Electronics, Part 3	;
Introducing The Digital Clock1/24	
Microprocessor and You, (The)	١
Microcomputer, Energy Electronics KX33B5/50	)
Micros On Your Bench8/26	
Microprocessor Technology12/20	
New Home Computer on The Market At \$5001/4	ļ
ELECTRONICS (General)	
Electronic Voltage Regulators	,
Magnetism	
Opto Electronics9/36	ò
Phase Locked Loops Revisited12/12	)
INDUSTRIAL ELECTRONICS	
Daveloning Service Herizons 1/16	

Looking Into Industrial Electronics
Non-Linear Look, (The)
Operational Amplifiers7/23
MICROWAVE OVENS Servicing Microwave Ovens
RADIO (Home Broadcast)
Troubleshooting FM-Stereo Radio
SERVICING TECHNIQUES (General) Intermittents I Have Found
RCA's Direct Address Tuning System
Sony and The G.C.S.
Sony and The G.C.S
Tracking Down TV interference11/30
SERVICING TECHNIQUES (Service Seminar) ADMIRAL
3M10/4M10—Horizontal oscillator driver problems2/10
4M10C—Snivets, ozone smell3/8
4M10—F100 opens, no apparent reason
9M50—Loss of video
M10—NTC resistor failure3/8
M10—Horizontal troubleshooting8/8
M55—IC60012/10
N3—Loss of sync
TL6—No sound
T15K10/16K10—Loss of sync
GENERAL ELECTRIC
CD—Loss of color
C1/L1—No or insufficient vertical
HE—Horizontal hld, colorshift
JA—22 volt zener
KE—Power supply diodes
MA/MB—No raster, buffer module
MA/MB—Vertical sweep insufficient8/8
MA/MB—No vertical sweep
MB-2—High voltage multiplier
MB-75—Herringbone
YA—Bottom, top foldover
YM—Hum
19QB—Horizontal output transistor
MACNAVOV
MAGNAVOX
T955—Vertical output socket
T960—Erratic horizontal sync
T979/T989—CRT socket resistors
T981/T982—Yoke connector
T981/2/7—Washout & retrace lines
T985—Intermittent secondary controls



## One C-meter stands out of the darkness—the \$130 B&K-PRECISION 820

For about one-third the cost of the most popular digital capacitance meter, you can own five times more measurement capability. The new B&K-PRECISION 820 reads from 0.1pF all the way to 1 Farad, in ten ranges. With 0.5% accuracy, the 820 resolves to 0.1pF for a maximum count of 9999.

The 820 retains its high accuracy in freezing cold to blistering 100 degree heat, making it ideal for field use. The bright LED display is easily readable under all lighting conditions. It has the versatility needed for any application and the durability to stay on the job. The 820 can be powered by disposable batteries or optional rechargeable batteries.

You can start discovering your own applications today by seeing your local distributor for immediate delivery. Unlike many specialized instruments, the 820 has almost unlimited applications in engineering, production line work, QC, education and field service. First time users are quickly discovering that the number of time-saving applications exceed their original expectations. For example, you can measure unmarked capacitors... Verify capacitor tolerance ... Measure cable capacitance... Select and match capacitors for critical circuit applications... Sample production components for quality assurance... Measure capacitance of complex series-parallel capacitor networks... Set trimmer capacitors to specific amounts of capacity.. Check capacitance in switches and other components.

PRECISION DYNASCAN CORPORATION

6460 W. Cortland Street • Chicago, IL 60635 • 312/889-9087
In Canada: Atlas Electronics Ontario

International Sales: Empire Exporters, Inc. 270 Newtown Road, Plainview, L.J., N.Y. 11803

T989—Brightness variations	TELEVISION	
T989—HV protection circuit	Electronic Tuning Systems	
T991—No video, narrow raster9/10	High Resolution Television	.9/18
T997—No horizontal sync10/13	New Developments in Television	.9/12
Odyssey—No ball reset10/13	Omega Digital Tuning Systems	.8/16
	Projection Television, Panasonic(DS)	
MOTOROLA	Quasar's Latest Color Receivers	.2/20
	RCA, 1979	
TS-934—Blue convergence11/12	Sylvania for '79	
T.W. 00	Zenith for '79	
PHILCO		,
3CS90/91—Sound module failure1/12	TEST INSTRUMENTS	
A & B line chasses—Hum bar3/12	Appliance And Auto Multitester	
CCY90/91—Sound module failure	EICO 540(NP)	2/42
	ATC's GTS-10 General Television Servicer(TI)	
RCA	` '	,
	Breadboard/Power Supply(NP)	
CTC31—Vertical foldover	Capacitance Box, Zi-Tech TE9000(NP)	5/48
CTC46—Trace SCR	CB/RF Signal Generator(NP)	8/48
CTC48—Circuitbreaker trips	CB Signal Generator, B&K Precision Model 2040(TR)	1/36
CTC59XA—Low voltage power supply	CB Signal Generator, Leader SG-227(NP)	6/46
CTC62—Intermittent vertical collapse	Clamp-On AC Adapter(NP)	9/58
CTC68—Intermittent horizontal hold	Clamp-On DMM(NP)	
CTC71—Insufficient width at high brightness	Color Bar Generator Leader LC6 397	
CTC 72—No color	Counter Timer, Phillips PM6620(NP)	10/49
CTC74—Turn on problems	Counter Timer, Systron Donner 6361A(NP)	8/51
CTC81—IF Module11/12	DC Power Supply, Systron-Donner HHB(NP)	6/44
KCS203—Intermittent start up	Digital Capacitance Meter (NP)	10/50
	Digital Clamp-On Ammeter (NP)	6/52
SONY	Digital Multimeter, Data Precision 258(NP)	8/51
KV1711—Dead fuses OK11/14	Digital Multimeter, Data Precision 1350(NP)	8/34
KV1722—Drive line & vertical foldover	Digital Multimeter, Data Precision Model 1750(NP)	1/43
	Digital Multimeter, DeForest Model MM200(NP)	10/51
GTE SYLVANIA	Digital Multimeter, NLS LM-300,	
A12—AGC-overload		
ATE AGO OVOROGO	LM-350(NP)	5/42
A12—Horizontal line	LM-350 (NP) Digital Multimeter, NLS RMS-350 (NP)	5/42 8/50
	Digital Multimeter, NLS RMS-350(NP)	8/50
A12—Horizontal line	Digital Multimeter, NLS RMS-350(NP) Digital Multimeter, Sinclair Radionics PDM35(NP)	8/50 1/39
A12—Horizontal line	Digital Multimeter, NLS RMS-350(NP) Digital Multimeter, Sinclair Radionics PDM35(NP) Digital Multimeters, Systron-Donner(NP)	8/50 1/39 4/43
A12—Horizontal line	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The)	8/50 1/39 4/43 6/22
A12—Horizontal line       .10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP)	8/50 1/39 4/43 6/22 10/51
A12—Horizontal line       .10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP)	8/50 1/39 4/43 6/22 10/51 4/34
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters	8/50 1/39 4/43 6/22 10/51
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator,	8/50 1/39 4/43 6/22 10/51 4/34 6/16
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10         E21—Black line on right of picture       .9/10	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10         E21—Black line on right of picture       .9/10         E21-3—Power supply regulator       .7/14	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10         E21—Black line on right of picture       .9/10         E21-3—Power supply regulator       .7/14         E21—Low brightness       .3/9	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10         E21—Black line on right of picture       .9/10         E21-3—Power supply regulator       .7/14         E21—Low brightness       .3/9         E21—Convergence       .2/12	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10         E21—Black line on right of picture       .9/10         E21-3—Power supply regulator       .7/14         E21—Low brightness       .3/9	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Ballantine Labs 5725C (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10         E21—Black line on right of picture       .9/10         E21-3—Power supply regulator       .7/14         E21—Low brightness       .3/9         E21—Convergence       .2/12         E41, 42, 44, 45—Dial light low, flickers       .5/14	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Continental Specialties (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10         E21—Black line on right of picture       .9/10         E21-3—Power supply regulator       .7/14         E21—Low brightness       .3/9         E21—Convergence       .2/12         E41, 42, 44, 45—Dial light low, flickers       .5/14	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Continental Specialties (NP) Frequency Counter, Davis Electronics (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10         E21—Black line on right of picture       .9/10         E21-3—Power supply regulator       .7/14         E21—Low brightness       .3/9         E21—Convergence       .2/12         E41, 42, 44, 45—Dial light low, flickers       .5/14	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Continental Specialties (NP) Frequency Counter, Davis Electronics (NP) Frequency Counter, Phillips PM6664-01 (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50 7/44
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10         E21—Black line on right of picture       .9/10         E21-3—Power supply regulator       .7/14         E21—Low brightness       .3/9         E21—Convergence       .2/12         E41, 42, 44, 45—Dial light low, flickers       .5/14         ZENITH       .3GC10—No low VHF       .6/14         19GB1—No audio       .1/14	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Continental Specialties (NP) Frequency Counter, Davis Electronics (NP) Frequency Counter, Phillips PM6664-01 (NP) Frequency Counter, Sencor FC51 (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       7/14         E03/04/05—Compressed lower third of picture       2/12         E20-21—Weak color       9/10         E21—No vertical       11/14         E21—Intermittent color       11/14         E21—Bottom red blue convergence       9/10         E21—Overload       9/10         E21—Black line on right of picture       9/10         E21-3—Power supply regulator       7/14         E21—Low brightness       3/9         E21—Convergence       2/12         E41, 42, 44, 45—Dial light low, flickers       5/14         ZENITH       13GC10—No low VHF       .6/14         19GB1—No audio       1/14         19HC55—Insufficient width       .5/19	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Continental Specialties (NP) Frequency Counter, Davis Electronics (NP) Frequency Counter, Phillips PM6664-01 (NP) Frequency Counter, Sencor FC51 (NP) Frequency Response Recorder, Leader	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50 7/44 9/54
A12—Horizontal line	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Ballantine Labs 5725C (NP) Frequency Counter, Davis Electronics (NP) Frequency Counter, Phillips PM6664-01 (NP) Frequency Counter, Sencor FC51 (NP) Frequency Response Recorder, Leader Instruments Model LFR-5600	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50 7/44 9/54
A12—Horizontal line	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Continental Specialties (NP) Frequency Counter, Davis Electronics (NP) Frequency Counter, Phillips PM6664-01 (NP) Frequency Counter, Sencor FC51 (NP) Frequency Response Recorder, Leader Instruments Model LFR-5600 Frequency Synthesizer, Comstron Adret (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50 7/44 9/54
A12—Horizontal line	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Continental Specialties (NP) Frequency Counter, Davis Electronics (NP) Frequency Counter, Phillips PM6664-01 (NP) Frequency Counter, Sencor FC51 (NP) Frequency Response Recorder, Leader Instruments Model LFR-5600 Frequency Synthesizer, Comstron Adret (NP) Function Generator, B&K-Precision 3010 (TR)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50 7/44 9/54
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       7/14         E03/04/05—Compressed lower third of picture       2/12         E20-21—Weak color       9/10         E21—No vertical       11/14         E21—Intermittent color       11/14         E21—Bottom red blue convergence       9/10         E21—Overload       9/10         E21—Black line on right of picture       9/10         E21-3—Power supply regulator       7/14         E21—Low brightness       3/9         E21—Convergence       2/12         E41, 42, 44, 45—Dial light low, flickers       5/14         ZENITH       13GC10—No low VHF       6/14         19GB1—No audio       1/14         19HC55—Insufficient width       5/19         23HC45—Intermittent raster & sound       10/14         23HC45Z4—No color       10-14         23HC50—Dark left 1/3 of pix       10/14         25EC58—Vertical retrace visible       6/14	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Continental Specialties (NP) Frequency Counter, Davis Electronics (NP) Frequency Counter, Phillips PM6664-01 (NP) Frequency Counter, Sencor FC51 (NP) Frequency Response Recorder, Leader Instruments Model LFR-5600 Frequency Synthesizer, Comstron Adret (NP) Function Generator, B&K-Precision 3010 (TR) Industrial TV Generator (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50 7/44 9/54 .2/44 6/50 7/34 7/40
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       7/14         E03/04/05—Compressed lower third of picture       2/12         E20-21—Weak color       9/10         E21—No vertical       11/14         E21—Intermittent color       11/14         E21—Bottom red blue convergence       9/10         E21—Overload       9/10         E21—Black line on right of picture       9/10         E21-3—Power supply regulator       7/14         E21—Low brightness       3/9         E21—Convergence       2/12         E41, 42, 44, 45—Dial light low, flickers       5/14         ZENITH       13GC10—No low VHF       6/14         19GB1—No audio       1/14         19HC55—Insufficient width       5/19         23HC45—Intermittent raster & sound       10/14         23HC45—No color       10-14         23HC50—Dark left 1/3 of pix       10/14         25EC58—Vertical retrace visible       6/14         25EC58—White streaks       10/14	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Ballantine Labs 5725C (NP) Frequency Counter, Continental Specialties (NP) Frequency Counter, Davis Electronics (NP) Frequency Counter, Phillips PM6664-01 (NP) Frequency Counter, Sencor FC51 (NP) Frequency Response Recorder, Leader Instruments Model LFR-5600 Frequency Synthesizer, Comstron Adret (NP) Function Generator, B&K-Precision 3010 (TR) Industrial TV Generator (NP) Instrument Probes, B&K (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50 7/44 9/54 .2/44 6/50 7/34 7/40 6/48
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       7/14         E03/04/05—Compressed lower third of picture       2/12         E20-21—Weak color       9/10         E21—No vertical       11/14         E21—Intermittent color       11/14         E21—Bottom red blue convergence       9/10         E21—Overload       9/10         E21—Black line on right of picture       9/10         E21-Black line on right of picture       9/10         E21-Jebw brightness       3/9         E21—Convergence       2/12         E41, 42, 44, 45—Dial light low, flickers       5/14         ZENITH       13GC10—No low VHF       6/14         19GB1—No audio       1/14         19HC55—Insufficient width       5/19         23HC45—Intermittent raster & sound       10/14         23HC45—No color       10-14         23HC50—Dark left 1/3 of pix       10/14         25EC58—Vertical retrace visible       6/14         25EC58—White streaks       10/14         25FC45—No high voltage       8/9	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Ballantine Labs 5725C (NP) Frequency Counter, Continental Specialties (NP) Frequency Counter, Davis Electronics (NP) Frequency Counter, Phillips PM6664-01 (NP) Frequency Counter, Sencor FC51 (NP) Frequency Response Recorder, Leader Instruments Model LFR-5600 Frequency Synthesizer, Comstron Adret (NP) Function Generator, B&K-Precision 3010 (TR) Industrial TV Generator (NP) Instrument Probes, B&K (NP) Lab Power Supply, Hewlett-Packard 6235A (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50 7/44 9/54 .2/44 6/50 7/34 7/40 6/48 4/43
A12—Horizontał line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10         E21—Black line on right of picture       .9/10         E21-Black line on right of picture       .9/10         E21-Jebrack line on right of picture       .9/10         E21-Convergence       .2/12         E21—Low brightness       .3/9         E21—Convergence       .2/12         E41, 42, 44, 45—Dial light low, flickers       .5/14         ZENITH       13GC10—No low VHF       .6/14         19GB1—No audio       .1/14         19HC55—Insufficient width       .5/19         23HC45—Intermittent raster & sound       .10/14         23HC45—No color       .10/14         23HC50—Dark left 1/3 of pix       .10/14         25EC58—Vertical retrace visible       .6/14         25EC58—White streaks       .10/14         25FC45—No high voltage       .8/9         25HC45—Low brightness color smears       .10	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Ballantine Labs 5725C (NP) Frequency Counter, Continental Specialties (NP) Frequency Counter, Davis Electronics (NP) Frequency Counter, Phillips PM6664-01 (NP) Frequency Counter, Sencor FC51 (NP) Frequency Response Recorder, Leader Instruments Model LFR-5600 Frequency Synthesizer, Comstron Adret (NP) Function Generator, B&K-Precision 3010 (TR) Industrial TV Generator (NP) Instrument Probes, B&K (NP) Lab Power Supply, Hewlett-Packard 6235A (NP) LCR Bridge, Leader Electronics, LCR-740 (TR)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50 7/44 9/54 2/44 6/50 7/34 7/40 6/48 4/43 10/34
A12—Horizontał line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10         E21—Black line on right of picture       .9/10         E21-Black line on right of picture       .9/10         E21-Jeback line on right of picture       .9/10         E21-Supply regulator       .7/14         E21—Low brightness       .3/9         E21—Convergence       .2/12         E41, 42, 44, 45—Dial light low, flickers       .5/14         ZENITH       13GC10—No low VHF       .6/14         19GB1—No audio       .1/14         19HC55—Insufficient width       .5/19         23HC45—Intermittent raster & sound       .10/14         23HC45—Intermittent raster & sound       .10/14         23HC50—Dark left 1/3 of pix       .10/14         25EC58—Vertical retrace visible       .6/14         25EC58—White streaks       .10/14         25FC45—No high voltage       .8/9         25HC45—Low brightness color sm	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Ballantine Labs 5725C (NP) Frequency Counter, Continental Specialties (NP) Frequency Counter, Davis Electronics (NP) Frequency Counter, Phillips PM6664-01 (NP) Frequency Counter, Sencor FC51 (NP) Frequency Response Recorder, Leader Instruments Model LFR-5600 Frequency Synthesizer, Comstron Adret (NP) Function Generator, B&K-Precision 3010 (TR) Industrial TV Generator (NP) Instrument Probes, B&K (NP) Lab Power Supply, Hewlett-Packard 6235A (NP) LCR Bridge, Leader Electronics, LCR-740 (TR) Logic Probe, AVR Catch-a-Pulse (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50 7/44 9/54 2/44 6/50 7/34 7/40 6/48 4/43 10/34 5/42
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10         E21—Black line on right of picture       .9/10         E21—Black line on right of picture       .9/10         E21—Coverload       .7/14         E21—Low brightness       .3/9         E21—Convergence       .2/12         E41, 42, 44, 45—Dial light low, flickers       .5/14         ZENITH       13GC10—No low VHF       .6/14         19GB1—No audio       .1/14         19HC55—Insufficient width       .5/19         23HC45—Intermittent raster & sound       .10/14         23HC50—Dark left 1/3 of pix       .10/14         23HC50—Dark left 1/3 of pix       .10/14         25EC58—White streaks       .10/14         25FC45—No high voltage       .8/9         25HC45—Low brightness color smears       .10/14         25HC45—C2 setup problems       .10/14         Modules—Bad contacts       .10/14	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Ballantine Labs 5725C (NP) Frequency Counter, Continental Specialties (NP) Frequency Counter, Davis Electronics (NP) Frequency Counter, Phillips PM6664-01 (NP) Frequency Counter, Sencor FC51 (NP) Frequency Response Recorder, Leader Instruments Model LFR-5600 Frequency Synthesizer, Comstron Adret (NP) Function Generator, B&K-Precision 3010 (TR) Industrial TV Generator (NP) Instrument Probes, B&K (NP) Lab Power Supply, Hewlett-Packard 6235A (NP) LCR Bridge, Leader Electronics, LCR-740 (TR) Logic Probes, B&K (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50 7/44 9/54 2/44 6/50 7/34 7/40 6/48 4/43 10/34 5/42 8/46
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10         E21—Black line on right of picture       .9/10         E21-3—Power supply regulator       .7/14         E21—Low brightness       .3/9         E21—Convergence       .2/12         E41, 42, 44, 45—Dial light low, flickers       .5/14         ZENITH       13GC10—No low VHF       .6/14         19GB1—No audio       .1/14         19HC55—Insufficient width       .5/19         23HC45—Intermittent raster & sound       .10/14         23HC45—Intermittent raster & sound       .10/14         23HC50—Dark left 1/3 of pix       .10/14         25EC58—Vertical retrace visible       .6/14         25EC58—White streaks       .10/14         25FC45—No high voltage       .8/9         25HC45—Low brightness color smears       .10/14         25HC45—C2 setup problems       .10/14         40dules—Bad contacts	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Ballantine Labs 5725C (NP) Frequency Counter, Continental Specialties (NP) Frequency Counter, Davis Electronics (NP) Frequency Counter, Phillips PM6664-01 (NP) Frequency Counter, Sencor FC51 (NP) Frequency Response Recorder, Leader Instruments Model LFR-5600 Frequency Synthesizer, Comstron Adret (NP) Function Generator, B&K-Precision 3010 (TR) Industrial TV Generator (NP) Instrument Probes, B&K (NP) Lab Power Supply, Hewlett-Packard 6235A (NP) LCR Bridge, Leader Electronics, LCR-740 (TR) Logic Probes, B&K (NP) Logic Probes, B&K (NP) Logic Probes, Heath (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50 7/44 9/54 2/44 6/50 7/34 7/40 6/48 4/43 10/34 5/42 8/46 10/48
A12—Horizontal line       10/13         A12—No sound, no video, SC408 shorts       .7/14         E03/04/05—Compressed lower third of picture       .2/12         E20-21—Weak color       .9/10         E21—No vertical       .11/14         E21—Intermittent color       .11/14         E21—Bottom red blue convergence       .9/10         E21—Overload       .9/10         E21—Black line on right of picture       .9/10         E21—Black line on right of picture       .9/10         E21—Coverload       .7/14         E21—Low brightness       .3/9         E21—Convergence       .2/12         E41, 42, 44, 45—Dial light low, flickers       .5/14         ZENITH       13GC10—No low VHF       .6/14         19GB1—No audio       .1/14         19HC55—Insufficient width       .5/19         23HC45—Intermittent raster & sound       .10/14         23HC50—Dark left 1/3 of pix       .10/14         23HC50—Dark left 1/3 of pix       .10/14         25EC58—White streaks       .10/14         25FC45—No high voltage       .8/9         25HC45—Low brightness color smears       .10/14         25HC45—C2 setup problems       .10/14         Modules—Bad contacts       .10/14	Digital Multimeter, NLS RMS-350 (NP) Digital Multimeter, Sinclair Radionics PDM35 (NP) Digital Multimeters, Systron-Donner (NP) DMM On Review, (The) Digital Panel Meter, NLS PM-351 (NP) Digital Volt-ohm Meter, Triplett Model 3300 (NP) Digital Voltmeters Distortion Analyzer/Oscillator, Hewlett-Packard 339A (NP) Extending Your Meter's Range FM Stereo Signal Generator (NP) Frequency Counter, Ballantine Labs 5720A (NP) Frequency Counter, Ballantine Labs 5725C (NP) Frequency Counter, Continental Specialties (NP) Frequency Counter, Davis Electronics (NP) Frequency Counter, Phillips PM6664-01 (NP) Frequency Counter, Sencor FC51 (NP) Frequency Response Recorder, Leader Instruments Model LFR-5600 Frequency Synthesizer, Comstron Adret (NP) Function Generator, B&K-Precision 3010 (TR) Industrial TV Generator (NP) Instrument Probes, B&K (NP) Lab Power Supply, Hewlett-Packard 6235A (NP) LCR Bridge, Leader Electronics, LCR-740 (TR) Logic Probes, B&K (NP)	8/50 1/39 4/43 6/22 10/51 4/34 6/16 2/40 10/20 10/48 1/40 5/52 9/56 8/50 7/44 9/54 2/44 6/50 7/34 7/40 6/48 4/43 10/34 5/42 8/46 10/48 9/60

# Here's a new tool repair shops can really use.

# 5/1. Warranty

ON REPLACEMENT TV PICTURE TUBES.

Aside from your fine work, what are you doing to make your customers return to you with more repairs? A nice smile and "thank you, please call again" may not be enough.

Well, Sylvania has come up with a new tool that's sure to help you turn every customer into a steady customer. It's a 5- year warranty\* that you can now offer on replacement picture tubes. So now not only can you offer the best in replacement tubes, but also have a 5-year backing from GTE Sylvania—one of the largest electronics corporations in the world.

For more information on how we can help your repair shop business just contact your nearest Sylvania distributor or GTE Sylvania, Distributor and Special Markets Division, Seneca Falls, N.Y. 13148

SYLVANIA



LIMITED WARRANTY LABOR NOT INCLUDED.

10 40	Multimeter, Leader LT70B(NP)	9/61
-	Modulation Meter, Racal-Dana 9008 9009(NP)	7/40
	Multimeter, Triplett 630(NP)	8/51
	Newcom 1978 (Test Equipment)	7/18
	Oscilloscope, B&K 1432(NP)	5/51
	Oscilloscope, DeForest Model 6010(NP)	10/46
	Oscilloscope, Hickok(NP)	9/58
	Oscilloscope, Leader LBO 507(NP)	5/44
	Oscilloscope, Motorola R1004A (NP)	9/60
	Oscilloscope, Non Linear Systems(NP)	10/51
9	Oscilloscope, Phillips Model PM3211 (NP)	2/41
	Oscilloscope, Dual Trace, Simpson Model 452 (NP)	7/41
	Oscilloscope, Tektronix D66A, D67A(NP)	11/40
	Oscilloscope, VIZ WO-527A(TR)	5/36
	RC Bridge, Continental Specialties(NP)	9/61
	Resistance Box(NP)	6/51
	RF Probe, Triplett(NP)	9/58
	R.F. Signal Generator, Phillips PM5326(NP)	4/52
	RF Wattmeter, Dielectric Communications(NP)	6/46
	RF Wattmeters, VIZ Test Instruments WV-551A,	
	WV-552A (NP)	2/45
	Science Workshop DBV-13(NP)	6/36
	Sine/Square Wave Oscillator(NP)	6/44
	Trouble Shooting With a Scope	6/28
	TV Pattern Generator, Signal	
	Sources 1203, 1204 (NP)	6/42
	Two-way Test Set, Bird 4300-064(NP)	1/39
	Video Analyzer, Sencore VA48(TR)	2/36
	VOM, VIZ WV520B(NP)	8/52
	Wattmeter, Transel Corp, Mark IIA(NP)	3/47



Wattmeter, Directional, Heath(NP WOW and Flutter Meter, Fidelipac Model 65-340(NP)	
TOOLS AND EQUIPMENT  Antenna Rod Cutter	3/46 5/50 3/48 7/42 3/46 5/52 2/40 8/46 6/42 5/44 6/48
VIDEO TAPE EQUIPMENT  VCR Maintenance Kit(NP)  Video Recorders, (Home)  Video Tape Recorders  VTR Test Gear	2/14
Car Radio Tuners CB Signal Characteristics Developing Service Horizons Digital Electronics, Part 3 Digital Voltmeters DMM on Review, (The) Electronic Tuning Systems Electronic Voltage Regulators Extending Your Meter's Range High Resolution Television Independent Electronic Service Intermittents I Have Found Introducing The Digital Gate Looking into Industrial Electronics Magnetism Make your Test Equipment do More MATV Amplifiers Micro processor and you, (The) Micros on your Bench Newcom 1978 New Developments in Television Non-Linear Look, (The) Omega Digital Tuning Systems Operational Amplifiers Opto Electronics Quasar's Latest Color Receivers RCA, 1979 RCA's Direct Address Tuning System Servicing Audio Components Servicing Microwave Ovens Sony and the G.C.S. Sylvania for '79 Tracking Down TV Interference Trouble Shooting with a Scope TV Antenna Development Video Recorders, (Home)	
Video Tape Recorders  VTR Test Gear  What's Ahead in Consumer Electronics  Zenith for '79	.2/16

P.O. Box 1005, Burlington, Iowa 52601

This is not just another continuity checker. In last, this amazing pocket tester is so unique, it's patented. It does everything! And it does without expensive meters and hard-to-handle test leads.

CORDLESS! SWITCHLESS!

With just a touch of the probe. you can test for:

- Continuity
- Voltage
- Polarity

Test: 6 volt to 240 VAC 1 volt to 90 volt DC

The \*DC% salid state CVP Multitester can be kept in pocket or tool box to instant v check

- Floating grounds
- Copacitors
- Leakage
- Fuses
- AC ire voltage
- DC voltage
- DC polarity
- Lamps
- Diodes
- Autovoltage check
- Breaks in printed circuit boards

- AC neutrals
- Ground potential on medical and other equipment
- Much more

Once you try the Workman CVP Multitester you'll never be without one again. See it now at your WEP/Workman distributor.

Uses 3 "N" cells (not included)

Workman battery #33-134 P.O. Box 3828


Sarasota, Fla. 33578 813-371-4242

WORKMAN TWX 810-864-0401 ELECTRONIC FRODUCTS INC

DR

Circle No. 130 on Reader Inquiry Card

ANNOUNCING THE WORKMAN



# BULLETIN

The oscilloscope is a primary measuring and troubleshooting instrument. Unfortunately, too often its capabilities and uses are not well understood by the technician. Some technicians are, in fact, reluctant to use the oscilloscope because of this lack of understanding. "Oscilloscopes" by Rien van Erk, is an attempt, in the words of the publisher, to bridge the information gap between the operator's manual and the application of the instrument to the problem at hand. The book begins by explaining the theory of the basic oscilloscope and then the theory of more sophisticated features, such as delayed sweep, and special instruments, such as memory oscilloscopes and sampling oscilloscopes. A number of examples of measurement setups are given. These are examined with a view to avoiding pitfalls which could result from a lack of understanding of oscilloscope limitations. An extensive glossary of terms and a chapter explaining oscilloscope specifications should make manufacturers' literature more understandable. "Oscilloscopes" gives a more than adequate basic explanation of oscilloscope usage. It is particularly good when explaining special features and specialized types of oscilloscopes. "Oscilloscopes: Functional Operation and Measuring Examples," Rien van Erk, 270 pages, 248 illustrations, \$16.50, McGraw-Hill.

Fordham Radio has just published its 1979 Catalog of 164 pages featuring a great variety of test equipment, tools and

supplies for the service industry. Most of the major consumer electronic test instrument manufacturers' equipment is included; tool kits as well as individual tools, are prominently featured; and a broad range of replacement parts are listed. The catalog is available free from Fordham Radio Supply Company, 855 Conklin St., Farmingdale, NY 11735.

"Understanding Solid State Electronics", new and updated third edition is now available. Written in very understandable, nontechnical language, it covers semiconductor devices and technology to provide a basic understanding of diodes, transistors, thyristors, digital and linear integrated circuits. MOS and large scale integrated circuits and the technology used in their fabrication. The book should be a good review for the technician and could clear up areas of hazy understanding. It is available for \$3.95 (softback) from Texas Instruments Inc., P.O. Box 3640, M.S. 84, Dallas, TX 75285.

A great quantity of sophisticated highfidelity audio equipment exists today and often confuses the technician with its complexity. Some television technicians refuse to repair stereo high-fidelity equipment. A direct coupled audio system can have apparent problem in one stage caused by a defective component in earlier stages. Feedback circuits can further complicate troubleshooting. "Handbook of Audio Circuit Design" and "Audio Technology Systems: Principles, Applications and Troubleshooting." both by Derek Cameron, can go a long way toward solving audio service problems. "Handbook" covers basic design, transistor biasing, feedback, amplifier configurations, and temperature compensation, for example. "Audio Technology Systems" covers amplifier types, distortion, measurements, and troubleshooting, and

FM tuner and stereo decoder troubleshooting. Several chapters cover electronic music and electronic organs. Some good basic information is offered on interference to audio equipment from outside sources such as radio transmitters and automobile ignition. Both books are published by *Reston Publishing Co.*, A Prentice-Hall Company, Reston, VA 22090. Price: \$15.95 each.

A new catalog of tools for electronics and precision mechanics is now available from Jensen Tools and Alloys. The 152-page catalog offers over 3000 tools for technicians, instrument mechanics, locksmiths, and hobbyists. For a free copy write: Jensen Tools and Alloys, 1230 S. Priest Dr., Tempe, AZ 85281.

Technical Training on Sony Betamax VTR's is now available on a series of video training tapes. Eight tapes cover: operation, technical overview, luminance signal processing, chroma signal processing, servo system, system control and audio, mechanical maintainence, troubleshooting and head replacement. The tapes run between 30 and 45 minutes each and cost \$24 each. A free catalog and additional information is available from: Sony Corporation, Training Tape Production, 700 W. Artesia Blvd., Compton, CA 90220.

A new Test Instrument short form catalog was recently released by Leader Instruments. The catalog reportedly covers many new test and measurement instruments introduced during the past several months. It is said to describe eight oscilloscope models, eight professional audio instruments, four multimeters, both analog and digital, two frequency counters. three color bar generators, including an NTSC Model, an FM multiplex generator, an LCR bridge and other instruments and accessories. The catalog is available from Leader distributors, or Leader Instrument Corp., 151 Dupont St., Plainview, NY 11803.

Automotive speakers and audio accessories are the major subjects of a new 1978-79 catalog from Almotronics. The catalog features single and coaxial and triaxial speakers and systems with and without enclosures, audio plugs, jacks, and cables, CB accessory mounts, speakers, plugs, cables and antennas, and telephone jacks, plug, and cords. It also illustrates displays for these products. For a free copy write: Almotronics, 9815 Roosevelt Blvd., Philadelphia, PA 19114. £77D

# The only thing you need to know about Quartz Crystals is...1-405-224-6780

When you call that number, you reach an expert who is backed by the world's largest stock of crystals and who can give you infoadvice-and service second to none.


# Sentry gives you:

- Best Delivery plus Emergency Service with Guaranteed Delivery
- Highest Quality with gold MIL-C-3098 Process
- Ask for Sentry Technology Manual





Toll Free Order Line 1-800-654-8850



General Electric has the magic number. A toll-free hotline connecting you directly with the GE Parts Center in most all areas. And the simple key to using it is charging your order to VISA, Master Charge or an approved GE Open Credit Account.

That's one way we're making your business easier. But it's not the only way. We're continuing to increase stocks throughout our national computer-linked parts distribution system. And striving to fill orders faster than ever before.

To make GE Performance Television even easier to service, we're packing a new Mini Manual into the back of every color set. It gives

you the right schematic diagram, parts list, symptom repair information and safety features for the set you're working on. Which makes your job a lot easier.

For our list of toll-free numbers and everything you need to order GETV parts fast fill out and send in the coupon below. It's our business to make your business easier.

ETD 78 "DUTCH" MEYÉR GENERAL ELECTRIC TELEVISION ONE COLLEGE BOULEVARD PORTSMOUTH, VIRGINIA 23705 Please send the following: ☐ Brochure covering GE toll-free-ordering numbers. Listing of Parts Distributors. Master Charge and VISA information. ☐ GE Open Credit Account information. Name Service Company Address Zip State City.



# TEST INSTRUMENT REPORT

Don't call them color bar generators anymore. We are long since past the time when the typical "color generator" provided only three or four color and line patterns. The new and modern breed of video generators have evolved into sophisticated video signal generating test instruments.

And Leader's LCG 397 Pattern

signals for use in television or VTR troubleshooting work.

The RF/VIF, 300 ohm output jacks work in conjunction with one of two green control pushbuttons to determine the mode of the output—either channel 5 or channel 6 RF frequencies, or (with the VIF/RF button engaged) the 45.75 MHz output for direct connection to the video IF input of the receiver. Thus the 397 maybe used as a tuner sub.

Another video output jack on the 397 supplies composite video and makes the unit a suitable source for VTR work.

The final two of the 10 control buttons select power on and off (red button) and the yellow works in conjunction with the scope trigger output to select either line (15.75 kHz) or field (60Hz).

Fifteen of the signals are for general use in convergence or video bandwidth response checks. There are the three color patterns plus the 12 dot and line patterns—the latter being the traditional vertical, horizontal, and crosshatch.


The LCG 397 provides two gated rainbow displays, the 10 bar display includes R-Y, B-Y and -R+y, the third, sixth, and ninth bars. Rapid phase checks may be made with the LCG 397 by selecting the three bar gated display which effectively shuts off all but the third, sixth and ninth bars.

In the ungated mode, the unit produces a continuous rainbow on the CRT.

One feature of the LCG 397 which facilitates quick color bandpass response is that all of the color bars are of equal 100 per cent amplitude, unlike the broadcast standard color signal which is attenuated to around 45 per cent in the G-Y range and boosted to 130 per cent of correct amplitude in the B-Y range. Thus by feeding the 10-bar gated rainbow into the receiver under test and reducing brightness while observing the screen, a general idea of the receiver's overall chroma bandpass may be obtained since the green bars should be first to disappear followed by red, and leaving blue.

Another interesting feature of this Leader generator is the variable color burst amplitude control dial for quick color killer threshold checks. In the calibration position the LCG provides a 100 per cent burst level. However, this is adjustable from zero to about 150 per cent of correct amplitude.

A rough check of video bandwidth is possible with the Pattern Generator with the help of the crosshatch patterns. Receivers with restricted bandwidths are unable to pass the high harmonic content of the narrow vertical line pulses, thus these lines appear washed out on



For more information about this instrument, circle 150 on The Reader Service Card in this issue.

# Leader Instrument's LCG 397 Pattern Generator

Packed with signals

By Richard W. Lay

Generator fits perfectly into this evolving trend of more punch per pound by providing alternative versions of the most often used video test signals and in extremely portable form.

But, this isn't all, this state of the art high technology piece of equipment is—pound for pound—among the most versatile generators on the market.

Weighing 1-½ pounds with a front panel 6-½ by 2-¼ inches, the LCG 397 is as ideally suited for bench work as it is adaptable to field service. The unit is controlled by 10, color coded, front panel pushbuttons, a three position slide switch and a variable color burst amplitude control knob.

Also located on the front panel is a power indicator LED that automatically signals low battery power by flashing when the four C-cells drop below 3.6 Vdc.

The relatively new entry from Leader, introduced officially at this year's NEW-COM show (see ET/D, July P. 18) really does go a step beyond, all things considered. Six blue front panel pushbutton controls, in conjunction with the slide switch, provide the 18 video substitution

the CRT screen under such conditions.

The three additional signals available from the 397 are the unmodulated video carrier and the unmodulated subcarrier. By depressing the blue pushbutton farthest to the right and selecting the sub carrier with the slide switch, a quick calibration check of the unit is possible. (For gated rainbow operation this should be 3.563795 MHz, plus or minus 20 Hz.)

Similarly by moving the slide switch to the upper position, a calibration check of


the unmodulated video carrier is possible (77.25 for Channel 5, 83.25 for Channel 6, and 45.75 for VIF).

The 18th pattern available is gray raster for purity checks.

Perhaps the feature that makes the LCG 397 easiest to use, however, is the scope trigger output which permits triggered input for all pattern displays with rock solid lock in.

Priced at \$295, the unit is available with an AC adapter for bench use. ET/D

# for an experience in electronics.



# get into cameras

Improve your income by acquiring additional skills as a camera repair technician. Increasing use of electronics in cameras is creating still more opportunities for camera repair specialists. Take advantage.

### Performance Training

National Camera developed the first comprehensive technical training for camera repair technicians in the '50's. More practicing technicians have received training from us than from any other single source. Now this better-than-ever professional program is as close to you as your mailbox. Learn at home!

### Complete Package

You get texts, tools, practice equipment — a complete program including the latest additions in photographic electronics - not available anywhere else.

# Free catalog

Find out about great training programs in camera repair technology. You can learn at home, keeping your present job, or at our one-year resident school in Colorful Colorado. For free information, use the card in this publication or write us today.



Technical Training Division, Dept. ECA 2000 West Union Ave. Englewood, Colorado 80110

Accredited member: NHSC, NATTS

# **Specifications**

PATTERNS:

Offset sub-carrier system 3.563795 MHz ± 20Hz

**BURST LEVEL** 0 to 150% variable

BAR LEVEL 100% fixed

**COLOR BARS** 10. 3 and rainbow

CONVERGENCE

Dots, intersection of vertical and horizontal bar, white on black background, 15 × 21, 7 ×

11, center dot.

Crosshatch, white lines, black background, 15 × 21, 7 × 11, Vertical lines, white, black background, 21,

Horizontal lines, white, black background, 15,

Gray raster, 0% level, black raster. Subcarrier, continuous color subcarrier, no sync.

RF/VIF Output Channel: 5 or 6: VIF Impedance: 300 balanced Output: 10mv or more

COMPOSITE VIDEO Output: App. 2v p-p Polarity: Negative sync Impedance: App. 10KΩ



NEW! AN IN-CIRCUIT ELECTROLYTIC CAPACITOR TESTER THAT REALLY WORKS!

The Creative Electronics ESR METER! (Equivalent Series Resistance)

Checks capacitors from 1 to 10,000 MFO in-circuit, charged or not!

Tells you how close to failure the capacitor is by measuring the dryness of the electrolyte - the major reason for electrolytic failures.

Plainly shows up intermittent opens resulting from bad terminations.

Research shows that both problems account for 99% of today's electrolytic failures. Both can be located instantly with our ESR Meter!

Increases the productivity & profit of the typical service shop by 5%. Patent pending. For free brochure, just send name & address to:

Creative Electronics

0 n 1 v ESR Brochure 1417 N. Selfridge Clawson, Mich. 48017 \$79.50 postpaid 30-day Satisfaction Guaranteed.

Circle No. 131 on Reader Inquiry Card

### DIGITAL MULTIMETER M - 1200



\$69.95 Kit

**\$89.95** Assembled

Comparable value \$189.00 10 Day Money Back Guarantee

- 3-1/2 digits .56" high for easy reading
- High accuracy, 1/2% typical
- 10 megohm input impedance
- Input overload protection to 1000V
- · Auto zeroing, automatic polarity Overrange indication
- · Low ohms, .01 ohm resolution
- · AC line operation. Battery optional
- Measure resistor or dlode in circuit

## SPECIFICATIONS

DC volts . Range 200MV, 2V 20V. 200V. 1000V. Resolution .1MV ... Range 2MA, 20MA DC Current .... 200MA, 2 amps. Resolution 1 microamp . Range 200MV, 2V AC volts 20V. 200V, 1000V. Resolution .1MV ... Range 2MA, 20MA AC Current 200MA, 2 amps. Resolution 1 microamp . Range 20, 200, 2k Resistance 200k, 2 meg, 20 meg. Resolution .01 ohm

Send check to:

## ELENCO ELECTRONICS. INC.

1936 Raymond Drive Northbrook, Illinois 60062

C.O.D. add \$2.50 Battery optional add \$10.00

Circle No. 108 on Reader Inquiry Card

# **DEALER'S** SHOWCASE

The suggested retail price of the Model 2300 is \$700. The Model 8000 is \$700. And the Model 2900 is \$500.

# **Audio Cabinet**

Circle No. 133 on Reader Inquiry Card

Gusdorf offers a new unit of electronic furniture intended to house audio components. It has four adjustable interior shelves which can accomodate most types of equipment. The lower section of the cabinet is storage compartments with slide up doors and removable record dividers. The full back has access holes with removable plugs to organize


alarm memory stores the time and date of an alarm, automatically displaying this information when the recorder is stopped. Thus, recorded events at specific alarm times can easily be located and reviewed. A remote alarm can trigger a change in recording speed to any of four pre-selected rates. Switches also permit the user to choose alarm duration, as well as any of 15 camera switcher pulse rates. Both models will be available at optional user prices of \$3090 for the TC3250 and \$2775 for the TC3200.






Circle No. 135 on Reader Inquiry Card

Channel Master has introduced a new CB beam called Signal Tracker. The Signal Tracker is a high efficiency beam made of drawn aluminum tubing. The company claims it can be completely assembled and ready for mounting in less than ten minutes. It has a boom length of 12.0 ft. Channel Master claims it has a 13.5 db gain over an isotropic source and front-to-back and side separation of 30 db, thereby outperforming beams up to 25% greater in length. It is gold EPC coated for weather protection and can be adjusted for optimum performance on a desired channel, covering all forty channels. The Model 5059's price is \$79.95. ETD







# Stereo High-Fidelity Equip.

Circle No. 132 on Reader Inquiry Card

A line of high end stereo high-fidelity equipment is available from Scientific Audio Electronics, Inc. Included in the line are a new power amplifier, the Model 2300; the model 8000 FM stereo tuner; the Model 2900 stereo preamplifier; and other items of sophisticated audio equipment, such as the Model 500 impulse noise reduction system.

The Model 2300 power amplifier, according to the manufacturer's specifications, delivers 150 watts per channel minimum RMS power into 8 ohms from 20 to 20,000Hz with no more than 0.05% THD and features full thermal protection, relays to protect the speakers from low frequency damage and electronic protection against transient overload and short circuits.

The Model 800 tuner has a digital readout, a linear phase IF section which allows stereo distortion of 0.2% or less, a MOSFET front end which produces a spurious response rejection of over 100dB and an IHF sensitivity of 1.6 uv. according to SAE.

The Model 2900 preamplifier, SAE states, features parametric equalization, 0.01% THD and IMD and a phono signal to noise of 90dB (IHF "A" weighted).



connecting wires. The Model #1435 stands 48 in. high, the left compartments are 23% in. wide, the right compartments are 191/2 in. wide and the compartments are 191/2 in. wide and the unit is 17 in. deep. The retail price is approximately \$144.

# Time Lapse Video Recorders

Circle No. 134 on Reader Inquiry Card

RCA Closed-Circuit Video Equipment has announced two new time lapse recorders for closed circuit TV security systems. The recorders, the standard TC3250 with an internal time/date generator and the low-cost TC3200 without this feature, use 1/2 in. VHS cassettes instead of the reel-to-reel' tapes used previously in most such systems. Both models permit the user to select any of 50 different record/ playback speeds, permitting a maximum recording time of 200 hours at the slowest speed. The TC3250 model incorporates controls that position the time/date display on the screen and also control with width of the display. An

101-416 p. (8½"x11")—Electronic Circuit Design Handbook-(\$17.95)

ELECTRONIC CIRCUIT DESIGN HANDBOOK

HAM RADIO
GIRGUITS

An Extraordinary Offer to introduce you to the benefits of Membership in

# **ELECTRONICS BOOK CLUB**

take any of these 22 unique electronics books (values to \$67\mathbb{\text{9}}) for only

\$ 199

for ALL FOUR

with a Trial Membership in the Book Club that guarantees to save you 25% to 75% on a wide selection of electronics books



# Facts About Club Membership

 The 4 introductory books of your choice carry publisher's retail prices of up to \$67.80. They are yours for only \$1.99 for all 4 (plus postage/handling) with your Trial Membership.

● You will receive the Club News, describing the current Selection, Alternates, and other books, every 4 weeks (13× a year). 
● If you want the Selection, do nothing; it will be sent to you automatically. If you do not wish to receive the Selection, or if you want to order one of the many Alternates offered, you simply give instructions on the reply form (and in the envelope) provided, and return it to us by the date specified. This date allows you at least 10 days in which to return the form. If, because of late mail delivery, you do not have 10 days to make a decision and so receive an unwanted Selection, you may return it at Club expense.

pense:

To complete your Trial Membership, you need buy only four additional monthly Selections or Alternates during the next 12 months. You may cancel your Membership any time after you nurchase these four books.

All books —including the Introductory Offer — are fully returnable after 10 days if you're not completely satisfied.
 All books are offered at low Member prices, plus a small

 All books are offered at low Member price postage and handling charge.

● Continuing Bonus: If you continue after this Trial Membership, you will earn a Dividend Certificate for every book you purchase. Three Certificates, Flus payment of the nominal sum of \$1.99 will entitle you to a valuable Book Dividend of your choice which you may choose from a list provided Members.

M ay we send you your choice of 4 of these practical time-and-money-saving books as part of an unusual offer of a Trial Membership in Electronics Book

Here are quality hardbound volumes, each especially designed to help you increase your know-how, earning power, and enjoyment of electronics. Whatever your interest in electronics, you'll find Electronics Book Club offers practical, quality books that you can put to immediate use and benefit.

This extraordinary offer is intended to prove to you through your own experience, that these very real advantages can be yours...that it is possible to keep up with the literature published in your areas of interest, and to save substantially while so doing. As part of your Trial Membership, you need purchase as few as four books during the coming 12 months. You would probably buy at least this many anyway, without the substantial savings offered through Club Membership.

To start your Membership on these attractive terms, simply fill out and mail the coupon today. You will receive the 4 books of your choice for 10-day inspection. YOU NEED SEND NO MONEY. If you're not delighted, return the books within 10 days and your Trial Membership will be cancelled without cost or obligation.

ELECTRONICS BOOK CLUB, Blue Ridge Summit, Pa. 17214

# **ELECTRONICS BOOK CLUB**

Blue Ridge Summit, Pa. 17214

Please open my Trial Membership in ELECTRONICS BOOK CLUB and send me the 4 books circled below. I understand the cost of the books I have selected is only \$1.99 for all 4, plus a small shipping charge. If not delighted, I may return the books within 10 days and owe nothing, and have my Trial Membership cancelled. I agree to purchase at least four additional books during the next 12 months after which I may cancel my membership at any time.

101 709 743 785 800 801 874 887 891 909 913 919 971 995 997 1012 1017 1035 1036 1085 1092 1101

Name	Phone
Address	
City	
State	Zip
(Valid for new Members or	ly. Foreign and Canada add 10%.) T-128

# **NEW PRODUCTS**



# Combination Microphone and Speaker


Circle No. 136 on Reader Inquiry Card

The same miniature transducer in user's ear can be used as a microphone and a speaker with The Ear Com system available from the Electronic Instrumentation Division of Lear Siegler, Inc. It allows hands-free, two-way communication in high ambient noise situations. The manufacturer states it is being used by SWAT teams, refinery and chemical plant workers and fire fighters as well as under cover and surveillance work by police agencies.

# Time Marker Generator/Sweep System

Circle No. 137 on Reader Inquiry Card

A low cost, time marker frequency sweep generator for commercial, educational, or hobby use in calibrating oscilloscopes is being introduced by A. E. Corp. of Needham, MA. The Time Marker frequency sweep generator lets an oscilloscope simultaneously display



the amplitude of a sweep signal at a number of different frequencies marked by a calibrated reference reticle. It is adjustable from 1hz to 100khz in factor of 10 increments. The A. E. Corp. Time Marker frequency sweep generator consists of a Model 12 sweep function generator and a Model 20 pulse generator linked by a Ramp and Marker interface. The Models 12 and 20 may be used independently and, if desired, a clock or oscillator may be substituted for the Model 20. The A. E. Corp. Time Marker frequency sweep generator retails for \$155 (kit) and \$240 (assembled). The Model 12, Model 20, and Ramp and Marker interface are also offered individually.

# **Mobile Towers**

Circle No. 138 on Reader Inquiry Card




Aluma Tower Company has introduced a new series of "Mobile Van Towers" for communications and test work. The manufacturer states the towers can be mounted on a standard ladder rack on top of a van, tilted to a vertical position and cranked up to the desired height easily by a single operator. Several models are available including two intended for use with internally mounted rotators.

# **Resistor Storage Box**

Circle No. 139 on Reader Inquiry Card


LOWCO Engineering's model RS-144 resistor selector box provides separate storage for 144 resistor valves, with "instant" visual inventory of all resistors. Ten to twenty-five resistors will fit in each



of the 144 compartments, depending on whether 1/4, 1/2, or 1 watt carbon or carbon film resistors are stocked. All compartments are individually pre-marked with the 5% range from  $1\Omega$  to  $990K\Omega$ . The size is  $14\times14\times3''$ . The price is \$4.75. Stocked with 1440 carbon film resistors, 10 of each value, the price is \$79.45.

# Wire-Wrapping Kit

Circle No. 140 on Reader Inquiry Card



A new wire-wrapping kit for the prototype builder or hobbyist is available from *OK Machine and Tool*. The kit includes the Model WSU-30, a combination wrap-unwrap tool and stripper for 30AWG wire, and a 50 ft roll, plus assorted 1 to 4 in. lengths of 30AWG Kynar insulated silver-plated copper wire. Wire colors available are red, blue, yellow and white. The kit is priced at \$12.95.

## **Digital Multimeter**

Circle No. 141 on Reader Inquiry Card

Sinclair Radionics has recently introduced a new bench portable digital multimeter, the DM235. This 3½ digit LED display meter is intended for portable use according to the manufacturer who states it weighs 1½ pounds and is only 1½ inches thick and operates on 4 "C" cells with a rechargeable battery pack and an ac adapter/charger available as options. The price is \$89.95.





# CLASSIFIED

RATES: 40 cents per word (minimum charge, \$10). Bold face words or words in all capital letters charged at 50 cents per word. Boxed or display ads charged at \$50 per column inch (one inch minimum). For ads using blind box number, add \$5 to total cost of ad. Send ad copy with payment to Dawn Anderson, ELECTRONIC TECHNICIAN/DEALER, 1 East First Street. Duluth, MN. 55802.

BOX NUMBER REPLIES: Mail box number replies to: ELECTRONIC TECHNICIAN/DEALER, Classified Ad Department, One East First Street, Duluth, MN 55802 Please include box number In address.

# FOR SALE

SONY-PANASONIC-RCA-ZENITH-EXACT REPLACEMENT PARTS—LARGE INVEN-TORIES—SEND PART OR MODEL NUM-BERS—WILL UPS COD—GREEN TELE RADIO DISTRIBUTORS, 172 SUNRISE HIGHWAY, ROCKVILLE CENTRE, N.Y. 11570 5/79

FOR SALE: COLOR PICTURE TUBE REBUILDING EQUIPMENT SEMI-AUTOMATIC ELECTRONICALLY CONTROLLED PROCESS. Call or write Atoll Television, 6425 Irving Park, Chicago, IL \$0634 Phone 312-545-6667.

TELEPHONES UNLIMITED, equipment, supplies, all types, regular, decorator, keyed, modular. Box 1147T, San Diego, California 92112.

TRANSISTOR REPLACEMENT. PHYLTRON ELECTRONICS LX REPLACEMENT LINE REPLACES THE MOST POPULAR REPLACEMENT TYPES AT OR BELOW DISTRIBUTOR COST. One year unconditional guarantee. Buy direct and save. Write for free catalog. Phyltron Electronics, 487 Springfield Ave., Summit, N.J. 07901.

ELECTRONIC BARGAINS, CLOSEOUTS, SURPLUS! Parts, equipment, stereo, industrial, educational. Amazing values! Fascinating items unavailable in stores or catalogs anywhere. Unusual FREE catalog. ETCO-013, Box 762, Plattsburgh, NY 12901.

# GET OUT OF THE TV RUT

Start making money now with Paltronix portable security systems. No technical hassles to keep up with. Full training provided. Good margins to work with. Plus your chance to diversify your services. For full details contact Don Musil, 48 West Golden Lake Road, Circle Pines, MN, 55014 (612) 786-4244. 9/78

Save hundreds: dependable, quality Head-Ends, V/V, U/V Converters, Camera Modulators. Factory prices. Send \$5.00 (or business card). "Information," Box 809, Boynton Beach, FL 33435.

# PICTURE TUBE MACHINE

We buy and sell NEW AND USED CRT rebuilding machinery. COMPLETE TRAINING. Buy with CONFIDENCE from the ORIGINAL MFGR. For complete details, send name, address and zip code to:

### LAKESIDE INDUSTRIES

4069-71 N. Elstone Ave., Chicago, IL 60618 Phone: 312-583-6565 TUBES—Receiving, Industrial and Semiconductors, factory boxed. Free price list. Low, low prices. TRANSLETERONIC INC. 1365-39th Street, Brooklyn, N.Y. 11218E 800-221-5802, 212-633-2800.

REPLACEMENT COLOR YOKES-DEAL-ERS ONLY. Zenith 95-2501-2532-2638-2667-S89633 etc. \$16.95. Magnavox 361380-1 \$18.95 etc. Sylvania, G.E. etc. \$14.95 to \$19.95. Request for price list on your letterhead. David Sims Enterprises, Inc., 665 Jerricho Turnpike, Huntington Statlon, N.Y. 11746

# GENUINE SONY SEMICONDUCTORS—CHECK THESE PRICES!!

EG. 1-9/ 10-24—SG613-8.50/7.30-SID 30-15 2.60/2.30, -2SC867A 5.10/4.90-2SC1114 5.50/4.80-2SC1358 6.50/5.70, -2SC1124 1.50/1.30-2SC634A 0.45/0.41. Contact us for complete list of Japanese semiconductors and pricing Information. Bescor, 547 S. Broadway, Hickville, NY 11801 (516) 822-3988

REPAIR TV TUNERS-High earnings, Complete Course Details, 12 Repair Tricks, Many Plans, Two lessons, all for \$2. Refundable. Frank Bocek, Box 3236, Ent., Redding, CA 96001.

Electronic Technician/Dealer 1966-1978, PF Reporter/Electronic Servicing 1965-1978. \$35. each or best offer, plus freight. Moraga TV, 1480 Moraga Rd., Morago, CA 94556.

### MATV—CATV INSTALLERS

Get lowest prices on antenna accessories, fastest service from ANTSCO CORPORA-TION. Call collect, ask for catalog & prices. All orders shipped same day. Sierra Madre, CA 91024. 213-355-2510.

LINEAR AMPLIFIER, 2-30 MHz, 150 watt solid state. FREQUENCY COUNTER, 300 MHz, 7 digit portable/mobile. OMNIPOLARIZED BASE ANTENNAS. Modulation boosting VOX-COMPRESSOR. Construction plans \$3.00 each \$10.00/all. Others! Catalog with order. PANAXIS Productions, Box 130-ET10, Paradise, CA 95969.

TV AND RADIO TUBES .36¢ EA!! Send for free color parts catalog. Your order free if not shipped in 24 hours. Cornell Electronics 4215-17 University San Diego California 92105.

Complete color, b/w picture tubes rebuilding equipment. Never used. Phone (212) 387-2744, Brooklyn, NY 11211. #FLOE3085063-02.

# **BUSINESS OPPORTUNITIES**

Sales & service for RCA plus authorized service for Zenith, Quasar, Nu-Tone Products, closed circuit and master antenna service. \$35,000 total price includes \$12,000 inventory. Good terms. Over \$30,000 net to owner. Contact Dean Vincent, Inc., 1445 Willamette St., Eugene, Or. 97401.

Vermont Radio-TV Sales & Service. Long established, owner retiring. Business \$175,000, w/R.E. \$275,000. Details to qualifed principle(s). Marble City Realty, Box 265, Rutland, Vermont 05701.

T.V. Sales & Service Business, in Florida. Zenith & RCA Franchise. \$15,000 cash. Write to: Mr. Jose A. Paredes, 2427 5th Ave. North, Saint Petersburg, FL 33713.

BROADCAST STATION. Start your own, any type! Unique Cable FM station requires no investment/experience. Receive free tapes, records. Learn how. Free details. "Broadcasting," Box 130-ET10, Paradise, CA 95969.

TV TECHNICIANS AND DEALERS, "INCREASE YOUR INCOME" thousands of dollars yearly! "Rent-Lease-Sell TV's." Easy to start or add to your present operation. 'Guaranteed complete basic plan and starter kit," \$15.00, or stamped envelope will get you free details. Perry's TV Leasing Systems, Box 1407, Santa Maria, Calif. 93456.

Television, stereo dealers—Increase gross income \$50,000 without increasing overhead. No additional investment or personnel required. Free details, Carank EM Box 7696, Naples, FL 33941.

"Rent Lease TV's anyone can!" Easy to start and operate. Even from your home. Send \$2.00 for basic information. Perry's TV, P. O. Box 1407. Santa Maria, CA 93454. 1/79

TV Sales and service, shopping center, suburb near San Francisco Bay, seven years. Completely equipped including late Dodge van. Excellent growth potential. Owner retiring. \$18,000 buys lease and all. Principals only, no shoppers please. Mornings (415) 376-3796.

For Sale. RCA TV & Appliance, Sales & Service. Nest North Dakota. Established 10 yrs. Over 115k gross average last 3 yrs. Other interest forces sale. Expanding town in energy area. Excellent Opportunity. Would consider partner as future buyer. Write R. Roach, P.O. Box 783, Watford City, N.D. 58854. 12/78

MECHANICALLY INCLINED INDIVIDU-ALS—BUILD ELECTRONIC DEVICES IN YOUR HOME. GET STARTED IN YOUR SPARE TIME. \$300 TO \$600/WK POSSI-BLE. EXPERIENCE NOT NECESSARY. WRITE FOR FREE LITERATURE. ELEC-TRONIC DEVELOPMENT LAB., BOX 1535 (B), PINELLAS PARK, FLA., 33565.

TV Business Located in Hompton, Va. \$18,000 including Trucks & Inventory. Established 5 years. Great Potential. Call Alexonder Realty, 34 West Queens Way, Hompton, Va. 23669. (804) 723-1303.

MOVING TO FLORIDA? TV SERVICE AND RENTAL BUSINESS FOR SALE ON FLORIDA'S WEST COAST. DOING \$40,000 - \$50,000 PER YEAR. ALL REASONABLE OFFERS CONSIDERED, ALSO BUILDING AVAILABLE. CONTACT: MR. SOTHERN, 1-813-535-2026 AFTER 7 PM OR WRITE: 1834 SUNRISE BLVD., CLEARWATER, FLORIDA 33520

### **HELP WANTED**

ELECTRONICS/AVIONICS EMPLOYMENT OPPORTUNITIES. Report on jobs now open. Details FREE. Aviation Employment Information Service, Box 240Y, Northport, New York 11768.

Earnings over \$20,000 a year to top outside Technicians. Qualifications: 15 years experience, absolute honesty, non-drinker, non-smoker. Benefits: group hospital plan, paid vacations, reimbursement for moving, excellent area to raise families, outdoor sports paradise. Send resume to American Television, 1032 South State, Orem, Utah 84057.

### WANTED

WANTED: PICTURE TUBE REBUILDING MACHINE, working or not. Call or write: Atoll Television, 6425 Irving Park, Chicago, IL 60634. Phone 312-545-6667. Hours 1-8 PM.

Wanted: Modulation or deviation meter for 100 watt 45 MHZ FM transmitter. New or used. John Collins, 3015 Chambers Circle, Colorado Springs, CO 80904.

# Where there is HOPE... there is life.

Give to



Department A, Washington, D.C. 20007

# AR Semiconductors Exact ECG Replacements

ECG NO.	DEALER COST	SUGG. RESALE PRICE	ECG NO.	DEALER COST	SUGG. RESALE PRICE	ECG NO.	DEALER COST	SUGG. RESALE PRICE
100 101 102 102A 103A 104 104MP 105 106 107 108 109 110MP 112 113 114 116 117 118 120 121 121 121 121 121 123 123 124 125 126 127 128 129 130 130MP 131 131 141 155 166 157 158 158 158 158 158 158 158 158 158 158	.85 .90 .87 .92 .99 1.09 .97 1.94 2.45 .55 .24 .35 .35 .35 .35 .35 .35 .37 .38 .35 .37 .38 .35 .37 .38 .39 .39 .39 .39 .39 .39 .39 .39 .39 .39	1.60 1.76 1.58 1.88 1.84 1.90 1.60 3.20 4.22 95 1.35 1.53 3.3 54 87 60 60 66 60 60 2.95 3.18 54 87 7.60 7.50 1.32 2.30 7.75 1.35 1.32 2.30 7.50 1.32 2.30 1.32 2.30 1.32 2.30 1.32 2.30 1.32 3.33 3.33 3.30 3.30 7.50 1.32 3.33 3.30 7.50 1.32 3.33 3.30 3.30 7.50 1.32 3.30 3.30 3.30 3.30 3.30 3.30 3.30 3	161 162 163A 164 165 166 167 168 169 170 171 172A 173B 175 176 177 180 181 182 183 184 185 186A 187A 189 190 191 192 193 194 195 196 197 199 210 221 222 222 222	.95 4.40 5.95 4.50 7.25 .95 1.126 1.26 1.27 1.25 .50 P 1.25 2.21 5.54 5.01 4.98 4.15 2.90 3.25 1.10 1.30 1.30 1.30 1.70 2.10 1.100 1.05 1.55	1.60 8.40 10.75 8.40 13.50 1.68 2.05 3.05 4.95 2.25 3.05 4.95 2.15 .90 .90 .95 8.88 8.84 4.40 5.00 .90 2.29 2.25 3.94 .90 .90 2.29 2.20 3.90 1.90 2.29 2.20 3.80 3.80 3.80 3.80 3.80 3.80 3.80 3.8	225 226 228 229 230 231 232 233 234 235 236 237 238 239 241 242 243 244 245 244 245 244 245 246 247 251 253 254 262 263 274 283 284 283 284 283 284 283 284 283 284 283 284 285 286 287 288 289 291 292 293 294 295 296 297 297 298 298 299 299 299 299 299 299 299 299	4.29 1.75 1.15 90 3.400 .59 6.25 4.605 1.55 1.85 1.85 1.85 1.85 5.95 1.60 3.10 5.95 1.60 1.60 1.65 1.60 1.65 1.60 1.65 1.60 1.65 1.60 1.60 1.60 1.60 1.60 1.60 1.60 1.60	5.67 2.92 1.31 1.53 5.11 5.85 .98 10.40 8.10 6.30 10.40 8.17 3.63 2.25 2.69 2.52 2.69 4.40 4.77 4.77 6.42 8.50 6.30 1.90 6.30 1.90 6.30 1.90 6.30 1.90 6.30 1.90 6.30 1.90 6.30 1.90 6.30 1.90 6.30 1.90 6.30 1.90 6.30 1.90 6.30 1.90 6.30 1.90 6.30 1.90 6.30 6.30 6.30 6.30 6.30 6.30 6.30 6.3

2 Year Unconditional Warranty • Same Day Shipping • No Minimum Order • Prepaid or C.O.D. Accepted \*Orders over \$25.00 shipped free, under \$25.00, add \$1.00 UPS

AR Semiconductors, P.O. Box 976, Union, N.J. 07083

send a message...

...write here.

3 6 12 (Copy must be in by 1st of month preceding)
LL BILL RATED FIRMS
COMPANY
STATEZIP
l

MAIL AD COPY TO: DAWN ANDERSON, ELECTRONIC TECHNICIAN/DEALER, 1 EAST FIRST STREET, DULUTH, MN. 55802.

RATES: 40 cents per word(minimum charge, \$10). Bold face words or words in all capital letters charged at 50 cents per word. Boxed or display ads charged at \$50 per column inch (one inch minimum). For ads using blind box number, add \$5 to total cost of ad.

## READER SERVICE INDEX 115 JFD Electronics Corp. .....27 ADVERTISER'S INDEX 127 B & K Division Dynascan Corp. ......33 118 Modular Electronics Services Ltd. ...............26 121 Cornell Electronics ......18 119 National Camera (NCTTD) ......41 131 Creative Electronics ......41 120 New-Tone Electronics ......8 106 Devco .....4 107 Electronics Book Club ......43 108 Elenco Electronics .......41 124 Sentry Manufacturing Co. ......38 125 Texas Tuner Service ......8 142 Fordham Radio Supply Co., Inc. ......45 126 Texas Tuner Service ......18 104 Triplett Corp. (for info) ......Cov. 4 112 GTE Sylvania EGC Consumer Renewal ......19 105 Triplett Corp. (for demo) ......Cov. 4 113 GTE Sylvania EGC Consumer Renewal ......35



General Electric, TV Business Div. ......39

General Electric, Tube Div. ......5

General Electric, Tube Div. .....23

# George V. Eltgroth is a Patent Attorney for General Electric. He is legally blind.

103 Zenith Radio Corp. ......Cov. 3



Circle No. 123 on Reader Inquiry Card

There's no waiting or turn-around time when you bring Zenith modules, tuners or sub-assemblies needing repair to your Zenith distributor.

That's bench strength for you—as deep, dependable, and easy to draw on as any you'll ever know.

Not only will the faulty component be replaced, but the replacement module will have been up-dated to incorporate the latest factory technical improvements.

And it's an over-the-counter exchange. You walk out with a Zenith factory repaired and re-conditioned replacement serviced by the same people who made the original.

So it simply makes good sense to exchange your modules, tuners, and sub-assemblies with those from the original source.

That's with your Zenith distributor, of course, for modules, tuners and sub-assemblies...and a bench that never quits!

For your own reputation and in your customers' best interest, always specify Zenith exact replacement parts and accessories.



The quality goes in before the name goes on®

**There** are times he'd give anything to draw on a bench as consistently strong, deep, and versatile as Zenith's!

Notre Dame basketball coach, "DIGGER" PHELPS

Circle No. 103 on Reader Inquiry Card

# THE NEW COMMON TO SERVICE OF THE NEW COMMON TO SERVICE OF THE SERV

# Model 3400 has features that upstage other compact DVOMs.



Built to flt your hand and budget, the new Model 3400 (shown actual size) is loaded with features. Like a color coded single range switch for one-hand selection of all functions overload protection for all ranges and 200 hour minimum battery life . . . time-saving automatics including auto-zeroing, autopolarity, auto low-battery and auto-overrange indication . . . easy to read .5"LCD readout. Six functions and 24 ranges, typical DC accuracy .5% Rdg, including High and Low Power Ohms for sensitive IC testing, makes the Model 3400 ideal for Jesign, production and maintenance testing, vocational tech training schools, commercial electronic equipment test and measurement use.

- 1. HAND SIZE, 3½ digit, single range switch —6 function, 24 ranges with Hi and Low Power Ohms, Auto-zero and Auto-polarity.
- 2. OVERLOAD PROTECTION—Protected up to 500 volts on all ranges with special 2 fuse arrangement.
- 3. BATTERY LIFE—200 hour minimum with 9V battery, display includes low battery incication.

ONLY \$140

Includes test leads, new screw-on insulated alligator clips for the prope, 9V alkaline battery, plus instruction book and 1 year warranty.

For a demonstration, cortact your Triplett distributor, Mod Center or representative. Triplett Corporation, Bluffton, Ohio 45817 (419) 358-5015, TWX (810) 490-2400.

Triplett performance... a tough act to follow

...Circle No. 104 for information ...Circle No. 105 for demonstration ...CIRCLE No. 105 for demonstration