

ii.

July, 1956



July, 1956

PROSPECTUS

cial Art, etc.

NEW LEARN THE PRACTICAL WAY. COURSES WITH EQUIPMENT

With many of our courses we supply actual

equipment thus combining theory and practice in the correct educational sequence. Courses include: Radio, Television, Electronics, Draughtsmanship,

Carpentry, Photography, and Commer

Ĩ.

PRACTICAL TELEVISION



POST THE COUPON TODAY FOR OUR BROCHURE ON THE LATEST METHODS OF HOME TRAINING FOR OVER 150 CAREERS & HOBBIES

529.

PRIVATE AND INDIVIDUAL TUITION IN YOUR OWN HOME City and Guilds Grouped Certificates In Telecommunications: A.M.Brlt.I.R.E. Examination, Radio Amateur's Licence, Radio and Television Servicing Certificates, General Radio and Television Courses, Radar, Sound Recording, etc. Also Courses In all other branches of Engineering and Commerce.

The advantages of E.M.I. training. \bigstar The teaching methods are planned to meet modern industrial requirements. \bigstar We offer training in all subjects which provide lucrative jobs or interesting hobbies. \bigstar A tutor is personally allotted by name to ensure private and individual tuition. \bigstar Free advice covering all aspects of training is given to students before and after enrolling with us.

s we supply actual ning theory and ect educational ide: Radio, Tele- Draughtsmanship, 7, and Commer-	Equipment supplied upon enrolment and remains your property. Courses from 15/- per month	
Theonly Postal	TRUTES College which is part of idustrial Organisation.	ADDRESS 7.53 SUBJECT(S)·OF INTEREST
-, / -		IC.38E

July, 1956

For maximum reliability **LECTROPACK** ETCHED FOIL ELECTROLYTICS

The Constructor depends upon the reliability of the components he uses. The fact that so many designers specify T.C.C. Condensers is evidence of their supremacy.

T.C.C. "Lectropack" Dry Electrolytic Condensers are robust yet compact and employ ALL-ALUMINIUM non-corrosive internal construction. The range below is a useful guide to the types available.

1	Capacity µF.	D.C.	Volts	Ripple Current	Dimensions in inches T.C.C.		T.C.C. Type No.	List Price	
	per .	Wkg.	Surge	Max, M/A	L	D	Type No.	Trice	
	60 - 100	275	325	450	41	13	CE 37 HE	16/-	
	60 - 250	,,	,,	530	41	14	CE 60 HE	28/-	8
	100 - 200	,,	.,	650	4늘	2	CE 60 HEA	28/-	
	100	350	400	450	2콫	<u>हे</u>	CE IO LE	13/6	
1	200	,,	,,	770	4월 2월 4월 4월	12	CE 36 LE	24/-	
	60 - 100	.,	,,	500	41	11	CE 36 LEB	23/-	L
	60 - 250	,,	,,	500	41/2	1ĝ	CE 60 LEB	34/-	L
	100 - 100	,,	.,	550	412	12	CE 36 LEA	26/	Ł
	100 - 200	,, ,	,,	700	1 4 ½	12	CE 60 LEA	33/-	
	60	450	550	450	412 412 314	1 출	CE 38 PE	14/-	
	60 - 100			500	41	1 -	CE 60 PE	29/-	

THE TELEGRAPH CONDENSER CO. LTD RADIO DIVISION : NORTH ACTON · LONDON · W 3 · Telephone : ACOrn 0061



This instrument has been developed to meet the growing demand for an for use in conjunction with electronic and other apparatus where it is imperative that the instrument should present a negligible loading factor upon the circuit under test.

The instrument consists basically of a balanced bridge voltmeter. It incorporates many unique features and a wide set of ranges so that in operation it is as simple to use as a normal multi-range testmeter.

The instrument gives 56 ranges of readings as follows :---

- D.C. VOLTS: 5mV. to 250V. (input
- Resistance 11.0 megohms.) 25mV. to 10,000V. (Input Resistance 110.0 megohms.) D.C. CURRENT: 0.5μA. to 1 Amp.
- (250mV. drop on all ranges.) A.C. VOLTS: 0.1V. to 2,500V. R.M.S. up to 2 Mc,s. With diode probe external 0.1V. to 250V. R.M.S. Useful measurements can be made up to 200 Mc/c the applied voltage up to 200 Mc/s, the applied voltage being limited to 100V. above 50
- A.C. OUTPUT POWER: 5mW to 5 watts in 6 different load resistances from 5 to 5.000 ohms,
- DECIBELS : -10db, to +20db,

CAPACITANCE: .0001 µF. to 50 µF.

- RESISTANCE : 0.2 ohm to 10 megohms.
- INSULATION : 0.1 megohm to 1,000 megohms.



11 MERIUM

List 140c contains the extended range.

> × 9ins. Size 121ins. \times 5 lins. £40 Weight : 121lbs.

The instrument operates on A.C. mains, 100-130V and 200-250V., 50-60c/s Write for fully descriptive pamphlet.

The instrument is quickly set up for any of the various tests to be undertaken, a single range selector switch automatically removing from the circuit any voltages and controls which are not required for the test in question.

Sole Proprietors and Manufacturers :

Mc/s.

THE AUTOMATIC COIL WINDER & ELECTRICAL EQUIPMENT CO. Ltd. = 'Phone : VICtoria 3404-9 Avocet House, 92-96, Vauxhall Bridge Road; London, S.W.1 E.T.M.3 16



Editor: F. J. CAMM Editorial and Advertisement Offices : "Practical Television," George Newnes, Ltd., Tower House,

Southampton Street, Strand, W.C.2. 'Phone : Temple Bar 4363. Telegrams : Newnes, Rand, London. Registered at the G.P.O. for transmission by Canadian Megazine Post.

Vol. 6 No. 72

EVERY MONTH

JULY, 1956

Televiews

FAREWELL TO ALLY PALLY

T was in 1936 that the BBC inaugurated the first public television service from their transmitting station at Alexandra Palace. affectionately known to millions of viewers as "Ally Pally." This soubriquet, a sure sign of popularity, has endured through the years, and it is with melancholy regret that viewers said good-bye to it on March 28th when the BBC's new London television station at Crystal Palace took over. The original Marconi-E.M.I. transmitters which have radiated the programmes almost faultlessly for 20 years are now silenced, being superseded by two sets of new Marconi vision and sound transmitters of greatly increased power and incorporating the most advanced The vision transmitters, each of techniques. 15 kW. output, operate in parallel, as also do the 41 kW, sound transmitters. This ensures continuity of service, for in the event of breakdown in any one transmitter its twin carries This means that the programme service on: continues at half-power until full working is restored. The vision transmitters have been so designed as to be fully capable of handling colour transmissions when they come. The effective radiated power of the Crystal Palace station is 60 kW., later to be raised to 120 kW., and finally to 200 kW.

Ally Pally paved the way for television as we know it to-day, and it was there that most of our leading technicians in television received their training.


TRAINING THE BBC STAFF

IN referring to the BBC technicians we are reminded that nearly 4,000 men and women have passed through the BBC Engineering Training Departments' School, which has just celebrated the 10th anniversary of its foundation. It is in Wood Norton Hall, formerly the home of the Duke of Orleans in the Vale of Evesham. Over 200 students can now reside there, and the number trained in the current year is expected to rise to well over 800. Training covers sound and television, and long-term plans for the introduction of colour television are envisaged by the introduction of a new course this year —a one-week colour television course for the senior staff.

At a recent Press conference the Chief Engineer emphasised that no date could yet be foreseen for the introduction of colour television. and the purpose of the present course is to give the senior executives an awareness of colour television problems well in advance. Fach year 40 or 50 students who are still at universities take an eight weeks' vacation course at Wood Norton, and there is a five-week course for staff in sound broadcasting to enable them to qualify for transfer to television. It must be pointed out, however, that only a small proportion of those who undergo courses at Wood Norton are university graduates, and one of the problems has been the imparting of highly technical knowledge to those who are without advanced mathematical training. Those who have such knowledge, therefore, have much greater chance of promotion.

PRINCIPLES FOR TELEVISION ADVER-TISING

THE I.T.A. has recently published "Principles in Television Advertising," containing the recommendations of the Advertising Advisory Committee. It is concerned with the legal requirements, the prevention of misleading advertisements, disparaging references, testimonials, guarantees, competitions and advertising in children's programmes. It is laid down as a general principle which will govern all television advertising that it should be legal, clean, honest and truthful, although how advertising can be honest without being truthful is not stated ! It is laid down that no advertisement shall contain any statement intended to promote sales by unfair comparison with or reference to cormetitive products or services.—F, J, C,



THE TV service engineer has to use a number of accurate and reliable testing instruments to enable him to do his job; a signal generator, first-class multi-meter and an oscilloscope are the tools of his trade and enable him to diagnose rule-ofthumb faults quickly, and also to deal with those rather elusive troubles which necessitate the employment of such equipment.

These instruments are expensive and are not normally possessed by the home constructor, yet quite a lot of work can be done without their aid and although the final tracking down of a fault may take much longer, it is possible, by employment of the correct technique, to trace many of the commoner faults with nothing more than a pair of earphones or failing that, the pick-up sockets of a broadcast receiver.

In some ways, the home constructor has a more difficult problem to face than the service engineer; the latter at least knows that the television receiver he is servicing has worked satisfactorily and that the derangement is therefore due to a fault developing in a component, whereas the home constructor is faced, when first switching on, with completely unknown quantities, and a fault may be due to a slight mistake in the wiring or mistaken value of a resistor or condenser.

Visual Faults

Television receivers, in spite of their complexity, have some advantages over broadcast receivers as it is often possible to localise immediately to a particular section a fault which reveals itself on the screen.

The skilled service engineer uses the screen in this fashion and certain weaknesses in specified classes of televisors become obvious from the results shown on the screen.

The raster itself reveals much to the skilled man and can provide a very good indication of the direction in which the trouble lies.

A normal raster should appear as a large number of horizontal lines in the form of an oblong which often carries superimposed on it a thicker line which zig-zags from the top to the bottom of the screen. This thicker line is the frame flyback and is generally found to be "cramped" towards the top of the screen.

The line should not appear when a picture is being received as the frame synchronising pulse blacks it out. In some commercial televisors where frame flyback suppression is employed the flyback is not evident.

When it is realised that the line oscillator and associated circuits produce the horizontal line and the frame oscillator the vertical scan we have, at once, an obvious clue to a failure of either section of the timebase.

Where flyback EHT is employed with magnetic circuits then a little more is involved but we will come to that later.

Should a vertical line only be seen on the screen then the indication is that the frame circuit is functioning but the line circuit is not : similarly, if a horizontal line only is seen on the screen then the line circuit is functioning and the frame circuit is not.

We have an immediate indication of the direction in which the fault lies.

If the raster is too narrow then the line circuit, although functioning in some fashion, is not giving its full output: similarly a raster which is far too short indicates that although the frame circuit is functioning it is not giving full output.

A raster which has its sides tending to close in towards the top of the screen has trapezium distortion in the horizontal scan; the fault, therefore, lies in the line circuits. Similar distortion on the left or right of the picture is due to a fault in the frame circuit.

Where the raster has a wavy edge then hum is reaching the line circuit or the deflection system directly, and where the raster has a dark bar across it then hum is reaching the modulation portion of the tube network.

It is clear that a careful examination of the screen will reveal much to the discerning constructor and will give him a definite indication of the direction of the trouble.

Of course, there are exceptions to the rules and this is one of the things which makes servicing so interesting, but they are exceptions; the method is to trace the obvious first and then, if this fails, to look for the not so obvious.

Where multi-purpose circuits are used then the boundary between sections is not so clearly defined. Where flyback EHT is employed; for example, a blank raster may indicate an actual failure in the EHT system or a fault in the line oscillator circuit.

Classification of Faults

TV receiver faults can be roughly classified under certain specific headings.

First we have power supply faults and the only reliable method of checking these is with a good class voltmeter.

Second we have EHT faults where the EHT is weak or absent altogether.

Third we have line oscillator and/or amplifier faults.

Fourth there are frame oscillator and/or amplifier faults.

Fifth we come to faults in the sync separator stages which can often prove very elusive.

Sixth there are faults in the vision receiver itself and, seventh, there are faults in the sound section.

Power Supply Faults

Faults in the power supplies are difficult to diagnose without the aid of instruments. The continuity of heater supplies can be fairly easily verified in the case of parallel heaters by use of a six-volt flashlamp bulb.

All that is necessary is to apply the bulb across the heater pins of each valveholder. Where valves are wired in parallel it is surprisingly easy to miss one valve in the chain, which will thereby give fault conditions according to the part of the circuit involved.

A bulb can be used also to check the supply to the C.R.T, heater.

The heaters of the valves themselves can be checked by the simple tester shown in Fig. 1. This is a bulb and battery connected in series with a pair of test leads. If the test leads are connected across the heater pins of the valve, the bulb will light up if the heater is sound. Note that the valve must be taken from the televisor; it is useless to apply the tester across the valveholder as a continuous circuit is made, irrespective of the valve under test, by the heaters of the other valves in the receiver.

Do not be misled by testing the valve across the valveholder pins when all other valves are removed, as the heater winding of the mains transformer will cause the bulb to light. The only sure method is to take the valve out and to test it outside the televisor.

If there is any doubt about connection of the valve pins and valve sockets, then the test can be made with the valve in its socket, provided all wiring is removed from the heater tags of the valveholder.

The simple continuity tester can be used to test the continuity of all low-resistance circuits where the resistance does not exceed a few ohms.

A heater supply fault which the tester will not reveal is a dead-short-circuit. It is possible for there to be a short-circuit in some part of the heater chain, yet the heaters of the valves will still light up to a certain extent. The only clue to this fault is that a section of the heater wiring will show obvious signs of overheating, or the transformer will start to smoke. It can be verified if the latter is due to a heater short or H.T. short simply by disconnecting the H.T.

Checking the H.T. supply is rather more difficult, and the only reliable method is by use of a voltmeter. A very rough indication that H.T. is present can be obtained by short-circuiting the point to chassis *momentarily* and observing if a spark is produced. The short must be a very rapid flick on and off or damage will be done.

EHT Supply

The service engineer is usually equipped with an electrostatic voltmeter for checking EHT supplies. An ordinary type of voltmeter is of little use because the current taken by the meter is so far in excess of the supply that the voltage drops enormously and an entirely false reading is obtained.

A further point is the possibility of damage to the meter due to arcing of the high voltage.

EHT supplies should be treated with the respect due to them, especially those which are obtained from a mains transformer, and the greatest care should be exercised. It is most unwise to probe around the EHT section when the supply is on.

When the constructor is faced with an entirely

blank screen, then the first thought is that the EHT supply has failed. A simple test can be made to verify this if due precautions are taken.

The first step is to test on the tube anode to verify if EHT is at that point. This can be done with the blade of a well-insulated screwdriver. If the blade is tapped on to the EHT terminal it should be possible to draw off a spark from the terminal. The length of the spark will vary according to the value of the EHT. Normally with, say, a VCR97 circuit it should be possible to draw off a $\frac{1}{2}$ in. spark, while some magnetic circuits will give a spark almost $\frac{1}{2}$ in. long.

If a spark can be drawn off then EHT is present.

A typical EHT supply for an electrostatic tube is shown in Fig. 2. (This is the EHT circuit of the PRACTICAL TELEVISION Simplex Televisor which has proved so popular with the home constructor.) The points at which the EHT can be tested are indicated by the letters A, B, C, etc. It should be possible to check the EHT from its

It should be possible to check the EHT from its source at the rectifier output at "A," through the smoothing resistor Ra to "B" to the "X" shift at "C" and the X2 plate on terminal 11 at "H." Naturally, the spark will be weaker as it passes through the various resistances.

The "Y" shift can be tested at "D" and at "J" on terminal 12 and the EHT bias on terminals 9 and 8 at "K" and "L."

Final anode supplies are checked at "E" and terminals 5, 7 and 10. It should also be possible to trace a weaker spark through "F" and "G," and possibly at "M." Little, if any, spark will be found at the brilliance control, but as this is getting rather beyond the final anode supply it will not often be necessary to check at this particular point. A brief short-circuit tapped to chassis would supply some indication here.




Fig. 2.—Testing points on electrostatic EHT.

Flyback EHT

The testing for EHT obtained from the line flyback is usually very simple. A typical circuit is given in Fig. 3, which shows the EHT circuit of the PRACTICAL TELEVISION Supervisor.




Fig: 3.-Testing points on electromagnetic EHT.

With magnetic tubes no elaborate network of EHT is required for biasing the deflector plates or for focusing, and the testing is therefore very straightforward.

The first check is with the screwdriver on the final anode of the tube. The EHT can then be checked back through to the rectifier valve V19, and it should also be possible to obtain a spark from the anode at "A."

Provided the line oscillator is working at about the correct frequency, then the only major points where EHT fails is in the loss of emission of the rectifier valve (or ageing of a metal rectifier where such is used), or an actual breakdown in the transformer itself, or breakdown to the chassis.

One point to note is that a blank screen does not necessarily mean that EHT is missing or the tube heater supply is faulty, as overbiasing of the tube can cause the same effect. If, therefore, the EHT is present suspect the components in the brilliance network.

Corona Discharge

The EHT can be severely diminished or even totally stopped by discharging to chassis or an earthed point. Usually the discharge can be heard as a "sizzling" sound, and is generally accompanied by a distinct smell of ozone. It is often difficult to locate and if a normal inspection does not reveal its source then two other methods can be employed.

The first method is to examine the chassis in complete darkness. Care must be taken in handling the chassis but it is quite often fairly easy to locate the point as it is seen as a stream of bluish sparks.

The second method is by use of an improvised stethoscope. Simply roll a magazine or piece of stiff paper into a tube and then, by applying one end to the ear the other end can be moved about the chassis until the loudest spot is found where the discharge is taking place. Again care must be taken and the tube should be at least lft. long. It is a nasty experience for the ear to touch, accidentally, an EHT spot!

Line Faults

The obvious line fault trouble is where the line oscillator is not functioning. Where a separate EHT supply is employed then a vertical line only will be seen on the screen. Where EHT is obtained from the line flyback then nothing will be seen on the screen as EHT will be missing if the line oscillator fails.

One of the first checks to make if the line circuit is suspected is to rotate the line hold control (sometimes labelled "horizontal hold "), and to listen for the whistle from the line oscillator.

In magnetic circuits the whistle can emanate, from the blocking transformer, if employed, from the output transformer or from the valve direct. In electrostatic circuits the whistle can be heard from the oscillator valve itself.

It is essential to rotate the hold control throughout its travel as in certain positions the whistle may be of such a high pitch as to be beyond the range of hearing. The actual point at which this occurs will vary according to the person, as sometimes one person can hear much higher sounds than another.

If the line oscillator does not appear to be working then a simple tester can be made for checking purposes, as shown in Fig. 4.

The tester is simply a pair of earphones connected in series with a condenser of 0.01μ F value. The condenser must be of good quality and known to be free from leakage.

If no earphones are possessed then a loudspeaker can be used, though this is not so effective. Failing a spare loudspeaker then the pick-up sockets of a broadcast receiver can be employed, or even the A.F. section of the televisor itself. In these last two cases use a condenser in each lead.

Application of the tester to a circuit is quite a straightforward business.

In Fig. 5 will be found a typical line oscillator and amplifier and the method of checking such a circuit will be explained in detail. The circuit shown is actually that of the PRACTICAL TELEVISION Simplex.

One of the leads from the tester should be placed on a chassis connection, preferably the lead without the condenser in it. If the other lead is placed on the anode, point "A," then rotation of the line hold control should reveal a whistle. The sync valve should be removed or aerial disconnected so that no confusion arises about the sync pulse.

If the whistle is not received then the valve circuit is not functioning.

If the whistle is received it can be traced through to the deflector plates. Put the test lead on point "B" and verify that the amplitude control Va is functioning, the strength of the sound becoming less as the slider is moved towards H.T. Check between point "C" and chassis, which

Check between point "C" and chassis, which will prove that the oscillation is reaching the amplifier valve.

A test on point "D" should reveal a much stronger signal showing that this section of the valve is amplifying correctly.

Check now on point "E," leaving the slider of the linearity control at about midway. Test next on point "E," which will show the signal is reaching the second grid of the valve. It should be approximately the same strength as at "C." Finally, check at point "G," and here an amplified

Finally, check at point "G," and here an amplified signal of about the same strength as at "D" should be heard.

If the EHT circuit is disconnected tests can be made on each side of the condensers Ca and Cb, and then directly on the pins of the tube.

Paraphase Circuits

Many VCR97 circuits employ paraphase circuits, and a typical example is given in Fig. 6, which shows the line circuit of the PRACTICAL TELEVISION Argus.

The method of checking with the tester is similar to that given in Fig. 5.

A check is first made at point "A," and if all is in order then remove the second valve and test at points "B" and "C." This signal should be heard,




Fig. 5.-Typical line circuit for electrostatic tube.

though rather weaker than at point "A." Now insert the valve and test at point "D." If all is well the signal should be heard here at about equal strength to point "A."

As an example of the utility of this test we could have a case where the raster is rather narrow, due to a failure in Vb circuit. This test will instantly show if Vb is functioning or is giving a weakened output.

Magnetic Circuits

Magnetic line circuits take many forms and it is not possible to cover all of them. The basic principles for testing are similar and so we will describe two most popular circuits in general use.

The first circuit is one which employs a blocking oscillator followed by an amplifying stage. Such a circuit is shown in Fig. 7 and is actually the line circuit of the PRACTICAL TELEVISION Receiver (originally the *Practical Wireless* Televisor).

Va is the blocking oscillator and Vb is the amplifying stage. The first check can be made at point "A" which will confirm if the oscillator is functioning as such. The line hold control should be rotated until the whistle is heard.

The next check is made at point "B" followed by point "C" to verify that the signal is getting through

to the amplifier. Next make a check at point "D" to verify that the signal is going through Vb. If a high voltage condenser is available it should be connected in series with the testing lead and a test made on point "E" then point "F" and finally across the scan coil at point "G."

The second type of circuit is that of the single valve where the one valve performs the functions of a *current* oscillator and supplies the coils via a transformer.

No check should be made on the anode of this valve unless a high-voltage condenser is available. Checks can be made across the scan coils themselves to verify that the signal is actually being passed to this point.

Frame Circuits

The different types of frame circuits can be tested in a similar manner though in this case, instead of a





Fig. 6.—Typical paraphase circuit.


high pitched whistle being heard the tone is very much lower and more like a burring sound.

As with the line circuit it should be possible to vary the pitch of the sound by operation of the hold control.

(To be continued)







TRANSMITTING SYSTEMS-PROJECTION RECEIVERS-AERIALS

Interlacing

AST month I dealt with the avoidance of flicker, pointing out that a repetition frequency of at least 48 frames per second is necessary. I also pointed out that at least 50 frames a second are desirable on 50 cycle power systems, and that such a high frame frequency required a wide frequency band during transmission, and because of this it was undesirable.

This is the reason why interlaced scanning is employed, because it overcomes the difficulty of the high frequency band necessary with 50 frames a second. Indeed, interlacing retains the advantages of it. In interlaced scanning, the picture is scanned 50 times per second, but only alternate lines are traced per scanning period. In the 405 line system at present employed, the odd-numbered lines are scanned first, and then the even-numbered lines (see Fig. 11, June issue), the even lines being placed as it were in the gaps between the odd lines.

Now it must be obvious that each $202\frac{1}{2}$ piece of the picture is transmitted in 1/50th of a second building up a complete picture every 25th of a second. It is difficult to understand why such an odd figure as 405 was chosen, but no doubt it provides the best compromise, and reduces the transmitting problems when a higher number of lines is used. Continental systems and American systems use 525 lines.

Frequency Bands


Television picture signals are radiated in much the same way as for sound broadcasts, by modulating the carrier wave with the video frequency, but with this important difference between picture and sound transmission. In order to transmit a picture with a great amount of detail, a much wider band of frequencies is required than is necessary for the transmission of sound. A trouble in this connection is chiefly experienced with contrasting pictures having areas changing suddenly from black to white. For example, let us presume that a draughts of the scanning line corresponds to the VERS-AERIALS By F. J. Camminum height of the contrasting tones of the board; the defects will be at a minimum, but as the change from black to white increases in depth the defect will be more apparent. In scanning scenes involving very rapid motion minute changes will occur in the picture between the period of the half-frames, resulting in a slight wavy or zigzag appearance of the vertical lines.

By making the frequency band approximately équal to two-thirds of the full frequency band, detail in both directions is balanced up.

Receiving and Transmitting Systems

In a complete receiving and transmitting system, first the image is scanned by the television camera, producing a series of varying currents which are the counterparts of the changes in light intensity along the scanning line. These varying currents are fed to a video frequency amplifier, the output from which is passed to what is known as a limiter, which is really a pulse generating system. The purpose of this limiter, as its name implies, is to prevent overloading at later stages. The triggering impulses operating in conjunction with the timebase are provided by the pulse generator which also superimposes the synchronising pulses on the signal currents.

Further amplification takes place after the limiter



board is being televised. If the width—Fig. 15.—Block diagram of a modern television receiver showing the of the scanning line corresponds to the

stage and the currents are then used to modulate the carrier wave generated by the oscillator. The modulated carrier is then passed on to the transmitting aerial by means of a radio frequency amplifier.

At the receiving end the aerial system picks up the signals from the transmitter and they are passed through a series of radio frequency stages, the output from which is mixed with that of a local oscillator giving rise to an intermediate frequency. This intermediate frequency is then amplified by a series of intermediate frequency stages.

Projection Receivers

Receivers employing large tubes are known as direct vision receivers. Another system, however, is in use —the projection system, which makes use of a much smaller cathode-ray tube. Its diameter is only 24in. The small picture received is magnified by optical methods to appear on a large flat screen. It has certain advantages over the direct vision receiver. It is well known that if a viewer stands far enough away from a television picture to render the line structure invisible, the angle it subtends at his eye is fixed and does not depend upon the size of the picture. If the viewer adjusts his distance until he just cannot see the lines he will find that the angle subtended is just the same whether a 12in., 15in., 17in. or even larger tube is employed.

The image thrown on the retina of his eyes is therefore of the same size, irrespective of the size of tube.

Therefore, the most obvious advantage of a large picture, as provided by projection receivers, is the improved angle of view which it permits. Another advantage which is not so obvious concerns the distance at which the eye muscles are at rest. A certain amount of effort is required to focus objects which are very close or very far away. In the region of 20ft, however, the eye muscles are much more relaxed. Another advantage can be considered as purely psychological. On the screen of a projection receiver a head and shoulders shot appears about life size and therefore it brings realism to the view. A " life-size" voice emanating from the mouth of a half or quarter size speaker is unreal.

The Aerial

The aerial, of course, is the device which picks up the sound and video waves and conveys them to the receiver. With television an aerial is required which greatly differs from that used for ordinary sound receivers. It is known as a dipole aerial, and it is used for ultra-short wave reception such as is used in television. It consists of two short lengths of metal rod or wire vertically disposed on the same axis, with a space separating them. The receiver is joined to the centre. The overall length of the aerial must be equivalent to one-half of the wavelength of the transmission. It is also known as a half-wave aerial. Television aerials take one of several forms, both outdoor and indoor.

We know that the waves radiated from the transmitter are similar to those formed by a stone when thrown into still water. The nearer the stone (the transmitter), the more pronounced the waves, which grow less and less discernible as the distance from




Fig. 16 .-. A home-built television receiver with the important parts identified.

their source increases. They can also be compared to rays of light in that they are reflected or reduced in strength by intervening objects to a greater extent than the much longer waves used for radio broadcasting.

For these reasons, the strength of the signal depends on the distance between the transmitter and receiver, the contours of the intervening country, the relative heights of the transmitting and receiving aerials, the construction of the building housing the receiver (steel-




Fig. 17.—A typical range of television aerials. (1) Indoor or loft model; (2) single dipole; (3) "H," and (4) "H" with two directors.

framed, plain brick, etc.), and the presence of large structures in the vicinity of or which overshadow the receiving site (large buildings, gasometers, etc.).

There are types of aerial available to meet most reception conditions. They fall roughly into two categories, directional and non-directional. Nondirectional aerials respond equally to signals coming from all directions, whilst directional aerials are most sensitive in one direction only. For this reason the latter are used when it is necessary to reduce interference received from directions other than that of the

desired television signals. In general, they provide greater signal strength than the non-directional. types, thus improving the relative proportion, of signal and interference; and even if the sources of interference are located on all sides of the receiver, directional aerials still reduce the interference from behind, whereas the nondirectional types, such as the single dipole, have no such properties. It is for this reason that it is sometimes necessary to use a directional outdoor aerial in a strong signal area near the transmitter. We have seen that the dipole consists of a rod cut to one-half the wavelength of the television transmission, with a connection taken from the centre. As, however, the sound and vision are transmitted on different wavelengths or frequencies, the aerial is cut to a point midway between the two in most cases, although some acrials are cut for vision only, as this is the most critical part of the received signal.

If you make your own aerial

you can experiment and find which is the most satisfactory length for your own particular local conditions. For the London transmission the length of the aerial should be about 11ft, and for the Sutton Coldfield about 7ft.9in. It is important to note that a few inches either way on these measurements may make quite a difference in reception, and best results therefore can only be obtained by careful experiments.

In strong signal areas it is possible to operate a number of receivers directly from one efficient agrial

installation. Where this is done it is important that certain technical considerations are observed in connection with the wiring, as otherwise reception may vary from one receiving point to another. It is also possible that the television receivers connected to the system may affect each other. By using an amplifier between the aerial and the receivers to increase the strength of the signal, a large number of receiving points may similarly be supplied by one actial. Such arrangements are usually referred to as "communal actial systems," and are ideally suited for blocks of flats or small individual dwellings situated in close proximity to one another.

The aerial for such systems can be installed in the optimum position, having regard to signal, interference and appearance.

A complete installation of this type can usually be installed at less cost per point than individual aerials. Many such installations have been carried out with most successful results.

As in the case of single installations, each building or group of buildings presents an individual problem, and it is necessary for tests to be carried out before a workable scheme can be put forward.




Fig. 18.—Photographs of some combined Band I and Band III aerials.



These are mounted on the rear of the chassis at the . right side, the vertical and horizontal shifts are mounted each side of a 1,000 by 1,000//F capacitor. The purpose of these controls is to regulate the amount of direct current passing through the scan coils. The effect of such a current is to shift the picture according to the current flowing, positive or negative. The receiver circuit is very straightforward, and reliable in operation.

THE receiver incorporates the well-known Plessey Mk. II chassis and because of this these notes may be used in the servicing of a large number of other models, including those in the Argosy, Columbia, Defiant, Marconi, Philco and Sobell ranges. Some variation may be found in various models and we certainly do not imply that the Plessey chassis will be found in all the models of the mentioned manufacturers ! The complete circuit diagram and the circuit description have already been printed in an earlier issue (June, 1954). The earlier Mk. I chassis has also been described and bears many of the characteristics of the one to be dealt with. A ready means of identifying the two is the

Timebases

The frame timebase employs an oscillator of the multivibrator type using a 6SN7 valve feeding a 6L18 frame output triode. This circuit is fairly trouble free except for a small resistor which regularly changes its value. The effect of this change is a decrease in the picture height as the resistor goes "high." It is the anode load resistor of one of the 6SN7 sections and is coloured brown, green, green (1.5M2). In all cases it should be replaced by a larger, $\frac{1}{2}$ watt, resistor of the same value. No difficulty should be experienced in locating the resistor—it is suspended in the wiring and connects directly to pin 5 of the 6SN7 valve base.




Fig. 2.—Circuit showing the C.R.T. wiring.

Poor frame linearity may be due to incorrect mains voltage adjustment, failing 6L18 valve or an alteration in value of the $2.2M\Omega$ grid leak. It is a characteristic of this circuit that a raster cannot be displayed without a vision signal to supply the sync pulses to the timebase. More will be said of this later.

The line timebase employs an EL38 self-oscillating pentode. No separate oscillator valve is employed and the circuit is shown in Fig. 4. The line hold, line linearity and width plunger are closely related and alteration to the width and linearity will almost always demand a reset of the hold slider.

However, the circuit is stable in operation, but if not a replacement EL38 will usually put things right. The H.T. metal rectifier, which is mounted on the left side of the rear chassis, has a profound effect upon the width of the picture, and this will reduce as the H.T. output voltage of the rectifier falls much below its rated 240 volts.

No EHT

The symptom of no EHT, no line timebase whistle, should direct attention to the EL38 and its associated components, the 6.8 K Ω screen dropping resistor, the controls, etc. It often happens that the line output transformer is at fault, however, and to facilitate the replacement of this a diagram is provided showing the actual connections. The transformer type is SL7 and the part number is CP72036. When fitting observe note on connections 9 and 10 with Fig. 3. The EHT rectifier valve is an EY51 and if the time-

base whistle is audible, but no raster can be resolved,

Frame Line Frame Voltage Adjustment Frame Shift Shift Aerial Height Hold Output Trans. ji. נם Attenuator ED. - 11 cove/ Fuses H V14Scanning Coil ٢ socket Metal Rectifier lisin 10 0 Frame 1/5 Output Line Output and E.H.T. Ċ Frame Width Osc. VI3 Transformi (@)_{V8} 0L10 \odot V4 ٢ \bigcirc Sound Rejector Sync Sep. VIO EY5 Ā Visio IF 0 Θ Sound EHT V3 e V7 smoothing ٥ VII 'n capacito Sound Main EL38 I.F. smoothing e lst. I.F. Sound capacitor's nd Vision Sound V2 Output Core Osc. Coil Tràns C.R.7 Anode 1/9 (0) CSD e VI e ō õ Socket for Loudspeaker RF Q, Aer'ial plug Trans. Trans. 0

Fig. 1.-Layout showing principal components.

Contrast

Volumę

and On/Off

a quick check of EHT voltage will show whether suspicion should be directed to this valve or not. If a spark cannot be drawn from the tube anode cap try again with the cap removed. If there is still no spark disconnect the .001 μ F EHT smoothing capacitor to prove that leakage through this is not responsible for the low or non-existent EHT. Assuming that this capacitor is in order, it will be necessary to examine the EY51. This is contained inside the line output transformer can. With the chassis removed and the EY51 exposed, test for spark at the anode (single wire end). If a spark can be drawn off, the EY51 will no doubt be in need of renewal. If it is immediately obvious that the valve heater is not glowing the foregoing tests may be dispensed with unless, of course, a replacement rectifier also does not heat up !

Sound and Vision

The actual sound and vision strip gives very little trouble and calls for but little attention. V1 is the R.F. amplifier in a conventional circuit with a sensitivity control in its cathode circuit. V2 is the mixer-oscillator. The oscillator coil is wired in the screen grid circuit. It is shunted by two fixed capacitors. If it is necessary to replace these at any time it is essential to use the identical types as the original. One has a negative temperature coefficient so that untoward oscillator drift does not occur as the temperature of the receiver changes. The oscillator coil is easily identified by its heavy gauge open winding. V3 is the first I.F. amplifier, common both

to sound and vision. Sound signals are taken from the anode to the first sound I,F. transformer via a 2 pF capacitor.

The receiver contrast control (on the front of the receiver, the brilliance being at the rear) is wired in the cathode circuit of V3 and thus affects the sound volume as well as the picture signal strength.

V4 is the vision I.F. amplifier and the sound rejector is wired in its cathode circuit. This is L10 and should be adjusted for minimum interference of sound with vision.

ference of sound with vision. The anode of V4 is transformer coupled to the vision detector or demodulator which is one section of V5 (6D2). The cathode of the detector is taken to chassis, via a $4.7 K\Omega$ in series with a 330 Ω resistor, a test point being provided at the junction so that a meter connected from here to chassis is actually across the 330 Ω resistor.

The cathode is coupled to the control grid of the video amplifier through a video choke shunted by a $47K\Omega$ resistor. The choke is actually wound on the resistor. From each side of the choke a 5 pF filter capacitor is taken to chassis, V6 is the video amplifier, the circuit of which is extremely simple. The anode load resistor is a $6.8K\Omega$, the bias resistor a 330 Ω shunted by a fixed 750 pF capacitor. One connection from the anode is taken to the sync separator via a 10K resistor, another connection is to the cathode of the second section of V5, which functions as the picture interference limiter, whilst a $.1\mu$ F capacitor, shunted by a 330K Ω resistor, carries the video signal to the C.R.T. cathode.

The anode of the limiter is wired to the cathode via three resistors and is taken to chassis through a $.05\mu$ F capacitor. The resistors are a 470K Ω , a 1M Ω and a 3.3M Ω .

Either the $3.3M\Omega$ or the $1M\Omega$ may be shorted by the action of a three position switch labelled "picture tone." The switch therefore alters the time constant of the circuit and controls the limiting action of the diode. The operation of the switch will tend to "flatten" the peak whites of the picture content.

Fault Symptoms

In order to describe the most common fault which occurs on this type of chassis it is necessary to examine the C.R.T. wiring.

As may be seen from Fig. 2, the cathode and heater are maintained at approximately the same D.C. potential by the inclusion of a 100K resistor. A 1/tF capacitor decouples the heater to chassis. Therefore, should a heater to cathode leak occur, part of the video signal will be shunted to chassis. This has the effect of persistent line tear, where the line hold control has no effect, and close inspection will reveal that some of the picture content is actually missing and the blank parts are discoloured.

Now this well-known effect does not occur so much on this model as on many others, as the frame timebase very quickly sync. "feels" the absence or partial absence of the sync pulses. Aspreviously mentioned, the frame timebase will not function properly unless reliable sync pulses are being applied. Therefore an unstable vertical movement may well herald the imminent necessity of an isolating trans-former. When the picture seems to fail completely, with what is left of the raster discoloured and flat, and this constantly building up and collapsing rapidly, the possibility of a heater/cathode short should not be ignored.

With the .1µF disconnectedthis is located under the chassis on the mains transformer-the picture should present a more The recognisable appearance. out of focus horizontal bands, the watery appearance of the verticals and loss of line hold being normal symptoms. To rectify this condition readers are referred to the January issue. The fitting instructions for isolating transformers have so many times been described before that we do not propose to repeat them here. The servicing article in the January issue dealt fully with this type of fault.

A word of warning, however; if a steady white line is present across the tube face, this does not indicate a tube fault, and the frame time-base itself will almost certainly be in need of attention. Always check the 6SN7 valve first, ensuring that *both* heaters are glowing, then inspect the 6L18 and make sure that a lead has not been pulled out of the four-pin scan coil connecting plug.


H.T. Supply

The normal H.T. is supplied from a metal rectifier of the 14A100 type. Some receivers employ a standard smoothing choke, whilst others use the field coil of the loudspeaker. Where the energised type is used the choke is omitted and where the choke is fitted a P.M. speaker will be found.

The A.C. input to the metal rectifier is derived from the transformer primary, highest tapping (250 volt). All valves, except the EV51, of course, have their heaters supplied from 6.3 volt windings on the transformer and although the tube heater is rated at two volts this winding is actually tapped, and 6.3 volt is available here if required. This winding has no connection to chassis except, of course, via the $.1\Omega F$ capacitor.

As the metal rectifier is fed from the transformer primary the chassis of the receiver is connected to one side of the mains and due respect and caution must be employed when handling under certain conditions.

Some models have extensive modifications such as




541

rotary controls in place of the slider type, a 12AU7 in place of the 6SN7GT, a Mullard MW31/16 in place of the Mazda CRM121 and the value of several resistors and capacitors may be found to differ, especially where the Mullard tube is employed.

As the MW31/16 has a 6.3 volt heater, the two-volt tapping is not used. This tube is not so liable to heater/cathode leakage as the CRM121, but it does seem to be prone to cathode to control grid failure.

An extremely interesting article by B. L. Morley



······

TV at Harwell


WHEN the U.K. Atomic Energy Authority opened its doors to visitors at Harwell recently they saw, among the many techniques, the newest application of industrial television.

For the peaceful uses of atomic energy an immense amount of detailed information on the properties of isotopes is essential. To obtain this information, isotopes have first to be sorted out, and this is done in what is called an electromagnetic isotope separator. A critical feature in the process involves keeping ion beams in sharp focus, and this is normally done by an observer watching the changing luminous patterns and telephoning instructions back to the control room operator.

This procedure is impracticable in the Authority's new separator for highly active isotopes, since this machine is built into a large sealed chamber to prevent the escape of any radiation.

A Pye industrial television camera, specially fitted with a shield so that it can operate in the strong magnetic field, has now been installed so that the control room operator can himself watch the luminous beam focus on a monitor screen.

Pye recently developed a special television camera for inspecting the interior of the nuclear reactors at the Atomic Energy Authority's Calder Hall atomic power station, a picture of which was shown in last month's issue (page 512). appeared in the February, 1954, issue, which dealt in detail with the frame multivibrator circuit of this receiver and included instructions for modifying the circuit so that the raster could be observed without the presence of frame sync pulses.



HUTURE OF BBC TELEVISION MR. GERALD BEADLE, Controller of the West Region of the BBC, who is to succeed Sir George Barnes as Director of Television Broadcasting in July, spoke of the future of BBC television at a dinner recently.

He said he would approach his new duties with zest and with admiration for the splendid achievements of the BBC Television staff so far. He expressed much pleasure at the prospect of working closely with Mr. Cecil McGivern who, he said, was more than any other single individual responsible for the present shape of the Service on the programme side.

present shape of the Service on the programme side. "Trying at this moment to peer forward through the mists of time I think I discern two formidable jumps before me. One is a second BBC Television Programme, which is absolutely necessary if a really conscientious service is to be offered to the public. The other is television in colour. When we shall reach them I do not know. The sooner the better as far as I am concerned. I hope we shall come up to these jumps during my term of office. . . ."

Mr. Beadle went on to say that he thought the BBC was in a uniquely favourable position because it had been conceived, borne and nourished through its early childhood by the British radio industry. It was a lusty youngster with a well-formed character of its own when it was taken over in 1927 by the present Corporation.



PRACTICAL TELEVISION



3.- A BRITISH SYSTEM

HE present American system of colour television is a simultaneous compatible system. This means that the information for each colour channel is transmitted simultaneously and not in sequence as in the systems discussed in the last article. The word compatible implies that the same scanning standards are used as for the black and white television system and the transmission is so arranged that the chrominance is separated from the luminance and the latter is transmitted as a signal which will give a normal picture on a black and white receiver. The chrominance signal contains colour information only and is used in a colour television receiver to modify the black and white picture and present it on a special tube in full colour. The following rather simplified description has related this American system to the existing British standards as it appears possible that this may be the system adopted eventually in this country.

The colour camera contains three camera tubes on which are produced optical images of the scene to be televised in each of the three primary colours by a system of dichroic mirrors as described previously. The output signals of these three tubes represent, at any instant, the amount of red, green or blue in the colour of the object which is being scanned—let us call these signals R, G and B. Now the luminance of any particular object is given by the equation Y=0.30R+0.59G+0.11B where Y stands for luminance. This follows from the fact that for equal energy sources of light the green light appears to the eye about twice as bright as the red one, and about six times as bright as the blue one. The output signals from the camera are therefore fed into what is known




Fig. 2. — Phase diagram showing the relative phase of the (R-Y) and (B-Y) signals, and also of the 1 and Q signals.

By C. Grant Dixon, M.A.

as a matrix amplifier which combines them in these proportions and delivers a combined Y signal which corresponds to a panchromatic representation of the original scene. This signal is then treated as a normal video signal and is transmitted in the normal way. A black and white receiver will thus display a perfectly satisfactory panchromatic image.

It would seem necessary to transmit three separate, channels of colour information in addition to the luminance, but by a very ingenious process all the colour information is condensed into a single






Fig. 1.-Frequency spectrum of the video signal.

chrominance channel which can be transmitted either separately or in the same channel as the luminance. To achieve this latter result, let us see first of all how the combined chrominance signal is produced. The matrix amplifier delivers two further signals R-Y and B-Y. The R-Y signal is the normal signal from the red camera tube with the luminance signal subtracted; this subtraction is brought about by adding a signal of opposite phase, the phase reversal being produced by a valve. The R-Y and B-Y signals thus define the amounts of purely colour information pertaining to the red and blue channels. As the Y signal was originally formed from the R, G and B signals it is clear that a G-Y signal can be obtained by suitably combining the R-Y and B-Y signals. It is therefore only necessary to transmit the two R-Y and B-Y signals along with the tuminance channel. The exact





way in which these chrominance signals are transmitted is still a matter of experiment in this country; they could well be transmitted on a separate fréquency with their own carrier or carriers, but it is naturally advantageous to keep all the transmission within a given frequency channel if this is at all possible. To achieve this the American system uses a reduced bandwidth for the chrominance channel. This would seem





Fig. 3.—Showing how a variation of colour is produced by combining the signals of different amplitudes.

transmission to suit the characteristics of the human eye.


Bandwidth

Having reduced the bandwidth of each colour difference signal it is now necessary to transmit them in the same channel as the luminance signal without mutual interference. If we consider a normal amplitude modulated transmission, it consists of a carrier with two "sidebands" whose frequencies are separated from the carrier by the modulating frequency. For audio transmission these sidebands are about 10 kc/s wide. For a television transmission they are 3.5 Mc/s wide and one of the sidebands is suppressed at the transmitter. But this is not the whole story—the modulating frequency consists largely of the line frequency of 10,125 cycles (in this country) and harmonics thereof, and so the whole of the sideband is not occupied. The energy appears in groups spaced at 10,125 cycle intervals with spaces in between (see Fig. 1). In order to make use of these gaps the modulated carrier which conveys the chrominance information is spaced from the main carrier by an odd harmonic of twice the line frequency; this ensures that the chrominance sidebands, which are similar in nature, interleave the luminance sidebands as shown in



the figure. The chrominance carrier is normally generated at 2.65781 Mc/s, modulated with the chrominance signal, mixed with the normal luminance video signal and then passed to the transmitter in the normal way.

But there are *two* colour difference signals to be transmitted, and the way in which this difficulty is overcome is one of the triumphs of modern electronic engineering. Each colour difference signal is caused to amplitude modulate a colour sub-carrier of the frequency mentioned above, but the two sub-carriers are 90 deg. out of phase. When these are combined we are left with a signal represented by a rotating vector whose amplitude is proportional to the saturation of the colour, and whose phase with respect to a given reference phase governs the actual hue transmitted. Fig. 2 is a phase diagram showing the relative phases of the different colours, and Fig. 3 shows how different amplitudes of the two colour difference



signals can produce different colours. This modulation is performed in a balanced modulator so that the colour sub-carrier is suppressed and its sidebands only are transmitted along with the luminance video. At the receiver the colour information is recovered by reinserting the carrier, with appropriate phase, in the colour demodulator section. Naturally the phase of the locally generated sub-carrier in the receiver must be the same as that of the original sub-carrier at the transmitter and this is ensured by transmitting a "burst" of about 8 cycles of the colour sub-carrier on the back porch of the line sync pulse (Fig. 4). This is separated out in the receiver and used to lock a crystal oscillator which provides the two demodulating signals (differing in phase by 90 deg.) through a phase shifting network.

Having recovered the R-Y and B-Y signals, these are then added in the proper proportion to give a signal which, when reversed in polarity is G-Y, i.e., -(G-Y)=0.51(R-Y)+0.19(B-Y). The three colour signals are then fed to the grids of a special three-gun colour cathode-ray tube and the luminance^{*} signal is fed to the cathodes. Thus the net effect on, say, the red gun is (R-Y)+Y=R, i.e., red signal, and similarly for the blue and green.

Referring back to the phase diagram, Fig. 2, it will be noticed that two lines are marked 1 and Q. The American system uses the I and Q signals instead of the R-Y and B-Y as it is found that the eve perceives

Mullard Line Selector

THIS new instrument enables any individual line to be selected from a complete picture signal and displayed on any conventional triggered oscilloscope. The line selector can be used on transmitter or receiver circuits in the examination of depth of modulation, D.C. levels, bandwidth and synchronisation. "Through" or "terminated" (80 ohms co-axial cable) measurements can be made.

Design Features

The Mullard line selector provides output pulses of 50 microseconds duration, delayed with respect to the frame synchronising pulses. These output pulses can be used to initiate the trace of a triggered oscilloscope, the sweep duration of which is adjusted to display one or more lines of the video signal.

Stability

The chief problem in a line selector is to provide jitter-free output pulses to trigger the oscilloscope. Since the line selected occurs only once in every complete picture cycle (i.e., on every "odd" frame only or every "even" frame only), the output pulse repetition frequency is 25 per second. The sweep time needed at the oscilloscope to display a single line is only about 100 microseconds. If a sweep expansion of 10 times is used in order to examine in detail a portion of the line, the effective sweep time is only 10 microseconds. This is very short compared with the interval between successive triggering pulses (40,000 microseconds) and a high order of stability of pulse repetition frequency is called for if serious jitter is to be avoided. In the Mullard Line Selector, freedom from jitter is obtained by the use of a special delay circuit and a built-in stabilised high tension supply.

Pulses of either polarity, with sharp leading edges, and a duration of about 50 microseconds, are supplied to the output co-axial sockets. The pulse repetition


medium-fine detail in colours which range from orange to cvan : colours which are similar to those used in the very early two-colour films. Thus a larger bandwidth is allotted to these colours and they are transmitted as the I channel whereas the green to magenta colours represented by the Q axis are given a narrower bandwidth. The I and O sidebands and their relation to the main carrier are shown in Fig. 5. Thus for low frequencies (coarse detail) full threecolour rendering is supplied; for medium frequencies (medium fine detail) two colour information is supplied, ranging from orange to cvan ; and for high frequencies (very fine detail) only the brightness component remains and the finest detail is rendered in shades of grey. This procedure carries a stage further the process of adapting the transmission to fit the human eye. In actual practice, however, it has been found that very little is lost if the R-Y and B-Y signals are used with equal bandwidth on each channel, and this simplifies receiver circuitry. Time alone will decide which is the final system to be adopted in this country.

To sum up, a block diagram is given (Fig. 6) to show the circuits which are used in a colour television receiver in addition to the normal circuits. Scanning and sync separating circuits are not shown and no details are given of the colour cathode-ray tube which will be considered in the next article.

(To be continued)

frequency may be 25 per second, as discussed above, but facilities are also provided for a p.r.f. of 50 per second, initiated by sine or square waves locked to the frame pulse. Suitable 50 c/s sine or square waves are provided by most commercial pattern generators, and enable the line selector to be used for investigating faulty interlacing.

The output pulses are delayed with respect to the frame synchronising pulses which initiate them.



Television Line Selector

In order to display single lines when using the 25 p.p.s. repetition frequency, the amount of delay introduced by the line selector is made to vary by discrete amounts, the duration of any particular delay being an integral multiple of the duration of one complete line.

The line selector can operate with positive or negative inputs of 5-50 volts (high impedance input) or 0.5 to 5 volts (low impedance input). The high impedance input (250 kilohms shunted by 12 pF), enables the instrument to be operated from the video stage of a receiver. The low impedance input, which can be switched to 22 kilohms or 80 ohms, is for "through" or "terminated" measurements where the signal is supplied via a co-axial cable.

July, 1956

Analysis of Viewing Audiences

BBC FIGURES FOR THE FIRST QUARTER, 1956

THE following table, issued by the BBC, shows that viewing audiences were much bigger in January/March, 1956, than in January/March, 1955.

Average level of evening viewing among the adult population :

	4	er cent. of the	
	ac	lult population	
January/March, 1956—BBC		15.4	
—I.T.A.		1.6	
•		17.0	
x		14.0	

January/March, 1955 ... In January/March, 1955, it was normal for some 5,600,000 adults to be viewing. In the same quarter of this year the average was 6,400,000. Of this latter figure viewers of BBC programmes accounted for about 5,800,000-an increase on the previous year, despite the introduction of competition. (The estimate, given above, of the size of the average I.T.A. audience during the past quarter, masks an increase following the opening of the Lichfield transmitter late in February. It is estimated that I.T.A. audiences averaged rather over 500,000 adults between January 1st and February 18th, and nearly 700,000 in the rest of the quarter.)

The following table compares the level of viewing amongst adults with TV receivers at home. The number of such people (the "TV public ") in January/ March, 1955, was about 12,100,000 and by January/ March, 1956, had increased to about 15,700,000. Since some of the latter could receive I.T.A. programmes as well as those of the BBC a distinction is made in Table IV between viewers who had, and had not, a choice of programme. The number of adults who could receive I.T.A. as well as BBC programmes at home is estimated to have been about 1,900,000 at the beginning of the quarter (when only the Croydon transmitter was transmitting I.T.A. programmes) to just under 3,000,000 at the end of the quarter, by

IGHTNING

HE following comments have been issued by Messrs. Belling & Lee, Ltd., manufacturers of aerials and accessories. Notices in certain sections of the Press suggest that there is a measure of risk of television aerials being struck by lightning. If there were any significant danger to property, the insurance companies would not be slow in adding a shilling or premium. Each "Belling-Lee" aerial carries an insurance against damage by lightning and this is passed on to the ultimate user. During the past 17 years well over two million TV aerials and "Skyrods" have been sold by Belling-Lee and erected, but claims for damage by lightning brought to their notice barely reach a dozen, and in no case was damage done to the fabric of the house but only to the receiver. In the same period many thousands of buildings without television aerials have been struck and damaged.

When lightning conductors are fitted to a high building, the conductors are generally of very heavy copper strip, about 12in. wide and fin. thick .: Cost

which time the Lichfield transmitter had been open for five weeks.

Average level of evening viewing amongst the adult television public:

	Per cent. of TV	Per cent. of TV
	public with	public without
	choice of	choice of
1	programme	programme
January/March, 1956		N - E at #
BBC	16.5	39.6
I.T.A	23.9	— .
	40.4	39.6
January/March 1955		43.8

(i) Amongst those whose sets could receive BBC programmes only, the average audience was slightly less this year than last. The difference; small as it is, does not, however, represent an equivalent fall in the average amount of time spent in viewing, for the number of hours of programmes was greater this year than last. For practical purposes it may be said that there has been no change in the extent to which this group of viewers watched television.

(ii) The level of viewing of those who have a choice differs little from that of those who have not. As was suggested in the report on the October/December quarter, the effect of "having a choice" is not to increase the amount of viewing, but to cause viewers to divide the same amount of time among the available alternatives.

(iii) Amongst those adults with a choice of programme-most of whom had, of course, deliberately adapted their receivers for this purpose-the average level of viewing of BBC programmes during the January/March quarter is estimated to have been 16.5 per cent., and that of I.T.A. programmes 23.9 per cent. Put another way, for every 41 of these people who were viewing the BBC, it was normal to find 59 viewing the I.T.A.

of labour and material would be many more times that of a television receiver and its aerial." Such buildings are not immune, and if the lightning charge is heavy, the copper will melt, but generally the copper is heavy enough to carry the charge. In the case of a television aerial, if the aerial is struck, the feeder (lead-in) generally disappears. It is instantaneously melted, and the charge follows the path of the metallic vapour. A report issued last year by the Fire Research Board confirmed that the presence of aerials has no effect on the prevalence of lightning strikes.

The rising column of smoke, or even air, issuing from a chimney is more conductive than the normal air surrounding the roof. The influence of that smoke or air is greater than any aerial, and if a static or lightning charge chooses to go to earth in the vicinity, it will follow down that conductive air column, and probably shatter the chimney (which is generally a carbon-coated tube); and perhaps destroy the fireplace on the way. In any case, the damage would be much more serious than if a television aerial were the fight as a contract in the state of the struck.

ł

-11-

T

PRACTICAL TELEVISION



FFDS I


postage 2/3.

MAIL ORDER ONLY

PRACTICAL TELEVISION

July, 1956

,		
$\begin{array}{c} \textbf{RADIO SUP} \\ \textbf{RADIO SUP} \\ Post Terms C.W.O. or C.O.D. NO C.O. 1/6 extra under £1: 2/- under $23.0 pcm c.S.A.E. with enguiries, please.S.A.E. with enguiries, please.T. S.A.E. S.A.E. With enguiries, please.T. S.A.E. S.$	 BATTERY SET CONVERTER KIT All parts for converting any normal type of Battery Receiver to A.C. mains 200250 v 50 vs. Supplies 120 v 90 v or 60 v at 40 ma. Fully smoothed and fully smoothed L.T. 62 v at 0.4 a to 1 a. Price including circuit 49/3. Or ready for use, 99 extra. BURY RECEIVER BATTERY ELIMINATOR KITAll parts for the construction of a unit (metal-case 5144-21n.) to supply Battery Portable incelvers requiring 50 v and 1/5 v. Fully smoothed. From 200-250 v 50 c s mains. Frie, inc. point-to-point wiring dia- grams, 39/9. Or assemble and tested at 46/9. C.S. TAI HIGH QUALITY TAPE DECK AMPLIFIER. For ALL Tapo Decks with High Impedance, Playback and Erasc Heads, such as Lane. Truvox. Adjustment to type of deck Ready for made by alteration of a Use ONLY resistor. For A.C. Mains 200-250 v. 200 (cs. Positive 11) GNS compensated identification of recording level given by Magis 15, 71 or 51 free of a knob. Lincar frequency resistor. Altomatic equalisation at tortonless reproduction. Sengati tortonless reproduction. Sengati tortonless reproduction. Sengati incording a A. amplific. Unity is incording a A. amplific. Such as the distribution of cording level given by Magis 10, 51, 71 or 51 frequency frequency response of a knob. Lincar frequency response of a knob. Lincar frequency response of a knob. Lincar frequency frequency of a knob. Conception and the tortionless reproduction. Sengati incording a A. amplific. Unit can also be used as a gram-applifier requiring input of 0.75 v R.M.S. Carriage 76. Hustrated leadets dd. Normels a a gram applifier requiring input of 0.75 v R.M.S. Carriage including 52/40. Also mains trane 1. F. 	
LASKY'S RADIO	SPECIAL OFFER! GARRARD RC.1 3-SPEED AUTO-CHANGERS Brand new in maker's cartons. Complete w turnover crystal pick-up. Incorporates automa record size selection (mixer). Cabinet spi required : 14in. x 12jin. x 49/16in. above a ziin. below motor board. Cream and Bro enamel finish. Limited quantity only. List fil.13.0. LASKY'S PRICE £8.19 Carr. 5/ Cabinets available.	ith the ace and the second sec



95년 548

All Channels, 3-, 4-, 5- and 6-element outdoor, also indoor and loft types, Aerialite, King Pin, Labgear, Belling Lee, Wolsey, etc. Also Co-axial Cable Aeraxial, Diplexes, Crossover Boxes, Co-axial Plugs, Co-axial Sockets.



THE NATIONAL

EARLS COURT August 22nd to

September 1st

RADIO SHOW

Name	Address	Stand No.	Name	Address	Stand No.
Aerialite, Ltd	Castle Wks., Stalybridge,	51	English Elec. Co.,	Queens Hse., Kingsway,	40
	Cheshire	212	Ltd.	W.C.2	
Airmee, Ltd Ambassador Radio & T/V, Ltd.	High Wycombe, Bucks. 37/39, Thurloe St., S.W.7	43	Ever Ready Co. (G.B.), Ltd.	Hercules Place, Hollo- way, N.7	54
Antiference, Ltd.	Bicester Rd., Aylesbury,	69	Ferguson Radio Corp., Ltd.	105-109, Judd St., W.C.1	12
Automatic Coil Winder & Elec.	Bucks. "Avocet House," 92/96, Vauxhall Bridge Rd.,	3	Ferranti, Ltd.	Hollinwood, Lancs.	31 & 68
Equip. Co., Ltd.	S.W.1		Garrard Eng. & Mfg. Co., Ltd.	Newcastle St., Swindon, Wilts.	50
Balcombe, Ltd., A. J.	52-58, Tabernacle St., E.C.2	. 61	General Elec. Co.,	Magnet Hse., Kingsway,	53
Belling & Lee, Ltd.	Gt. Cambridge Rd., Enfield, Mddx.	49	Ltd. Goodmans Indus-	W.C.2 Axiom Wks., Lancelot	105
Bowmaker, Ltd	29/30, St. James's St., S.W.1	208	tries, Ltd. Gramophone Co.,	Rd., Wembley, Middx. Hayes, Middx.	28
Bulgin & Co., Ltd.,	Bye Pass Rd., Barking,	26	Ltd.		
A. F. Bush Radio, Ltd.	Essex Power Rd., Chiswick, W.4	17 & 29	Hart & Co., Ltd., Alfred	243-249, Upper St., High- bury Corner, Islington, N.1	209
Ĉhannel Elec- tronic Industries, Ltd.	Dunstan Rd. Estate, Burnham - on - Sea, Somerset	108	Hunt (Capacitors), Ltd., A. H.	Bendon Valley, Garratt L a n e, Wandsworth, S.W.18	25
Cole, Ltd., E. K	Ekco Wks., Southend-on- Sea, Essex	24 & 30	Independent Tele- vision Authority	14, Princes Gate, S.W.7	309, 310 &
Collaro, Ltd	Ripple Wks., By-Pass Rd., Barking, Essex	21	Invicta Radio, Ltd.	100, Gt. Portland St., W.1	311 65
Co-operative Wholesale	1, Balloon St., Man- chester, 4	35 & 37	J. B. Mfg. Co.	Howard Way, Harlow,	115
Society, Ltd. Cosmocord, Ltd.	700, Gt. Cambridge Rd.,	202	(Cabinets), Ltd. J. Beam Aerials, Ltd.	Essex Westonia Weston Favell, Northampton	I
Cossor, Ltd., A. C.	Enfield, Middx. Cossor Hse., Highbury	57	Kolster-Brandes,		20
Cossor Instru-	Grove, N.5 Cossor Hse., Highbury	206	Ltd.	· · · · · · · · · · · · · · · · · · ·	20
ments, Ltd.	Grove, N.5	58	Labgear (Cam- bridge) Ltd.	Willow Place, Cambridge	203
Decca Record Co., Ltd.	1-3, Brixton Rd., S.W.9		McMichael Radio,	Slough, Bucks.	59
Domain Products, Ltd.	Domain Wks., Barnby St., N.W.1	107	Ltd. Marconiphone Co.,	Hayes, Middx.	23
DubilierCondenser Co. (1925), Ltd.	Ducon Wks., Victoria Rd., North Acton, W.3	62	Ltd. Masteradio, Ltd.	10-20, Fitzroy Place,	15
Dynatron Radio, Ltd.	"The Firs," Castle Hill, Maidenhead, Berks.	, 4	Mullard, Ltd	N.W.1 Century Hse., Shaftesbury	32
E.A.P. (Tape Recorders), Ltd.	9, Field Place, St. John St., E.C.1	215	Multicore Solders, Ltd.	Ave., W.C.2 Maylands Ave., Hemel Hempstead, Herts.	10
E.M.I., Ltd E.M.I. Institutes, Ltd.	Hayes, Middx. 10, Pembridge Sq., W.2	16 307	Murphy Radio, Ltd.	Welwyn Garden City, Herts.	42
Edison Swan Elec. Co., Etd.	155, Charing Cross Rd., W.C.2	19	NEWNES, LTD., GEORGE	Tower Hse., Southampton Street, Strand, W.C.2	111
Electric Audio Re- producers, Ltd.	The Square, Isleworth, Middx,	67	Nixa Record Co., Ltd.		5
producers, Etd.	HINGA,		Latte.		۹ است

List of Principal Exhibitors

in Alphabetical Order, with Stand Numbers

PRACTICAL TELEVISION

Stand

Ju	V.	1956

Name -	Address	Stand No.
Pam (Radio & T/V) Ltd.	295, Regent St., W.1	55
Pamphonic Repro- ducers, Ltd.	17, Stratton St., W.I	34
Peto Scott Elec. Instruments, Ltd.	Addlestone Rd., Wey- bridge, Surrey	14
Philco (Overseas), Ltd.	Romford Rd., Chigwell, Essex	22
Philips Elec., Ltd.	Century Hse., Shaftes- bury Ave., W.C.2	44 & 45
Pilot Radio, Ltd	Park Royal Rd., N.W.10	27
Plessey Co., Ltd	Vicarage Lane, Ilford, Essex	- 9
Portogram Radio Elec. Ind., Ltd.	Preil Wks., St. Rule St., S.W.8	66
Pye, Ltd	Cambridge	13
AND "PRA	TICAL WIRELESS " CTICAL TELEVISION " TAND No. 111	,
RCA Photophone,	Lincoln Way, Windmill	
Ltd.	Rd., Sunbury - on -	103
Radio & Allied		33
	Rd., Sunbury - on - Thames, Middx. Langley Park, Slough, Bucks.	
Radio & Allied Ind., Ltd. Radio Gramophone Dev. Co., Ltd. Regentone Radio	Rd., Sunbury - on - Thames, Middx. Langley Park, Slough, Bucks. Eastern Avenue West, Mawneys, Romford, Essex Eastern Ave. West, Rom-	33
Radio & Allied Ind., Ltd. Radio Gramophone Dev. Co., Ltd.	Rd., Sunbury - on - Thames, Middx. Langley Park, Slough, Bucks. Eastern Avenue West, Mawneys, Romford, Essex	33 52

Rola Celestion, Ltd.	Ferry Wks., Thames Ditton, Surrey	6
Simon Sound Ser- vice, Ltd.	48, George St., Portman Square, W.1	46

Square, W.1

Television in Malta

ALTA has not yet plunged into the maelstrom of television by erecting its own transmitter, but there appears to be good possibilities of reception there from the new transmitter which is to be erected on Sicily.

The Radio Audizioni Italia (R.A.I.) are proposing to erect a new transmitter on Monte Lauro for television broadcasting.

The site of the transmitter brings it to a height of over 3,000ft. above sea level (actually it is 980 metres). and should radiate over a fairly wide area, though ghost reception is possible in some areas due to reflections from Mount Etna.

The transmissions will follow the usual standard as already existing in Italy, i.e., the 625-line system with negative modulation and frequency modulated sound (the C.C.I.R. system).

At present we have no information on the polarisation but it is possible that this will be vertical as in the case of the Turin transmitter. The C.C.I.R. system generally recommends horizontal polarisation, and this is mostly the standard method in Europe.

The exception to this, of course, is France, which has not adopted the C.C.I.R. system but has her own 441-line and 819-line system, with vertical polarisation. The 441-line system is virtually obso-

Name	Address	Stand No.
Spencer-West, Ltd.	Quay Works, North Quay, Great Yarmouth, Norfolk	211
Standard Tel. & Cables (Brimar) Ltd.	Receiver Valve Division, Footscray, Sidcup, Kent	39
Standard Tel. & Cables, Ltd. (SenTerCel)	Connaught Hse., Aldwych, W.C.2	117
Stella Radio & Tel. Co., Ltd.	Oxford Hse., 9-15, Oxford St., W.1	56
Tape Recorders (Electronics)Ltd.	784-788, High Rd., Tot- tenham, N.17	- 38
Taylor Electrical	Montrose Ave., Slough,	106
Instruments, Ltd. Telegraph Con- denser Co., Ltd.	Bucks Wales Farm Rd., North Acton, W.3	64
Telerection, Ltd.	Antenna Wks., St. Pauls, Cheltenham, Glos.	. 18
Telequipment, Ltd.	313, Chase Rd., South- gate, N.14	63
Ultra Elec., Ltd	Western Ave., Acton, W.3	. 41
Valradio, Ltd	New Chapel Rd., Feltham, Middx.	213
Vidor, Ltd	West St., Erith, Kent	11
Waveforms, Ltd	Radar Wks., Truro Rd., N.22	205
Westinghouse Brake & Signal Co., Ltd.	82, York Way, King's Cross, N.1	102
Whiteley Elec. Radio Co., Ltd.	Radio Wks., Victoria St., Mansfield, Notts.	.47
Wolsey Television, Ltd.	43-45, K n i g h t ' s H i l l, West Norwood, S.E.27	2

lescent and will eventually be completely replaced by the 819-line system.

The new transmitter in Sicily will operate on channel E5, which is in Band HI. Figures given are 174 Mc/s vision carrier with sound on 181 Mc/s.

Vision is to be radiated at a power of 7.5 Kw., the aerial power gain being 12.

Although the transmitter is at a distance of 200 miles from Malta, the fact that some of the distance is over the sea makes it hopeful that reception may be obtainable at high points in the island, and with a good aerial system we think it is possible to get signals under favourable conditions.

Please note that we do not expect anyone to rush to order a television receiver on the strength of this, but we think that the experimenter would find it worth his while.

Circuits used in the British system could be adapted. As negative modulation is employed it would be necessary to reverse the connections of the cathode and anode of the diode detector in the vision circuit. In most cases the line oscillator would cater for 625 lines, but if this is found not to be the case, then a reduction of the discharge condenser should enable the frequency to be covered.

As an example, the condenser in the popular Miller circuit could be reduced to 50pF (the actual value depends, on the value of the associated resistors).

S

NEW BAND III NEW CONVERTER

DETAILS OF A UNIT FOR LICHFIELD AND LONDON

By "Serviceman"

N OW that some experience has been gained on the practical use of converters for the ITA, several points have been clarified; some of these points were anticipated in the early stages and were taken care of in the design.

One rather important point which was not fully anticipated by some was the possibility of re-radiation, and this has been a real problem in certain localities. Where conditions have been severe it has been found that the operation of a converter has caused re-radiation of the Band III signal into Band I, with the result that near neighbours have been receiving the ITA programme superimposed on their BBC picture.

In Band 1 there has been comparatively little trouble from re-radiation mainly because of the practically universal use of an R.F. pentode valve as the first valve of the receiver.

Modern technique has developed the cascode circuit so much that it is practically a universal arrangement for the front end of Band III receivers, including converters. The use of the cascode is an obvious choice because of its inherently low-noise characteristics.

In Band III our main noise problem is that of valve noise and the amount of noise generated in the very first valve of a receiver is amplified by all the subsequent stages. It is obvious, therefore, that the first stage noise must be kept as low as possible; the R.F. pentode generates comparatively more noise than the triodes arranged in cascode and hence the development of the latter type of circuit.

Where signal strengths are of an average value then it is possible that a pentode can be used, and trials were made with this class of circuit. The results

proved quite satisfactory and the circuit described in these pages was designed.

It is important to realise that with the pentode valve we have the position of two grids between the anode and the grid. In the case of the triode there is nothing between the grid and the anode and so a kind of feedback can and does occur between them. This feedback is the well-known "Miller" effect.

Without delving too deeply into the technicalities it can be said that a signal at the anode of the triode can "get through" to the grid and hence into the grid circuit and the aerial system.

The feedback generally takes the form of oscillation and so when a triode valve is used for highfrequency work some method must be employed to overcome this defect.

A simple method is to feed back a portion of the output signals from the anode to the grid circuit so that it is in opposition to the feedback taking place internally within the valve. The method is termed neutralisation.

Most forms of neutralisation depend upon a tuned circuit and it is very effective at the *frequency to which the input is tuned*. What is not so obvious is that at other frequencies the neutralisation may not be so effective and it is possible for a frequency removed in value from the signal frequency to get back from the anode to the grid of the valve and thence to the aerial system without any apparent ill effect.

Earthing the grid of the valve as is done in cascode circuits is not the complete answer, and even in the cascode circuit which has two triode valves in series so to speak, it has been found that appreciable feedback can take place.

The net result is a radiation from the aerial system




Fig. 1.-Layout and wiring of the converter.

Please note that this is not invariably the case, but it happens far more frequently than is realised.

With multi-channel televisors the problem is not so accute especially where the new standard I.F. is used: Radiation may take place at the intermediate frequency but it is not so likely to cause interference except where a similar receiver has bad screening of its 1.F. stages.

When more televisors using cascode circuits and I.F.s at 34.75 Mc/s are in use, then some further troubles from interference may be experienced.




Fig. 2.-Suggested form of aerial switching,

The present design described here has gone back to the use of the pentode to act as a buffer between oscillator and mixer and the aerial circuit.

It will be found that for normal service area working the circuit will prove very satisfactory, but where the signal is weak then a preamplifier can be added, but it is recommended that this is of the cascode type.

The gain of this converter is a little better than the standard cascode arrangement yet it will not be found to be too noisy.

The Converter

The circuit of the converter is shown in Fig. 9. It is a two-valve circuit using an EF80 pentode R.F. amplifier, followed by an ECF82 a triode pentode oscillator and mixer.

The input to the converter is made via a filter circuit L1 C18 which is tuned to reject the local station (in most cases this will be Sutton Coldfield on Channel IV for Lichfield viewers).

It will be noted that the aerial is isolated from the chassis and the receiver by C1 and C2. The reason is to ensure that the aerial itself does not become alive should the feed from the power supply be of the universal type. C1 and C2 should be good quality ceramic type of condensers.

The aerial circuit is tapped into the first Band III




Fig. 4.—Suitable power supply unit.

coil L2 the tap being made at about half a turn. By this method some stage gain can often be obtained. If little is gained in actual practice then L2 can be substituted with a 100 Ω resistor which provides an input (taking into account the input impedance of the valve) which matches reasonably well into an 80 Ω feed.

V1 is a conventional R.F. amplifier with decoupled heater supply, this being accomplished by the simply-made choke "CH1."

The output of the valve is tuned by L3, which is at Band III signal frequency. Note that the H.T. feed to this value is fully decoupled.

Output from VI is fed directly to the grid of the mixer V2 via the small condenser C6. Note that it is a good precaution to use a screen on this valve in an effort to prevent Band I break-through. 1.1 must also be screened for the same reason, and for this reason a Haynes type of coil unit is specified.

The second portion of V2 is used in a standard Colpitts circuit C13 forming the tuning capacitor. It was decided to make this a variable component so as to overcome the possibility of frequency drift. It




Fig. 3.—Output switching.

has a maximum capacity of 10 pF and is a Cyldon type number 18/5.

The control to this tuner can be brought out on a long spindle so that it can form a user control. After the converter has been lined up, then the capacitor should simply be adjusted for maximum sound.

There should be very little difficulty in this connection, as televisors made for Sutton Coldfield and for Holme Moss employ the single sideband method with the use of the lower sideband.

Output from the oscillator is fed directly to the grid of the mixer portion of V2. There is no internal connection made within the valve itself.

Bracket for Operating arm Toggle Switch Toggle Switch Section through spind/e ====== Chassi**s**

Fig. 5.-Method of mounting power supply switch.

Note that the output feed is taken via the condensers C8 and C9 so that the feeding coaxial cable is isolated from the chassis.

The Aerial System

It will be practicable in many cases for the ITA signals to be received on Sutton Coldfield (Channel 4)-aerials. In this case switching could be arranged so that the aerial is switched from the Band III programme to the Band I. A schematic diagram of this is shown in Fig. 2. A two-position two-way switch is required and can be wired as shown in the diagram.

Such a method avoids using a separate aerial for Band III and also avoids the necessity of plugging aerials in and out. The disadvantages are the possibility of feedback causing instability and the losses likely to be incurred in the switch. For the latter reason it is advisable to use a switch of the ceramic type, and one taken from an old R.F.24 or 25 unit will prove of value.

Where a separate power supply is used for the converter, then the changeover switch can be coupled to a toggle switch to switch the power on and off.

The toggle switch can be mounted by means of a simple bracket so that it can be actuated by the operation of the aerial switch. The spindle on the aerial switch is drilled and an operating arm (a small bolt




Fig. 8.—Practical arrangement of Fig. 3.

through the drilling) is fitted in such a position that when the switch is in Band III position the toggle switch is operated, and the convertor switched on, or when in the Band I position the converter is switched off.

If this arrangement is tried it is advisable to have a pilot light in a visible position so that the converter is not left switched on unnecessarily.

Generally speaking it is better to control the supply to the converter by the same switch which controls

the televisor, but the above method of coupling with the aerial changeover switch can be employed.

Where a separate Band III aerial is used this can be left permanently connected to the converter and, if desired, the output section can be switched as given in the PRACTICAL TELEVISION Band III Converter. The circuit for this arrangement is given in Fig. 3, and the practical circuit as applied to a two-pole double-throw switch is shown in Fig. 8.

If it is desired to use a single feeder for a Band III aerial, plus a Band I aerial, then the arrangement shown in Fig. 6 can be employed. Note that this arrangement should only be used where there is adequate Band I and Band III signal strength.

The Coils

The coils are made in two kinds : there is L1 (the Band I rejector coil) and L5, which is the output coil, both of these being wound on Haynes coil forms,




Fig. 6.-Method of using a single feeder.

and there are the signal frequency and oscillator coils which are wound on $\frac{1}{3}$ in, diameter coil forms.

Coil L1

This is the Band I rejector coil and is wound on a Haynes coil former, which provides effective screening. For Channel 4 (Sutton Coldfield) seven complete turns are required. Enamelled wire should be used of about 32 s.w.g. and adjacent turns should touch each other. The opposite ends of the coil are brought out to the side wires and C18 is wired directly across them. It will be found that there is sufficient room within the coil screen to get the small condenser situated comfortably.

If the converter is to be used on a receiver tuned to *Holme Moss*, then nine turns will be required, while for *Wenvoe* six turns are necessary.

If it is intended to use the converter with a fivechannel receiver, i.e., one which can be switched over any of the five channels in Band I, then it is a good idea to operate the converter for another channel.




Fig. 7.-Details of the chassis.

For example, if Sutton Coldfield is the local station, then the converter can be tuned for Holme Moss and when in use the televisor can be switched to Holme Moss. This will avoid possibilities of breakthrough.

If the constructor wishes to use the converter on the London (Channel 1) frequency, then the coil should have 11 turns.

Coil L2

This is the primary tuning coil. It is wound with about 22 s.w.g. bare wire on a $\frac{1}{4}$ in. diameter coil form. Two complete turns are required, the spacing between being at $\frac{1}{4}$ in.

To wind the coil, first wind on one turn and mark the half-turn position ; take the wire off and at the marked position make the tap by soldering a short length of wire at that point. Now place the wire back on the former and complete the winding of the two turns.

When the coil is set in position in the unit, then the soldering of the ends should keep the wire in position on the former. Do not use coil dope, though a little dope placed at the bottom end and the top end may be permissible. Dope of the low loss type must be employed.

Coil L3

This coil is wound exactly as 1.2 except that no tap is made. Two turns spaced at $\frac{1}{4}$ in. are required and coil dope should not be used.

Coil L4

This is the oscillator coil and it is wound, like L2 and L3, on $\frac{1}{2}$ in. coil forms. Enamelled wire should be used and the turns should practically touch each other. 22 s.w.g. wire should be employed.


Coil L5

A Haynes coil unit is used for this coil as for L1. It comprises two coils, the first one (connected in the anode of V2) is wound exactly like L1 and the same number of turns is required.

The second small coupling coil is wound above the main coil, within $\frac{1}{3}$ in. of it. This means that the two coils must be separated by $\frac{1}{3}$ in.

For channels 3, 4 and 5 two complete turns are required. For channels 1 and 2 only three complete turns are required.

One tuning core is necessary and this covers both coils. In practice only the bigger coil is tuned.



554

Construction

The construction of the converter is quite straightforward, the main point being short leads, direct earth connections and chassis ventilation. The latter is to counter any frequency drift though the variable tuner will do much to overcome this.

The chassis can be made of aluminium and the main dimensions are given in Fig. 7. Remember to make ventilation holes.

Haynes coil units can be made up when the chassis has been constructed and then bolted in position. Remember to take note of the pins to which the coil connections are made within the coil can.

Mount the valveholders, the remaining coil forms, the input and output sockets, and the tag strips and then commence the wiring. A wiring diagram is given in Fig. 1.

Keep all leads short and direct and leave no more than $\frac{1}{2}$ in. of wire from a component where possible. In order to avoid damaging resistors, etc., with heat the wiring pliers should grip the wire between the component and the soldering point so as to carry away the heat.

When the wiring has been completed check it carefully with the circuit diagram and ensure that all is correct.

Power Supply

It is recommended that a separate power supply is fed to the converter where possible. A small standard power pack for A.C. mains is shown in Fig. 4. The transformer should have an output of 250 v. at 30 m/A and 6.3 v. 1-2 A.

Two metal rectifiers RM3 are used in series to cater for the 250 volts (each rectifier handles 125 volts). Any similar type of rectifier can be used.

Where it is desired to work the unit from the existing power supplies in the televisor, care must be taken as many modern television receivers are working at the limit.

If the power arrangements are D.C. then the D.C. equivalent of the valves must be used of course.

It is important that the power unit is kept well clear of the converter proper, though both can be mounted on the same chassis if desired. The main precaution is to avoid frequency drift due to heating effects.

Alignment

With the power supply connected the unit should be allowed to warm up and then the output can be plugged into the televisor input.

The output coil L5 should now be adjusted until a hissing noise is heard on the loudspeaker of the televisor. Note that as most televisors have the contrast control arranged so that it has some effect on the sound as well as the contrast, then the control should be adjusted for maximum.

It is possible that "snow" may be seen on the screen at this point when normal brilliance is used, but it should be ignored for the time being.

With the Band III aerial plugged in the "fine" tuning control should be set at mid-position, and a non-metallic trimmer should be used to adjust L5 for maximum hiss. Now adjust the oscillator core until the Band III sound is heard in the loudspeaker. If any Band I breakthrough is heard before this stage is reached, then adjust L1 to eliminate it.

When the sound is received then adjust L2 and L3

for maximum sound, watching the screen meanwhile to ensure that the picture signal is not overloading the circuits. The contrast can be reduced to avoid this effect and the volume control adjusted to avoid overloading the sound section.

The next step is to concentrate on the picture, and the tuning cores of L1 and L3 should be set about mid-position so as to effect a compromise between vision and the sound. Finally the output coil L5 should be adjusted, keeping the picture quality at its normal standard and the sound at full volume.

The "fine" tuning control can then be set so as to obtain maximum sound with good picture quality.

Note that it may be possible, in some cases, to get a double appearance of the picture, but at only one setting of the oscillator core will sound and vision be received together.

Aerials

It is not possible to forecast what type of aerial will suit any particular locality as conditions vary so much from one point to another.

In localities close to the transmitter then an indoor aerial will probably be found to be satisfactory, but high signal strength is not the simple deciding factor. The very high frequencies used in Band III are much more prone to reflection than those on Band I and ghosts may be a problem. In this case, a directional aerial must be used, and if the resultant signal strength is too great attenuators can be fitted.

Before investing in a new aerial, viewers who are within the service area can try the converter on their existing Band I aerial. In many cases this will be found satisfactory.

For distant locations then a good Yagi array will be required and it is advisable to use low-loss feeder cable. A 100ft. length of cable which gives a loss of about 2 db. on Band I can give a loss of 8 db. or more on Band III. Such a loss could easily be mistaken for poor operation of the converter.

PRACTICAL WIRELESS JULY ISSUE NOW ON SALE PRICE 1/3

An oscilloscope employing a $3\frac{1}{2}$ in. tube and built in the form of three units in a box in which the top half containing the tube may be raised or lowered to facilitate viewing, is the main constructional feature of the current issue of our companion paper, "Practical Wireless." Construction and servicing are facilitated by the fact that each section of the 'scope is built as a separate unit and the complete instrument measures 16in. from front to back, 12in. high, and $9\frac{1}{2}$ in. wide. The containing case is of wood.

Other constructional features in this issue include an Electronic Timer, primarily designed for photographic purposes, but which has other uses; a valveless Radio Control Receiver employing two transistors and a diode; a Superhet Tuner in the series on Practical Amplifier Design; and an improvement to the High-power Tape Amplifier described in the March issue.

Articles on a Compact Stabilised High Voltage Supply, Using Test Instruments, Choosing and Using Modulator Valves, Servicing the Ultra Troubadour and Surplus Power Valves, in addition to the regular features, complete this July issue.

July, 1956

I.T.A. Northern Region Transmitters

SERVICE AREAS COVERED BY WINTER HILL AND EMLEY MOOR

THE map below shows approximately the areas in which the reception of signals from the authority's television transmitters at Winter Hill and Emley Moor should be possible. Winter Hill operates on Channel 9 and Emley Moor will be on Channel 10.

Provided that the correct type of receiving aerial recommended for the various localities is used and the appropriate conversion of single-channel receivers to obtain the alternative programme is made, reception conditions are 'expected to be as follows :

Inner unshaded zones (Primary Service Areas)

Most viewers in these areas, unless situated in specially unfavourable positions, for example, immediately behind high ground or screened by high buildings, will receive a satisfactory service.

Shaded zones (Secondary Service Areas)

Within these zones a substantial proportion of viewers will receive a satisfactory service, but there will be some local areas in which reception conditions will be poor.

Outside the shaded zones

Some favourably situated viewers will be able to obtain a reasonable service.


Extent of Service Areas

The Primary Service Area for the Winter Hill Transmitter extends in the north-west as far as Barrow-in-Furness (over 50 miles); in the north to Settle (about 35 miles); in the east to Glossop (approximately 30 miles); in the southwest to beyond Wrexham (approximately 50 miles); and in the west to beyond Rhyl (approximately 45 miles).

The Primary Service Area for the Emley Moor Transmitter extends in the north to Harrogate (about 30 miles); in the east to Hull (approximately 55 miles); and in the south to Newark (approximately 50 miles).

The Secondary Service Areas extend in most districts to places between five and 10 miles beyond the primary areas, but the Secondary Service Area of the Emley Moor transmitter extends to beyond Northallerton in the north and Grimsby in the east.

Special Note : In the central Pennine area, coverage will be "patchy" and some places may have poor reception from one or both transmitters.



July, 1956

,

PRACTICAL TELEVISION

۴.

8

P. & P., 1/- £2 orders post free. (Export Extra.) C.O.D. Service 1/5

- July, 1956	
C.R.T. ISOLATION TRANSFORMER Type A. Low leakage windings. Ratio I: 1.25 giving a 25% boost on Secondary. 2 v., 10/6; 1 4.9, 10/6; 6.3 v., 10/6; 10.8 v., 10/6; 1 4.3 v., 10/6; 6.3 v., 10/6; 6.0.8 v., 10/6; 1 4.3 v., 10/6; 6.3 v., 10/6; 10.8 v., 10/6; 1 4.3 v., 10/6; 6.3 v., 10/6; 10.8 v., 10/6; 1 4.3 v., 10/6; 10.8 v., 10/6; 1 4.3 v., 10/6; 10.8 v., 10/6; 1 4.3 v., 10/6; 10.8 v., 10/6; 10.4 v., 10/6; 10.8 v., 10/6; 10.9 v., 10.9	ALL WAYE RADIOGRAM CHASSIS ALL WAYE RADIOGRAM CHASSIS THEEE WAYEBANDS FIVE VALVES S.W. 16 m50 m. LATBET MULLARD M.Y. 200 m50 m. EATBET MULLARD M.Y. 200 m50 m. M. 200 m50 m
rels. Brand new boxed 17/6. Spools 5" metal 1/6, 7" plastic 4/3. O/P. TRANSFORMERS. Heavy Duty 50 nA. 4/6, Multratio, push-pull, 6/6. Tapped small pentode, 3/9, L.F. GROKES 15/10 H. 60/65 m.A. $0/-7$. NALNS TRANS. 330-0-0360, 30 mA. 6.3 \cdot , tapped 4 v. 4 a., 5 v. tapped 4 v. 2 a., ditto 250-0200, 21/- HEATER TRANS. Mapped princ. 300/250 v. 6.3 \cdot .	22in, records. Brand new in maker's boxes 1 High impedance lightweight Pick-up with sapphire needle, will match any Amplifier or Radio. Less than half price. £5.19.6. carr. and ins. 5/6.
 HEATTER TRANS. Tapped prim. 200/250 v. 6.3 v. Hamo, 76: tapped sec. 2, 4, 63 v. Hamo, 8/6. VCR97 TESTED FULL PICTURE, 82. COPPER FLATED AERIAL RODS. 4 x 12in. push fitting 3/e 40x. p. 8 p. 1/- RAADDI FORMERS with Cans and core, in. 80. ; iin. 106. HI. FORMERS with Cans and Core. 2 in. 9. w. 1 (in. and in. sq. x 2 in. 2/e a. 200/220 v. or 250/250 v. 1411. Stormer, 14(11. SOLOM Miget Lond Address and sec. 1 (in. 200/220 v. or 250/250 v. 1411. Stormer, 14(11. SOLOM Miget Lond, 24/- MAINS DROPPERS. 3 x 1 iin. Add, Silders, 3: amp. 750 ohms, 4/32 amp. 1,000 ohms, 4/3. ADROPERS. 3 x 1 iin. Add, Silders, 2/- MINS DROPERS. 3 x 1 iin. Add, Silders, 2/- Gin. Goodmans, 17/6. 7in. x 4in. Goodmans, 2/-, 6in. Goodmans, 17/6. 7in. x 4in. Goodmans, 2/-, 6in. Goodmans, 18/6. 0in. R. & A. 30/- Sin. M. E. 2.5 k. or 2 k. field, tapped O. P. tanals, 2/4, GSTA DIODE, 6.C. 2/ 7ystal Book, 17/6 Sin. M. E. 3.5 k. or 2 k. field, tapped O. P. tanals, 2/4, HIGH MESTANCE PHONES. 4,000 ohms, 17/6 pr. CRYSTAL MIKE INSERT by Acos, precision engineered. Size only 1 x 3/16in. Bargain Price 6(6, No transformer required. 	t E E E E E E E E E E E E E E E E E E E
SWITCH CLEANER Fluid, squirt-spout, 4/3 tin. TWIN GANG TUNING CONDENSERS, 4005 m(d. midget with trimmers, 8/6; 375 pf, n dget, less trimmers, 6/6; .0005 Standard size with trimmers and feet, 9/- ; less trimmers, 8/-; ditto, solied, 2/6, SPEAKER FRET. Woven Plastic TYGAN. Walnut tone. 121n, wide, 2/0, per (out. Expanded metal.	Automatically places Pick-up on records, 7in. 16in, or 12in. Auto Stop. Baseplate 12 z 8in. Height 2in. Depth 1in. Price \$7.15.6, post free.
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	 B.S.R. MONARCH. 3-speed Motor and Turn- table with selecting switch for 33, 45 and 78 r.p.m. records. 10.2 MONARCH Lightweipht 90 cps. 41th Acos Xtal turnover head, selparate Sappling styles for LP, and Standard records. SPECIAL OFFER, THE TWO ! \$4, 15.6, post 2/6. T.V. PRE-AMP. (MCMICHAEL). Turnable rhannels 1 to 3. (Will Amplify Output of your Band 3. Converter.) Midget 5ize, High Gain Fringe Model, B.V.A. Valve, Full instructions. Ready for use. (H.T. 200 v. L.T. 6.3 v., 3 amp. required.) BRAND NEW, 26/- each. SPECIAL MAINS POWER PACK for abuve, 25/- oxtra. F.M. TUNEE COLL KIT. 22/6. H.F. coil, Acrial coil, Oscillator Coil, two. I.F. Trans- formers 10.7 Mc/S. Detector transformer and heater choile. With elreuit and component list, mein four 6.4M6. Chassis and Dial, 19/6.
BP91 Special Prick-37/6-The Set X79 We have no connection wit RADIO COMPONEN	h any other firm. Please address all Mai

Tel. THO1665. Buses 133 or 68 pass door. 48-hour postal Service.

-

- 1	TELETRON BAND III CONVERTER For London, Midland and Northern Trans- missions.
	missions. Suitable all T.V. makes. T.R.F. or Superhet.
	Suitable all T.V. makes. T.R.F. or Superhet. Ready wound coils, two EF80 valves, all components, punched chassis, circuit diagaan, wiring plans. COMPLETE KIT for mains
	operation 200-250 V. A.C. 23,10.0.
	AS ABOVE less POWER PACK. Requires 200 v. 20 mA. H.T. 6.3 v. 6 a. L.T. \$2,5.0. Mains Transformer to above Spec 10/6 Min. Westinghouse Rect. ditto \$16 D. B. (10 %) for severe unit \$16
	Mains Transformer to above Spec 10/6 Mine Westinghouse Rect ditto
	B.B.C/I.T.A. crossover unit 7/6 Punched and drilled chassis 3/9
ASSIS ALVES	Larger chassis for Mains Model 6/-
LARD DBC41.	Full plans and circuit details 6d.
i0.	Volume Controls 80 CABLE COAX
dium- [.] dbaek,	Long spindles. Guarar- Semi-air spaced Poly- teed 1 year. All values thene insulated. in. dia.
ss Dial uilable.	10,000 ohms to 2 Meg. Stranded core. 9d. yd.
lvory. 1 from	Volume Controls Long spindles. Guaran- teed 1 year. All values No.000 ohms to 2 Mee. Standard core. 3/- 4/- 4/9 Ext. Spkr. Type, 3/
6.	COAX PLUGS 1/- DOUBLE SOCKET 1/3
IASSIS	BALANCED TWIN FEEDER, yd. 6d. 80 or 300 chuis. DITTO SCREENED per yd. 1/-, 80 ohms only.
	WIRE-WOUND POTS. 3 WATT. Pre-Set Min. T.V. Type. All values 25 ohms to 30 K., 3/- ea.,
*	50 K., 4) (Carbon 50 K. to 2 m., 3/) WIRE-WOUND 4 WATT. Pots, 21in. Spindle.
10in. and s! High	Values, 160 ohms to 50 K., 5/6 ; 100 K., 6/6. CONDENSERS. New stock. 001 mfd. 7 kV.
rencedle, than bali	T.C.C., 5/6. Ditto, 20 kV., 9/6; 100 pf. to 500 pf. Micas, 6d.; Tubular 500 v001 to .01 mfd., 9d.;
	v., 1/3; .1 msd 2,500 volts 5/6.
	SALARAGE TWIN FEEDER, 4.1.4.1.8.4.8.50 e.300 abnus. DITTO SCREENED per yd. 1/- 50 obnus oudy. WIVE WOVND POTE 5 obnus to 20 K. 3/- ea. 30 K. 4/- (Cárbon SZ 5 obnus to 20 K. 3/- ea. 30 K. 4/- (Cárbon SZ 5 obnus to 20 K. 3/- ea. 30 K. 4/- (Cárbon SZ 5 obnus to 20 K. 3/- ea. 30 K. 4/- (Cárbon SZ 5 obnus to 20 K. 3/- ea. 30 K. 4/- (Cárbon SZ 5 obnus to 20 K. 3/- ea. 30 K. 4/- (Cárbon SZ 5 obnus to 20 K. 3/- ea. 70 K. 4/- (Cárbon SZ 5 obnus to 20 K. 3/- 6 Values, 100 obnus to 60 K. 5/6 (10 K. 6/- ONDENSERS, New SCA. 400 m/d. 7 kV. 505.1.1/- (25.1/6) (25.1/5)
A .	1.5 pi. to 500 pf., 1/9; 515 pf. to 1.000 pf., 2/-,
% - 1	I.F. TRANSFORMERS 7/6 pair
	1.F. TRANSFORMERS 7/6 pair 465 Ke/s Slog tuning Miniature Can, 21in. x im. x im. High Q and good bandwidth. By Pye Radio. Data sheet supplied.
	NEW ELECTROLYTICS: FAMOUS MAKES
	$\begin{array}{c c c c c c c c c c c c c c c c c c c $
	$\begin{array}{cccccccccccccccccccccccccccccccccccc$
	8/450 v. 2/3 6/- 32+32/350 v. 4/6 8/500 v. 2/9 CAN TYPES 32+32/450 v. 6/6
	16/450 v. 3/6 Clips 36. $64 + 120/275$ v. 7/6 16/506 v. 4/- 16/450 v. 3/6 $64 + 120/350$ v. 11/6
Mixer Hi-Fi	25/25 v. 1/9 60/350 v. 5/8 12/6 12/6 12/6 12/6 12/6 12/6 12/6
stylus. Base-	50/50 v. $2/-8 + 16/450$ v. $3/-1600$ v. $1/600$ v. $1/600$ v. $6/6Selew Base Type 512, 8/500 v. 3/-: 16/500 v. 4/-.$
51in. .C.	SENTERCEL RECTIFIERS, E.H.T. TYPE FLY- BACK VOLTAGES, K3/25 2 kV., 4/3; K3/40 3.2
ready	kV., 6/-; K3/45, 3.6 kV., 6/6; K3/50 4 kV., 7/3 : K3/100 8 kV., 12/6; MAINS TYPE, RM1, 125 v.,
hanger	60 mA., 4/-; RM2, 100 mA., 4/9; RM3, 120 mA., 5/9: RM4, 250 v. 275 mA., 16/-,
unit	G.E.C. Neon Osgim, S.B.C., 2/6. COLLS Wearite, "P" type, 3/- each. Osmor Midget
apphire Switch	TELETEON, L. & Med., with re-action, 3/6.
s, 7in., x 84in.	ALUMINIUM CHASSIS, 18 s.w.g. undrilled
st free.	With 4 sides, riveted corners and lattice fixing holes, 24 in. sides. 7 x 4in., 4/6; 9 x 6in., 5/9;
Turn-	boles, 21in. sides. 7 x 4in., 4/6; 9 x 6in., 5/9; 11 x 7in., 6/9; 13 x 9in., 8/6: 14 x 11iu., 10/6; 15 x 14in., 12/6; 18 x 16 x 3in., 16/6.
and 78 v. A.C. weight	FULL WAVE BRIDGE SELENIUM RECTIFIERS, 2, 6 or 12 v. 13 amp. 8/9; 2 a., 11/3; 4 a., 17/6, CHARGER TRANSFORMERS, Tapped input 200/
eparate ecords.	CHARGER TRANSFORMERS. Tapped input 200/ 250 v. for charging at 2, 6 or 12 v., 11 amp., 13/6: 4 amp., 21/-
ost 2/6.	4 amp., 21/
unable	4 AND. 21 All BERMARDS books in stock, VALVE MANUALS I & II, 5/- én, part. VALVE MANUALS I & II, 5/- én, part. VALVE and TV TUBE equivalent's book 5/- AGDD HYDROMETER, New Ex Gort. Universi- able. Fracked in marcia case 7 x 1 in dia, 4/6.
of your 1 Gain -	ACID HYDROMETER. New Ex Govt. Unbreak- able. Packed in metal case 7 x 11in. dia., 4/6.
v., .3 each.	5 p. 4-way 2 wafer, long spindle 6/6
each. above,	2 p. 2-way, 3 p. 2-way, 8nort spindle 2/6 2 p. 6-way, 4 p. 2-way, 4 p. 3-way, long spindle 3/6
·	able. Packed in motal case 7 x 12 in. dia., 4/6. WAYECHANGE SWITCHES. 5 p. 4-way 2 wafer, long spindle
F. coil,	9 pin, 1/ MOULDED Mazda and Inct. Oct. 6d. BYG RSA RSG B9A 03 R76 with can 1.6
Trans- her and	VCR97 2/6, B9A with can 2/6. CERAMIC. EF50. B7G. B9A. Int. Oct. 1/ B7G with
oponent 1, 19/6.	can 1/9. BLACK CRACKLE PAINT, air drying, 3/-tin.
	ail Orders correctly as below.
307 \	WHITEHORSE RD., WEST CROYDON
OPEN	ALL DAY-(Wed. 1 p.m.) 10 page list 3d



Television Receiving Licences THE following statement shows

the approximate number of Television Receiving Licences in force at the end of April, 1956, in respect of receiving stations situated within the various postal regions of England, Wales, Scotland and Northern Ireland.

Region			Totàl
London Postal		•••	1,309,615
Home Counties			662.938
Midland		•••	1,003,570
North Eastern	•••	• • •	885,506
North Western			838,658
South Western			389,005
Wales and Border	Counties	•••	324,146
Total England and Scotland	Wales		5,413,438
Scotland			355,121
Northern Ireland			43,619
Am. ~ % .			
Total			5,812,178

During April the number of television licences increased by 72,585.

Fixed Advertising Positions

NO clarify the position concerning fixed advertising spots, following questions arising out of statements in the House of Commons in March by the Postmaster-General, the Independent Television Authority states that it has informed the programme companies that there is no reason why they should not enter into arrangements for the appearance of advertisements at fixed transmission times.

The practice of selling advertising space at fixed positions is commonplace in all forms of advertising, whether in newspapers, magazines or in outdoor advertising, and its extension into television advertising is a natural and legitimate development. There is certainly nothing which precludes it in the Television Act.

British Television for East Germany. AS a result of the Leipzig Fair last February, Pye, Ltd. have received an order for £30,000 worth of television transmission equipment for East Germany.

Two-thirds of this equipment, which is for studio broadcasting purposes, has already been delivered, and the remainder will be despatched shortly.

During the course of the fair. at which Pye exhibited a wide range of television, telecommunications and scientific instruments, many useful business contacts were made with the U.S.S.R., Poland, Czechoslovakia, Rumania, Bulgaria, China, India and Hungary, from whom Pye have already received an order for a television outside broadcasting van.

I.T.A. Northern Region (Lancashire) Transmitter

THE first Northern transmitter at Winter Hill, near Bolton; opened on Thursday, 3rd May. The programmes on all weekdays will be provided by Granada TV


network, and those on Saturdays and Sundays will be provided by A.B.C. television.

The transmitter operates on Channel 9 (vision 194.75 Mc/s, sound 191.25 Mc/s), and will have an effective radiated power of approximately 100 kilowatts. It is expected that viewers in most of Lancashire and Cheshire and parts of North Wales and Westmorland will be able to receive satisfactory signals.

BBC Colour Film Record

THE first film series to be made in colour by BBC television will be of Mrs. Doris Langley Moore's collection in the Museum of Costume at Eridge Castle, near Tunbridge Wells. Filming will begin in the summer.

There will be six 15-minute films, covering fashions from Elizabethan to modern times. A BBC spokesman said the films



The Transmitter Control Room at Winter Hill during installation tests. Mr. P. A. T. Bevan, Chief Engineer of I.T.A., is in the centre.

would be shown in black and white ' ' probably in the autumn.'

They are to be made in colour as a permanent record of the collection, which suggests that the corporation is preparing to build up a film library in colour ready for regular transmissions. An optimistic date for colour television would be 1959.

Granada TV network therefore family friend to thousands of homestart with a big audience level builders. advantage.

Baghdad TV Station

ON Wednesday, the 2nd Mav. which is the birthday of King Feisal of Iraq, the Middle East's first television station was opened in Baghdad by the King.

The majority of the grammes will be educational. It is planned to operate will be the first primarily cational service concentrating on child and adult education grammes, Iraq authorities will be giving a television service, which, in the educational sense, will be greatly vance of anvthing available in Great Britain, and parallel where else in the world. Pye supplied equipment and are manning the station for the

King Feisal making the inaugural broadcast when the new television station was opened at Baghdad in May.

Audience Research

THE A. C. Neilsen Co. on the completion of the first of its regular surveys in the Manchester area (at the end of April) reported 351,000 households ready to receive programmes from Granada TV network at Winter Hill,

This survey measured the number of homes equipped as of a mean date of March 28th, 1956. It is pointed out that the first

Neilsen survey in the London area prior to the opening transmissions revealed only 188,000 households, and in Birmingham the first survey revealed 245.000

Obituary

PHE death of well-known TV and radio handyman W. P. Matthew in March came as a sad surprise to his many friends, his colleagues in the publishing world and thousands of radio and TV fans.

time being.

Mr. Matthew's name was almost synonymous with Do It Yourself -he was, in fact, one of the first handymen to develop and encourage the post-war vogue which has now swept the country. More recently his Saturday afternoon Do It Yourself programme on households. ATV had made him almost a

Portuguese TV

pro-

what

edu-

pro-

Ťhe

in ad-

without

any-

the

THE Radio Corporation of America and General Electric of America have submitted lower tenders than Marconi and Pve of Britain for a television transmitting system for Portugal. The bids and delivery times were: R.C.A. £398,060-five months; G.E.A. £433,030-one to four months; Marconi £478,865-12 to 19 months; Pye £556,508nine to 18 months.

Party Political Broadcasts, 1956-57 AFTER joint consultations with the Government and the Opposition, the following arrangements for party political broad-casts in the year April 1st, 1956, to March 31, 1957, have been made by the corporation and the authority, in conjunction with the Independent Television programme companies.

There will be two series of party political broadcasts :

(1) Sound

Government	•••	4	
Opposition	•••	3	
Liberal		1	
(2) Television			• 2
Government	•••	4	
Opposition	•••	4	
Liberal		1	


The maximum durátion of the sound broadcasts will be 20 minutes. They will normally be given as hitherto at 9.15 p.m. in the BBC's Home Service. They will be repeated, in sound only, at the end of the BBC and Independent Television programmes.

The television broadcasts will be transmitted simultaneously in the BBC and Independent Television programmes. Their duration will be 25 minutes for two each of the Government and Opposition broadcasts and 15 minutes for the remainder. The longer broadcasts will be given at 7.05 p.m. and the shorter ones at 7.05 p.m. or at 7.15 p.m.

The Editor will be pleased to consider articles of a practical nature suitable for publication in "Practical Television." Such articles should be written on one side of the paper only, and should contain the name and address of the sender. Whils the Editor does not hold himself responsible for manuscripts, every effort will be made to return them if a stamped and addressed envelope is enclosed. All correspondence intended for the Editor, "George Newnes, Ltd., Tower House, Southampton Street, Strand, W.C.2.

Owing to the rapid progress in the design of radio apparatus and to our efforts to keep our readers in touch with the latest developments, we give no warranty that apparatus described in our columns is not the subject of letters patent.

Copyright in all drawings, photographs and articles published in "Practical Television" is specifically reserved throughout the countries signatory to the Berne Convention and the U.S.A. Reproductions or initiations of any of these are therefore expressly forbidden.



July, 195.6

PRACTICAL TELEVISION

561

BAND 3 T/V CONVERTER - 183 Mc/s-196 Mc/s £2-5-0 post free.

Suitable for London, Sutton Coldfield and Northern Transmission.

This Unit, comprising drilled chassis, 7in. x 4in. x 2½in., two miniature valves and met. rect., wound coils, res., cond., etc., is a slightly modified version incorporating variable oscillator tuning of the circuit shown in Wireless World, May, 1954. It has proved itself highly successful—over 5,000 sets have already been sold to buyers all over England. We invite you to visit us and see it in operation for your-selves. Suitable for most types of T/V Sets. T.R.F. or Superhet. Blueprint and circuit

details will be sent on application by return of details will be sent on application by return of post, 1/6, post free. Supply voltages required 200-250 v., 20 mA, H.T. 6.3 v. 1 a. L.T. Power pack components to fit chassis as illustrated, 30/- extra. Complete set wired, tested and aligned ready for use 20/- extra. Band 1, Band 3 Ae switching can now be added, switch kit, 6/6. Full range of Band 3 aerials in stock. Addustrs from 7/6 per set, dipoles-indeor 6/6, outdoor with cable, 13/9. Band 1-Band 3 Cross-over filter unit, from 10/6.

B.B.C. BREAK-THROUGH FILTER. Tunable filter unit for B.B.C. pattern rejection, 8/6.

Volume Controls | 80 CABLE COAX Midget Ediswan type. STANDARD lin. diam. nene insulated.

Long Spindles, Guaran-	Polythene insulated.
tced 1 year. All Log	GRADE "A" ONLY.
values 10,000 ohms to 2	8d. vd.
Meg-obms.	
No Sw. S.P.Sw. D.P.Sw.	SPECIAL Semi-air
3/- 4/- 4/9	spaced polythene, 80
Linear type volume con-	ohm Coan tin. diam.
trols 50,000 ohms to 2	Stranded core. Losses
Megohms less switch	^{cut 50%} . 9d. yd.
only 4 - each.	
CJAX PLU35 1/2	SOCKETS 1/-
COUPLER 1/3	OUTLET BOXES 4/6

TWIN FEEDER, 80 ohms, 6d. yd. : 300 ohms, 8d. yd. TWIN SCREEN FEEDER, 80 ohms, 1/- yd.

TWIN SCREEN TEEDER, SO GAINS, 1/- 90. TRIMMERS, Ceramic, 4 pf.-70 pf. 9d. 100 pf. 150 pf., 1/3; 250 pf., 1/8; 600 pf., 1/9, PHILPS Bechive Type-2 to S pf. or 3 to 30 pf., 1/3 esch. ESISTORS...Pref. values 10 ohms 10 megohms.

CARBON	WIRE WOUND
20% Type. 1 w., 3d.;	5 w.) 25 ohms→ 1/3
1 w., 5d.; 1 w., 6d.;	10 w. 10,000 1/6
2 w. 93.	15 w.) ohm3 2/-
10% Typ3, 1 w., 9d.;	5 w.) 15,000- 1/9
5% Type, ½ w., 1/	33,000 10-w. ohms 2/3
1% Hi-Stab, 1 w., 2/	
WIRE-WOUND POTS.	3w. LAB COLVERN, Etc.
Fre-Set Min. T/V. Type.	Standard Size Pots. 21m.
Knurled Slotted Knob.	Spindle. High Grade.
All values 25 ohms to 30	All Values. 100 ohms to
k., 3/- ea. 50 K., 4/	50 K., 5/6; 100 K., 6/6.
Ditto Carbon Track	W/W EXT. SPEAKER
50 K. to 2 Meg., 3/	CONTROL. 10 Ω , 3/
CONDENSERS Mica or	S. Mica. All pret. values.
3 pf. to 680 pf., 6d, each.	Ceramic types, 2.2-5,000
pf., as available, 9d. each	. Tubulars, 450 v. Hunts
and T.C.C., .0005, .001, .0	0.5, .01, .02 and .1 350 v.
9d., .05, .1 500 v. Hunts	Moldseal, 1/-, .25 Hunts,
1/65 Hunts, 1/91	,500 v. T.C.C. (Simplex).
SILVER MICA CONDEN	SERS10%.
5 pf. to 500 pf., 1/ 600	pf. to 3,000 pf., 1/3.
1% 1.5 pf. to 500 pf., 1/9.	515 pf. to 5,000 pf. 2
ALUMINIUM CHASSIS	18 s.w.g. Plain, undrilled,

eđ. ALUMINIUM CHASSIS.-10 S.W.Z. FABL, budfiled, Iolded & sides and riveled corners slattlee firing holes, Strong and soundly constructed with 21 in. sides. 7 in. x iu., 4/6 : 9in. x ioin., 5/9 : 11 in. x 7in., 6/9 : 13 in. x 9in., 8/6 : 14 in. x 11 in., 10/8 ; and 18 in. x 16 in. x 3in., 10/6.

16in. x 3in., 16/6. CARBON MIKE INSERT.—Superior quality type 21in. x 1in. Brand new and boxed only, 3/6 cach. BEIMISTORS.—CZI ior. 3a. heater chains, 3/6. COPPER ENAMEL WIES—1 ht. 14 to 20 s.w.g., 21. : 22 to 28 s.w.g., 2/6. : 30 to 40 s.w.g., 3/6. SWITCH CLEANER FUNCI, squit spont, 3/9 din. TWIN GANG TUNING CONDENSERS.—375 pf., Midget, 6/6. : ditto, with dust cover and trimmers, 8/6. .0005 mid. Standard size with feet, 8/6;

3 VALVE AMPLIFIER

3 VALVE AMPLIFIER, With variable Tone and Volume controls, 3 Midget B.V.A. valves, 4 watts output. Neg-feedback, Chassis isolated from Mains. A.C. 200/250 v. A quality amplifier at an economical price. PRICE \$3.19.6, Carr. 2/6. Wired and tested, 15/- extra. Circuit and instr., 1/6, ree with kit.



ELECTROLYTICS ALL	TYPES NEW STOCK
Tubutar Wire Ends	Can Types, Clips., 3d. ea. .8+8/450 v. T.C.C. \ 4/6
25/25 v., 50/12 v. 1/9	-8+8/450 v. T.C.C. 4/6
50/50 v., 4/500 v. 2/-	8+16/450 v. Hunts 5/- 16+16+8/350 v. 5/6
100/25 v. 2/- 9/500 v. Dub. 2/6	· 16+16/450 v. B.E.C. 5/6
8+9,500 v. Dub. 4/8	16+16/450 v. B.E.C. 5/6 16+16/450 v. Dub. 6/-
8+16 450 v. Hunts 5/-	32/350 V. B.E.C 4/-
16/450 v. B.E.C. 3/6	32+32/450 v. B.E.C. 6/6
16/500 v. Dub. 4/-	60/350 v. B.E.C. 6/6
16+16/450 v. T.C.C. 5/6	60+100/350 v. 11/6 60+250/275 v. 12/3
32/350 v. B.E.C. 4/-	64+120/275 v. 11/8
32/500 v. Dub. 5/-	100+200/275 v. B.E.C.,
32+32/350 v. B.E.C. 5/6	12/5
SENTERCEL RECTIFIER BACK VOLTAGES.—K3/: RV., (/-; K3/45, 3.6 kV.,	S. E.H.T. TYPE FLY-
BACK VOLTAGES	25 2 KV., 4/3; K.3/40 3.2
K3/100 S kV. 19/8 MAI	INS TYPE
K3/100 8 kV., 12/6; MAI 60 ma., 4/-; RM2, 100 r	na. 4/9 : RM3, 120 ma.
5/9; RM4 type; 250 v. 2	75 ma., 16/-
ENGRAVED CONTROL	KNOBS for din. Spindle.
Din. diam. Walnut or Standard engravings, 1/6	Ivory. Gold filled, 16
Standard (ngravings, 1/b	ea. Flain Rhobs to match
above, 15in. 10d. ea., 15in Ivory, 15in., 1/- ea.; 1ir	9d es. Pointer Knobs
Black with White Line 9d	Let a second second
WEARITE "P " TYPE CO	ILS. All ranges] to 7.
2/6 ea. Osmor Q Series langes from 3/3, Full 1	Coils. Slug tuned. All
langes from 3/3. Full 1	ange popular Coil Packs
·	
·	IÉRS 465 k/cs
I.F. TRANSFORM Brand new ex-manufacture size 21 " x 2" x 3", c wound coils, High"Q.	IÈRS 465 k/cs turer's midget L.R.T., lust core tuning, Litz Bargain offer, 7/6 pair.
I.F. TRANSFORM Brand new ex-manufam size 21" x 1" x 1", wound coils, High Q. MAINS TRANSFORMER	IERS 465 k/cs eturer's midget I.R.T., lust core tuning, Litz Bargain offer, 7/6 pair. SMade in our own
I.F. TRANSFORM Brand new ex-manufac size 21" x 1" x 3", c wound coils, High"Q. MAINS TRANSFORMER Workshops to Top Grade	IERS 465 k/cs tuner's midget I.R.T., hast core tuning, Litz Bargain offer, 7/6 pair. SMade in our own spec. Fully interleared
1.F. TRANSFORM Brand new ex-manufak size 21" x 1" x 1", o woind coils, High'Q. MAINS TRANSFORMER Workshops to Top Grade and impregnated. RA TYPE 250 y, 60 ma. F.	IERS 465 k/cs turer's midget L.R.T., lust core tuning, Litz Bargain offer, 7/6 pair. S.—Made in our own spec. Fully interleaved DIO AND AMPLIFIER W. sec., 5v. of 6.3 v. 1 a.
I.F. TRANSFORM Brand new ex-manufacture worling colf x x x x x worling colfs, High Q. MAINS TRANSFORMER Workshops to Top Grade and impregnated. RA TYPE250 v., 80 ma. F. ret. 6.3 v. 2.5 a. set Htr	IERS 465 k/cs tuner's midget I.R.T., last core tuning, Litz Bargain oliter, 7/8 pair. S.—Made in our own spec. Fully interleaved DiO AND AMPLIFER W. sec., 5 v. or 6.3 v. 1 a. s. 21/s. etc. C.R.T. HTR.
1.F. TRANSFORM Brand new ex-manufactive system of the sy	IERS 465 k/cs tuner's midget L.R.T., lust core tuning, Litz Bargain otter, 7/6 pair. SMade in our own spec. Fully interleaved DIO AND AMPLIFIER W. sec., 5 v. or 6.3 v. 1 a. s. 21/-, etc. C.R.T. HTR., leakage with or without
1.F. TRANSFORM Brand new ex-manufacture size 21" x 1" x 1", c worlind coling, High Qu. MAINS TRANSFORMER Workshops to Top Grade and impregnated. RA TYPE-250 v, 60 ma. F. rect. 6.3 v. 2.5 a. set Hir ISOLATION TYPE, Low 25% ex- hoed voltage	IERS 465 k/cs sturer's midget I.R.T., hust core tuning, Litz Bargain oliter, 7/8 pair. S.—Made in our own spec. Fully interleaved DIO AND AMPLIFIER W. sec., 5 v. or 6.3 v. 1 a. s, 24/r. etc. C.R.T. HTR., leakage with or without Ratup 1: 1 or 1 25 v.
1.F. TRANSFORM Brand new ex-manufacture size 21" x 1" x 1", c worlind coling, High Qu. MAINS TRANSFORMER Workshops to Top Grade and impregnated. RA TYPE-250 v, 60 ma. F. rect. 6.3 v. 2.5 a. set Hir ISOLATION TYPE, Low 25% ex- hoed voltage	IERS 465 k/cs sturer's midget I.R.T., hust core tuning, Litz Bargain oliter, 7/8 pair. S.—Made in our own spec. Fully interleaved DIO AND AMPLIFIER W. sec., 5 v. or 6.3 v. 1 a. s, 24/r. etc. C.R.T. HTR., leakage with or without Ratup 1: 1 or 1 25 v.
1.F. TRANSFORM Brand new ex-manular size 21" x 3" x 3" c woind coils, High Q. MAINS TRANSFORMER Workshops to Top Grad- and impregnated. RA minpregnated. RA 107E2230 v, 60 ma. P. rett. 6.3 v. 2.5 a, set Ht ISOLATION TFFELOW 25% sec. boost roltage. 10/6 ; 4 v. 10/6 ; 6.3 Ditto with mans prims Specials to order.	IERS
1.F. TRANSFORM Brand new ex-manular size 21" x 3" x 3" c woind coils, High Q. MAINS TRANSFORMER Workshops to Top Grad- and impregnated. RA minpregnated. RA 107E2230 v, 60 ma. P. rett. 6.3 v. 2.5 a, set Ht ISOLATION TFFELOW 25% sec. boost roltage. 10/6 ; 4 v. 10/6 ; 6.3 Ditto with mans prims Specials to order.	IERS
1.F. TRANSFORM Brand new ex-manular size 21° x 3° x 1° c world coils, High '0. MAINS TRANSFORMER Workshops to Top Grade and impregnated. RA TYPE .—250 v., 60 ma, F. rect. 6.3 v. 2.5 a. set. Htr ISOLATION TYPE . EXOLATION TYPE . EXOLATION TYPE . EXOLATION TYPE . EXOLATION TYPE . EXOLUTION TYPE . EXOLUTION TYPE . EXOLUTION TYPE . EXOLUTION EXOLUTION	 IERS - 465 k/cs tuner's midget L.R.T., lust core tuning, Litz Bargáin offer, 7/6 pair. S.—Made in our own spec. Fully interleaved DIO AND AMPLIFIER W. sec. 5 v. or 6.3 v. 1 a. s., 21/-, etc. C.R.T. HTR leakage with or without Ratto 1:1 or 1.25, 2 v. v., 10/6, 1.33 v. 10/6 arise 200/250 v. 12/6. ma., 5/-, 15 II. 100 ma., 16: 20 H. 150 ma., 15/6
1.F. TRANSFORM Braud new ex-manufaction of the semi- size 21' x 2' x 1', c worlind coline, High '0. MAIN3 TRANSFORMER Workshops to Top Grade and impregnated. RA TYPE 230 v. 60 ma. F. rett. 6.3 v. 2: 5. as et Hit ISOLATION TYPE, -Low 35°, sec. boost voltage. 10/6; 4 v. 10/6; 6.3 Ditto with manus primus Specials to order. LP , CHOKES10 Hr 65 10/6; 10 H., 120 ma., 10 Simplex, 10/6; Soundher	 IERS - 465 k/cs Ethers's midget I.F.T., hast core tuning, Litz Bargain oliter, 7/8 pair. S.—Made in our own spec. Fully interleaved DiO AND AMPLIFIER W. sec., 5 v. or 6.3 v. 1 a. s. 21/v. etc. C.R.T. HTR. leakage with or without Ratto 1:1 or 1.25, 2 v. v. 10/6; 1:3.3 v., 10/6 ma., 5/-; 15 II. 100 ma., /6; 20 H. 150 ma., 15/6; master, 10/6.
1.F. TRANSFORM Brand new ex-manufaction of the semi- size $21^{\circ} \times 1^{\circ} \times 1^{\circ}$. (would coild, sligh (2). MAINS TRANSFORMER Workshops to Top Grade and impregnated. RA TYPE.—230 v., 60 ma. F. ret. 6.3 v. 2.5 a. set Hir ISOLATION TYPE.—Low 25°_{0} sec. boost voltage. 10/6; 4 v. $10/6$; 6.3 Ditto with mains prims Specials to order. L.F. CHOKES.—10 H: 65 Jimples, 10/6; Sound Simples, 10/6; Sound	 IERS - 465 k/cs turer's midget L.R.T., lust core tuning, Litz Bargain oliter, 7/8 pair. SMade in our own spec. Fully interleaved DIO AND AMPLIFIER W. sec., J. v. of 6.3 v. 1 a. a. 21/- etc. C.R.T. HTR., leakage with or without Rattoj 1: 10 - 15, 2 v. v. 10/6; 13.3 v. 10/6 tries 200/250 v. 12/6. ma., 5/-; 15 H. 100 ma., (6; 20 H. 150 ma., 15/6 naster, 10/6.
1.F. TRANSFORM Brand new ex-manufaction of the second state of	 IERS - 465 k/cs sturer's midget L.R.T., lust core tuning, Litz Bargain oliter, 7/8 pair. SMade in our own spec. Fully interleaved DIO AND AMPLIFIER W. sec., J. v. of 6.3 v. 1 a. s, 21/- etc. C.R.T. HTR., leakage with or without Rattoj 1: 10 - 15, 2 v. v. 10/6; 1: 3.3 v. 10/6 arise 200/250 v. 12/6. ma., 5/-; 15 II. 100 ma., (6; 20 H. 150 ma., 15/6; naster, 10/6. DER 80/40. 18g., 3d. per. b.2/6.
1.F. TRANSFORM Brand new ex-manufaction of the second state of	 IERS - 465 k/cs sturer's midget L.R.T., lust core tuning, Litz Bargain oliter, 7/8 pair. SMade in our own spec. Fully interleaved DIO AND AMPLIFIER W. sec., J. v. of 6.3 v. 1 a. s, 21/- etc. C.R.T. HTR., leakage with or without Rattoj 1: 10 - 15, 2 v. v. 10/6; 1: 3.3 v. 10/6 arise 200/250 v. 12/6. ma., 5/-; 15 II. 100 ma., (6; 20 H. 150 ma., 15/6; naster, 10/6. DER 80/40. 18g., 3d. per. b.2/6.
1.F. TRANSFORM Brand new ex-manufaction of the second state of	 IERS - 465 k/cs sturer's midget L.R.T., lust core tuning, Litz Bargain oliter, 7/8 pair. SMade in our own spec. Fully interleaved DIO AND AMPLIFIER W. sec., J. v. of 6.3 v. 1 a. s, 21/- etc. C.R.T. HTR., leakage with or without Rattoj 1: 10 - 15, 2 v. v. 10/6; 1: 3.3 v. 10/6 arise 200/250 v. 12/6. ma., 5/-; 15 II. 100 ma., (6; 20 H. 150 ma., 15/6; naster, 10/6. DER 80/40. 18g., 3d. per. b.2/6.
1,F. TRANSFORM Braud new ex-manufac size 21' x 2' x 1', c worlind coint, High '0. MAIN3 TRANSFORMER Workshops to Top Grade and impregnated. RA TYPE250 v. 60 ma. F. rett. 6.3 v. 2: 5. as et Hit ISOLATION TYPE, -Low 35°, see. boost voltage. 10/6; 4 v. 10/6; 6.3 Ditto with mans primu Specials to order. LF, CHOKES10 H / c 5. 10/6; 10 H., 120 ma., 10 Simplex, 10/6; Sound, Log / c 10/6; Simplex, 10/6; Sound, Log / c 10/6; Simplex, 10/6; Sound, Log / c 10/6; Simplex, 10/6; Sound, 10/6; Sim, Celes, 18/6; 7 x. 18/6; Sim, Elac., 20/-; 21/6; Jion, R. and A., 5	IERS 465 k/cs burner's midget I.F.T., hast core tuning, Litz Bargain oliter, 7/8 pair. S.—Made in our own spec. Fully interleaved DiO AND AMPLIFIER W. sec., 5 v. or 6.3 v. 1 a. s. 21/v. etc. C.R.T. HTR., leakage with or without Ratto 1:1 or 1.25, 2 v. v. 10/6; 1.3.3 v., 10/6 ma., 5/-; 15 II. 100 ma., /6; 20 H. 150 ma., 15/6; master, 10/6. DER 40/40, 18g., 3d. per. o, 2/6. OHM. 5in. Celes., 17/6; in. Goodmans Elliptical, 8in. Goodmans Supeical, 8/0-; 125. Plessey, 35/-;
1.F. TRANSFORM Brand new ex-manufactures and the semi- size 21" x 1" x 1", c worlind coling, High '0. MAINS TRANSFORMER Workshops to Top Grade and impregnated. RA TYPE250 v, 60 ma. F. rect. 6.3 v. 2.5 a. set Hir HSOLATION TYPELow 35% see. boost voltage. 10/6 : 0 H. T20 ma., 10 35% see. boost voltage. 10/6 : 10 H. T20 ma., 10 35% see. boost voltage. L P. CHOKES10 Hr 63 10/6 : 10 H. T20 ma., 10 36m Cless, 18/6 ; 7 x 36m Cless, 18/6 ; 7 x 18/6 ; 10 in. R. and A., \$10, M. BLAC. 20, to him Real and A.	 IERS - 465 k/cs sturer's midget I.R.T., hast core tuning, Litz Bargain oliter, 7/8 pair. SMade in our own spec. Fully interleaved DIO AND AMPLIFIER W. sec., 5 v. or 6.3 v. 1 a, s. 21/v. etc. C.R.T. HTR., leakage with or without Ratoy 1: 1 or 1.25, 2 v. v. 10/6; 13.3 v. 10/6 arics 200/250 v. 12/6 mas. 5/-: 15 II. 100 ma., /6; 20 H. 150 ma., 15/6; master, 10/6. DER 60/40. 18g., 3d. per., 5/2/6. Jin. Goodmans special, Sin. Goodmans special, S/-, tappel O.P. tunas., 24/6.
1.F. TRANSFORM Braud new ex-manufac size 21' x 2' x 1', c worlind coint, High '0. MAIN3 TRANSFORMER Workshops to Top Grade and impregnated. RA TYPE250 v. 60 ma. F. rett. 6.3 v. 2: 5. as et Hit ISOLATION TYPE, -Low 35°, see. boost voltage. 10/6; 4 v. 10/6; 6.3 Ditto with mans primu Specials to order. LP, CHOKES10 H: 6.5 10/6; 10 H., 120 ma., 10 Simplex, 10/6; South Corder ERSIN MULTICORE SOL y1, 166, 44, pery 4; 41/6; 10(10, 200; 10/6; South ERSIN MULTICORE SOL y1, 166, 44, pery 4; 41/6; 10(10, 200; 18/6; 7 v. 18/6; Nin. Elac., 20/- 21/6; 10/6; Apet, 14/6; 15/6; Nin. R. and A.; Sin, ME, 2 & ohms field EFCORDING TAPE1	IERS 465 k/cs burner's midget I.F.T., hast core tuning, Litz Bargain oliter, 7/8 pair. S.—Made in our own spec. Fully interleaved DiO AND AMPLIFIER W. sec., 5 v. or 6.3 v. 1 a. s. 21/v. etc. C.R.T. HTR., leakage with or without Ratto 1:1 or 1.25, 2 v. v. 10/6; 1.3.3 v., 10/6 ma., 5/-; 15 II. 100 ma., /6; 20 H. 150 ma., 15/6; master, 10/6. DER 40/40, 18g., 3d. per. o, 2/6. OHM. 5in. Celes., 17/6; in. Goodmans Elliptical, 8in. Goodmans Supeical, 8/0-; 125. Plessey, 35/-;

F.M. TUNER-UNIT (87 mc/s-105 mc/s) by Jason.—As tested and approved by Radio tonstructor. Complete Kit of parts to build this modern highly successful unit, drilled chassis and J B. dial, coils and cans. 4 BVA miniature valves and all components, etc., for only 46.10.0, post free. SUPERIOR TYPE (1)ASS DIAL.—Calibrated in Mo/s and edge lit by 2 pilot lamps, 12/6 extra. Hiustrated handbook with full details, 2/- post free. free.

TRS RADIO COMPONENT SPECIALISTS (Est. 1946) (THO 2188) 70 BRIGSTOCK ROAD, THORNTON HEATH, SURREY

50 yards Thornton Heath Station. Listed above are only ; few item; from our very large stock.

Buses 130A, 133, 159, 166 & 190

Send 3d, stamp today for Complete Bargain List. Hours : 9 a.m.-6 p.m., I p.m. Wed. OPEN ALL DAY SAT.

-Terms :- C.W.O: or C.O.D. Kindly make cheques, P.O.s, etc. payable to T.R.S. Post/Picking up to 405.74., 115. 1/1, 315. 1/6, 315. 2. (1015. 2/9

PRACTICAL TELEVISION

A SPARK OF GENIUS!

I.C.S. training supplies the spark you need to further your career. The Courses I.C.S. offer are practical and up to date, they recognise the present emphasis on Frequency Modulation, and can help you attain one of the many well-paid posts that exist today in the radio world. Prepare yourself now, at home and in your own time, with the expert help of I.C.S. tutors. The cost of an I.C.S. Course is moderate and includes all books.

Among the I.C.S. Courses available are :

- FREQUENCY MODULATION ENGINEERING
- T/V ENGINEERING
- RADIO SERVICING
- RADIO ENGINEERING
- RADAR ENGINEERING
- BASIC
 INI
 ELECTRONICS
 ELE
 - INDUSTRIAL ELECTRONICS
- ELECTRONIC ENGINEERING

Complete the coupon below and post it to us for further details of the Course which interests you. Write to: Dept. 172B, I.C.S., Kingsway, W.C.2.

REDUCED TERMS FOR H.M. FORCES

INTERNATIONAL CORRESPONDENCE SCHOOLS DEPT. 172B, INTERNATIONAL BUILDINGS KINGSWAY, LONDON, W.C.2.
Please send FREE book onAge
NAME (Block letters please)
ADDRESS
OCCUPATION
INTERNATIONAL CORRESPONDENCE SCHOOLS




Aerials, 30/- plus 2/- carriage. Thousands of Valves, Condensers, Resistors—Can We Help You? MULLARD 510 and GEC 912 all specified parts and lists available. Catalogue, Book Lists, S.A.E. **RADIO SERVICING CO.**, 82, SOUTH EALING ROAD, LONDON, W.S. Tel.: EAL 5737. Next Sth. Ealing Tube, 65 Bus. 1 p.m. Wed.

July, 1956

562

PRACTICIAL IN JOIN



UNDERNEATH THE DIPOLE

TELEVISION PICK-UPS AND REFLECTIONS

"TOP TOWN"

THERE was no roughness or amateurishness about the "Top Town" show which the BBC put on at the Royal Hall. Harrogate, when Blackburn con-tested with Stoke-on-Trent in the battle of entertainment of the amateur field for 1956. Both teams put up very creditable performances with a wide variety of musical, dancing, magic and comedy acts. not to mention one or two surprise novelties. Amateur shows of this type are sometimes rather boring. but a high standard of talent and the excellent high-speed production work of Barney Colehan gave this "Top Town" show a gloss and polish which surpassed many professional variety shows. The excellent BBC Northern variety orchestra, conducted by Alyn Ainsworth, made a major contri-bution to this success, and sound reproduction on my set was excellent,

SOUND OUALITY

THE picture quality of commercial TV continues to improve at the same time as the sound Even seems to be deteriorating. the London Palladium Show appears to have a rough sound quality from time to time, with occasional bursts of excessive " top." One recent Sunday the Palladium orchestra seemed to be overcrowded with scratchy violins, so peaky was the sound pick-up of the higher frequencies. In common with many other viewers, I repeatedly changed over to the BBC to check whether the sound side of my receiver had developed trouble or that it had become detuned. Not enough trouble is taken with mixing on the sound side, in any case. Take Rediffusion's excellent presenta-tion of the Hallé Orchestra, for instance. Marvels are accomplished with the picture. When Ravel's "Bolero" was played, ingenious "Bolero" was played, ingenious montages and superimpositions


The individual instruments. balance of the sound had no connection with the picture. Instru-ments prominent in the picture should be given emphasis (but not too much emphasis) in the associated sound. Reproduction from sound film continues to be below par, and this is not always due to deficiences in the original photographic sound track. Cue marks on the picture for the ends of film sequences in news items. feature programmes or advertising spots should be abolished. They are intended as warnings or signals for change-overs to another reel (as in the cinemas) or to a following "live" sequence. It would be quite easy to fix metal staples in the film perforations which would complete an electrical circuit to ring a bell or buzzer—or even to actuate switches to make such change-overs entirely automatic. Presentation of TV shows is shows is If the worked out in seconds. shows are run to time, then automatic switching is the only answer. The human element, the variation in the reflexes of different engineers, cannot be relied upon all the time. Engineers, like actors, sometimes "fluff" their lines, and timing to the split second is more than ever essential with the kind of network

By Iconos

were employed, with close-ups of operation now being organised by the commercial TV companies.

SPLIT-SECOND TIMING

A-R's ambitious production of "Hamlet," with Paul Schofield, ingeniously gave the highlights of the Bard's work by truncating about three hours playing-time into an hour and a half. At least, nearly an hour and a half-for the final soliloquy after Hamlet's death was cut short and had to be faded out to give way to a timed commercial. This incident raised a chorus of protest in some quarters, which I think was a little unreasonable. The split-second timing necessary for network transmissions, with local interpolations at provincial stations, is unavoidable with commercial television, and producers will have to get used to the idea that they should rehearse and time the show to give a few minutes' leeway in the case of long, dramatic productions. In any case, the bloodthirsty last seene, the climax, had been magnificently played and came over with the horrific punch of an American gangster film. After this, and Hamlet's death, the restto me, at any rate-is anticlimax.,



One of the latest electronic devices - a nuclear-magnetic-resonance spectroscope seen at the second international instrument show in London."

"Hamlet" on commercial TV was highly successful, in which the rather over-busy foreground movements were considerably helped by the simple background designs.

MIDLANDS TV

ONGRATULATIONS, too, to the commercial TV contractors in the Midlands area-A.B.C. IV and A.TV—for their smooth and production technique. Now, both BBC centres in Manchester turn out a fine polished job. don't suppose many weeks will pass before the commercial TV theatres in both Birmingham and Manchester will be settling down to a steady output of slick, wellpresented and entertaining shows. The bottle-neck will then be scripts ; there is no dearth of



A view during the opening of a transonic wind tunnel. H.R.H. The Duke of Edinburgh opened this new site and watched the results televised to another part of the building,

start-up in the Birmingham area. where the I.T.A.'s Lichfield transmitter seems to have been well received and welcomed. Already can be seen the pattern of programme exchanges between the provincial and London contractors, with consequent economies for all parties. As was to be expected, the Palladium Show and "I Love Lucy " went out from the Midlands transmitter and several of the Birmingham items (from the former Astoria, Aston) were networked through to London. I liked A.B.C.-TV's "Film Fanfare" with I liked its clever interpolation of new and old films, but some of the Birmingham light musical programmes have been rather below standard in presentation, slickness and general appeal. However, it will be remembered that the BBC's TV presentations in Manchester, first in the old Rusholme film studio and then in their TV theatre at Hulme, both started off with a roughness of both technical values

scripts and material for sketches and revues, but the quality of material sent in has been very poor indeed. The Head of Associated Rediffusion was quite correct when he publicly stated this fact. The only way to obtain a sufficient supply of script material is to employ regular staff writers by the dozen. There is a tendency for the few good ones to write themselves dry.

COMEDY

THE bright long evenings of summer are yielding a rich The I.T.V. harvest of comedy. companies seem to be convinced that viewers will stay indoors only if it's laughter they're after, to borrow Tommy Trinder's slogan. And the crazier the show, the more popular it seems to be. Some features are so surrealistically crazissimo as to defy all descriptions. Such a show was "The guest, who stooged with Ted Ray Idiot Weekly," now superseded by before breaking into song, was "A Show Called Fred," in which Jack Buchanan.

July, 1956

Peter Sellers and his team of goons put over slick impressionistic comedy and burlesques in a most unorthodox manner. This show has improved week by week and, I am told by many viewers, is an acquired taste, like caviar or gorgonzola. So far as I am concerned. I am not very partial to either of these delicacies, but I certainly have acquired the appetite of a gourmet for this weekly dish of nonsense. The shows are put over at a tremendous pace and the burlesque items strike a new vein of comedy. possible only with the technical gadgetry of television. The bur-lesque of "Dragnet," for instance, in which the usual goon gang— Peter Sellers, Spike Milligan, Kenneth Connor and Valentine Dyall—were assisted by guest artists Paul Carpenter and Irene Handl, struck a new "high" in non-corny humour. I took a tape recording of the sound of this show, by the way, and find the playback (sound only, of course) just as funny as the original. Perhaps this is because I remembered the screamingly funny visual so well.

COMICS GALORE

OMEDY is not the monopoly COMEDY is not the monopoly of the I.T.V., however. Nor-man Evans was back again in The Norman Evans Show" on the BBC, assisted by Betty Jumel and Mrs. Shufflewick, in several amusing sketches and in his own inimitable " Over the Garden Wall" spot, in which he plays the garrulous dame. Norman's style of comedy is strictly conventional, in the music hall tradition, but his perfect timing of gags, his clowning and his warm personality come over TV excellently. The produc-tion, by Richard Afton, was care-fully planned and skilfully directed, and though the emphasis was naturally on comedy, there were pleasing ballet items by Nadia Nerina and Alexis Rassine, dancing routines by the Television Toppers and a knockabout act by Desmond and Marks. Another first-class BBC laughter show was the Saturday "Comedy Hour," in which Ted Ray and his brother-inlaw, Harold (Kenneth Connor) scored heavily with a simple sketch about a drawer that wouldn't open, and also "M.I. $5\frac{1}{2}$," in which Greta Gynt, Cameron Hall and Jimmy Wheeler assisted in a mix-up with pills of the same size intended for different purposes. A welcome

July, 1956

PRACTICAL TELEVISION



42-46, Windmill Hill, 152-3, Fleet Street, 29, Stroud Green Rd., 249, Kilburn High Ruislip, Midtx., E.C.4. Finsbury Park, N.4. Half day, Wednesday, Half day, Saturday. Half day, Thursday. MAIda Vale 4921.

565

Balances reception of ITA and BBC in all areas and avoids constant adjustment of controls. The Osmor is the only variable attenuator that will reduce the signal exactly to the required level. Easily Fitted—just plug in. Reduction ratios variable 2-1 to 10-1. An Essential with all types of Band III Converters. 15/-. From your Dealer-or direct.

ITA CONVERTERS

OSMOR VARIABLE Band I

A very efficient Band III Converter for all TV sets of any age (including TRF). Approximately one hour to build'! Guaranteed no breakthrough of Band I. Will convert any Band III Channel to any Band I Channel. Station switching. A.C. or A.C./D.C. Size

4% in. x 21 in. x 3in. Circuits, Wiring Diagrams and full constructional information, ready to fit inside your TV cabinet.

Complete Kit

Completely wired

FREE We keep right up to date in building the latest circuits published in "Practical Wireless," "Wireless World " and " Radio Constructor " and we stock the components specified. Send 71d. in stamps for circuits, fully descriptive literature together with coil and coilpack leaflets, component lists, chassis drawings and templates.

ITA Band III CONVERTER KIT

ATTENUATOR

Complete with all components, including power unit, for construction of an efficient Band III converter. Nothing else to buy. Circuit, wiring diagram, chassis templates and complete instructions, £6.19.9.

418 Brighton Road, South Croydon, OSMOR RADIO PRODUCTS LTD. ^{418 Brig} Surrey. Croydon 5148-9



July, 1956

from

im-

BAND I FILTER

BBC

proves picture. Suitable

Fitted in two minutes.

for all makes. 10/- inc. instructions.

ITA aerial and

Rejects

LONDON · LICHFIELD · MANCHESTER

65/-

80/-

ت ديسو

1

احد مراجع



The Editor does not necessarily agree with the opinions expressed by his correspondents. All letters must be accompanied by the name and address of the sender (not necessarily for publication).

A READER'S SUGGESTION

SIR, I have recently had an idea for prolonging the life of cathode-ray tubes. Why not have an "auxiliary" filament next to the usual one. This could be wired to separate pins and when the tube started to fail or the filament actually broke the wiring could be changed to the auxiliary filament.

This arrangement could also be used in expensive power valves as well.-A. J. PASSER (N.W.11).

AN OSCILLOSCOPE FOR TV

. . $S_{\rm Hg}^{\rm IR}$ -It has been brought to my notice that in Fig. 1, page 458 May issue, pins 9, 10 and 11 of the VCR139A are not shown connected to chassis. They should, of course, all go to chassis. -J. HILLMAN (N. Ireland).

COAXIAL TIP

SIR. The quickest, cleanest, safest and casiest way of stripping the polythene insulation from the end of the inner core of coaxial is : Prick round the polythene by pressing between thumbnail and index finger, then twist off the polythene sheath by giving it plenty of turns between thumb and finger, while withdrawing. This twists the multiple fine wires together and gives a lovely end for threading and for soldering with no danger of either melting polythene or cutting any wires.

Welcome back to PRACTICAL TELEVISION! I was using my "Viewmaster" on Alexandra Palace and Band III with Band III converter. Now that the BBC is on C.P. and lower sideband I only get a bandwidth of one Mc/s. Is there any alternative to the conversion described in Dec./May issue, and if so has it' been described in any past issues? If not I suppose 1 must dispose of my converter. Maybe many more readers are in similar circumstances now.-E. J. FISHER (Chiswick, W.4.).

TV BREAKTHROUGH

SIR,-1 am very interested in radio and am a keen reader of your excellent magazine. I was listening reader of your excellent magazine. I was listening on 84 metres when I picked up the TV sound channel of the Kirk o' Shotts transmitter. The signal was about strength 2-3 with heavy background noise. I wonder if any other reader has had the same experience or could explain how this happened. The TV was on in a different room.-VICTOR W. STEWART (14) (Edinburgh).

TURRET TUNER TROUBLES

SIR,-I have found with turret type tuners which use pre-aligned clip-in coils that the tags of adjacent coils are liable to touch and this can give rise to some very elusive interference showing as patterning and flashing on the screen.

As the fixing of the coils in these turrets is not very positive the interference may be intermittent and difficult to trace.

The fine limits worked to when producing these coils make it essential that the tags are bent inwards and the minimum of solder is used and even so,

because the coils tend to float contact may still be made.

As these tuners are normally supplied with coils only for the appropriate Band I channel and two channels in Band III, the easiest remedy is to space. out the coils, leaving a gap between each one, adjust the stops and reconnect the wires to the appropriate tags where separate gain controls are used.


I hope this may be of help to some of my fellow readers.—PETER ADKINS (Belvedere).

I.T.A. SOUND QUALITY

SIR,—I should like to make my protest regarding the quality of sound on the comments of the second s quality of sound on the commercial channel. The programme material for the most part is satisfactory, but the "commercials" are, for the most part, intolerable from a quality point of view. One-of my main grouses is that so many of the male speakers in these advertisements shout. It would almost seem as though they think that they will reach a larger audience if they raise their voices. This is particularly noticeable on one particular firm, and I think such a tendency to raucousness will lead to the introduction of "commercial killers" as in the States. These cut out the speech and the result will, therefore, be that the advertisers will reach a much smaller audience-in other words, if they go on shouting and making these adverts noisy they will kill the goose that lays the golden eggs. At my home we like one or two of these commercials, mainly because they are tuneful and the announcement is made in a quiet conversational tone. The moment the shouters" come on we turn off the volume. -D. DOWLING (East Ham).

I.F. TRIMMERS

SIR,-I wonder if you would allow me to air a grievance or make an appeal to manufacturers . of screened coils and I.F. transformers. I recently built your "SuperVisor" and found the trimming a most dangerous and awkward performance. This is due to the fact that the screened coils have trimmers at both top and bottom, with the result that you have to prop the set up on its side and work first on one side and then the other. I have found this applies to almost every commercial set also, and I would have thought that in these days it would be quite a simple matter to wind coils which could be mounted in a horizontal position on an insulated strip held in a vertical position in the cans, and thus have both trimmers accessible from the side of the can. This would enable all trimming and realignment to be effected without carrying out juggling feats with the weighty chassis. What about it, manufacturers? -H. J. P. NORRIS (YORK).





SOME FURTHER NOTES AND SOME QUERIES ANSWERED

VERY few queries have arisen from the details which have already been given in the past two issues on this particular test instrument, although there are one or two points which need further explanation. In addition, there are two small misprints to point out. These occurred in the illustration of the circuit, Fig. 1 on page 458 of the May

issue. In the circuit pins 9, 10 and 11 are shown connected together, but the earth connection was omitted from the junction point of these three electrodes. In other words, pins 9, 10 and 11 are all joined to earth. In the list of parts which appeared below this diagram, resistor R23 was wrongly indicated as being a pre-set. It is, of course, a normal $\frac{1}{2}$ watt fixed component.

Controls

568

Fig. 3 of the May issue indicated a drilling arrangement for the panel and in the prototype the controls were arranged as shown in the dia-gram on this page. The illustration which was originally in the heading is unfortunately not sufficiently clear to enable the individual markings to be identified, and so the illustration given here shows how all the various holes are utilised including a number of earth sockets which will be found extremely useful. It will be noted from the heading illustration already referred to that pieces of paper have been fixed to the panel beneath some of the indicating knobs and scales or indicating points drawn. It is, of course, possible to obtain transfers having scale form, and these present a much more professional appearance. Transfers are also available with letters or words so that other indications may also be made to give the finished instrument a professional finish.

Regarding Fig. 10 on page 459 of

the May issue, the seven large holes are for the international octal valveholders, and accordingly the diameter should be 11 in. The small hole on the upper portion is $\frac{3}{6}$ in. in diameter.

Finally, whilst we are always willing to assist readers to overcome difficulties met with in the building or operation of apparatus described in these pages, we regret that we cannot, for obvious reasons, give instructions for modifying a published circuit or using components and valves other than those specified. Whilst it might appear from a study of the circuit that a proposed modi-

fication might be in order, it is generally necessary to carry out a bench test in order to make certain that some unexpected trouble does not arise and obviously we cannot do this for every proposed modification.

The layout is not critical and although no practical layout or wiring diagram is given the two pictures of the top and underside of chassis on pages 456 and 457 of the May issue should enable the reader to make up the instrument.




Diagram of the controls for the finished instrument,

- July, 1956

PRACTICAL TELEVISION



VEWI

Specially prepared sets of radio parts from which we teach you, in your own home, the working of fundamental electronic circuits and bring you easily to the point when you can construct and service radio sets. Whether you are a student for an examination; starting a new hobby; intent upon a career in industry; or running your own business — these Practical Courses are intended for YOU — and may be yours at a Very Moderate Cost.

EASY TERMS FROM 15/-AMONTH With these outfits, which you receive upon enrolment, you are instructed how to build basic Electronic Circuits (Amplifiers, Oscillators, Power Units, etc.) leading to complete Radio and Television Receiver Testing and Servicing.



TELEVISION-With this

equipment you are instructed in the design, construction, servicing and testing of a modern high quality Television Receiver. ALL EQUIPMENT SUPPLIED IMMEDIATELY AND REMAINS YOUR PROPERTY

BEGINNER'S RADIO OUTFITS

- For carrying out basic practical work in Radio and Electronics, from first principles and leading to the design and building of simple Receivers.




The only Postal College which is part of a world-wide Industrial Organisation

1C.55

PRACTICAL TELEVISION

July, 1956





Whilst we are always pleased to assist readers with their technical difficulties, we regret that we are unable to supply diagrams or provide instructions for modifying surplus equimment. We cannot supply alternative details for constructional articles which appear in these pages. WE CANNOT UNDERTAKE TO ANSWER QUERIES OVER THE TELEPHONE. The coupon from p. 575 must be attached to all Queries, and if a postal reply is required a stamped and addressed envelope must be enclosed.

MARCONIPHONE VT85A

When I switched off last night the picture and sound were perfect, but now there is sound only. The screen is absolutely blank, but sound is O.K. As the tube is only a few months old I wondered if the EY51 rectifier valve could be the trouble, if so, how would I test same and would the heaters be alight? Both fuses in set are O.K. Therefore, if you can suggest cause of blank screen, no picture or raster I will be very pleased. -F. Tonkin (Grangetown).

In all probability the EY51 is at fault. We would suggest you make a spark test at the C.R.T. anode. If none is available, inspect the EY51, which is inside the can of the line output transformer (left side behind metal rectifier) and ensure its heater is glowing. As the valve is operated purely by the line timebase, the characteristic whistle of this should be listened for. If operation of the line hold control does not make this whistle distinctly audible, check the EL38 line oscillator and output valve. If the whistle is audible, but the EY51 is not being heated, it is advisable to replace this valve before proceeding further. A further possibility is that the $.001\mu \bar{F}$ EHT smoothing capacitor may be leaking. This carries the tag to which the tube anode lead is connected.

RGD 1800

I have a RGD television model 1800 which has developed trouble, namely low vision and low sound, either of which can be cured by the three trimmers at back, i.e. osc. trimmer for loudest sound, R.F. and aerial 1.5 Mc/s less vision carrier.

I find by juggling with these three trimmers I can either get normal sound or normal vision or both very poor. Also there is a slight fuzziness on the screen although outlines seem clear enough.

Could you please diagnose the trouble ?---W. T. (Sittingbourne).

The oscillator trimmer should be adjusted for maximum sound consistent with minimum sound on vision, and the aerial and R.F. trimmers for a compromise between sound and vision. If the

performance is still poor, we would suggest-that you check the aerial system, as it would seem that the trouble lies here, particularly in view of your remarks concerning "fuzziness" of the picture.

PYE MODEL LV30C

The line hold breaks up with a loss of focus. This persists for a few seconds and then clears, leaving the picture perfect as before. Sometimes the picture starts to pull slightly before the above fault comes on, but other times the fault starts without warning. A. B. (Dartford).

If the definition of the picture, as distinct from the focus of the raster, deteriorates when the fault occurs, then we feel that the trouble may be caused by a heater to cathode leak in the picture tube. You could check the condition of the video amplifier stage, when working normally and under the fault condition, in an endeavour to establish whether the trouble lies in this section. The associated value may be intermittently defective as this sometimes causes the same effect and tends to break up the line synchronising.

ULTRA V600

I have an Ultra V600, and I am having trouble with loss of picture height; the sides and bottom of picture stay normal.

I have changed the frame amplifier (V4) and have also changed C8, but this has not cured the trouble. I would therefore be very pleased to hear your comments on this.—J. S. (Dover).

Check the condition of the 6K25 and the resistors associated with the height control. Often, either this valve or one or more of the associated resistors becomes defective and causes a reduction of frame scan amplitude.

EKCO TC138B

I have a Teletron Converter and the only way I could cut out BBC was by soldering a length of coax. cable about 15in. long to the conversion chassis and then soldered to the convertor output lead; this cuts out BBC. At times the picture is very good, sometimes lines. I think it is BBC still breaking through. Can that short length of cable cause any trouble in the set? It has been working a month now. My aerial is a three-element inside the roof.—S. P.

The coaxial stub will not harm the receiver, but, as well as cutting out the BBC, may attenuate the ITA. If you are getting enough signal, however, we hardly feel that you need worry.

KB FV30B

I am repairing a television for a friend of mine and replaced the faulty line output transformer as well as the valve EY51 which had a burnt out heater. I replaced valve 6J5 and 6BG6 both 30 per cent. I cannot trace the trouble now which is no heater in EY51. In every other valve, including tube, I have heaters working. G. M. (Newark).

This indicates that the line timebase is inoperative. If the associated smaller components, such as resistors and capacitors, are in order, then you, will probably find that the line scanning coils have a shorted turn, assuming, of course, that the replacement line output transformer is in good condition and that it has been correctly wired in the circuit.

FERGUSON 988T

When the set is switched on the picture narrows with large blank spaces at the top and bottom. The picture heightens as set warms up; when fully warmed up the top of picture will rise or fall in a spongy fashion. To keep picture at reasonable shape I have to adjust vertical hold at intervals and occasionally the linearity control at the base of the set.

Sometimes, if left, the top of picture will heighten till objects on the screen become long. To bring the top down again I have to turn vertical hold clock-wise, then wait a short time till picture slips, then lock, the picture will then decrease in height leaving a gap again at top.

Incidentally, when height control is operated to decrease height the bottom alone comes up and is sometimes accompanied by a violent shivering up and down.

There is no effect on sound except for a scratching noise when volume is turned to switch off.—M. P. (Dagenham).

Check the condition of the two ECL80 valves situated in line on the left-hand side of the picture tube. These valves are concerned with the frame timebase; the one nearest the potentiometer (frame linearity control) is the frame amplifier. Also check the condition of the grid resistors and coupling capacitors.

ALBA T411

The picture develops the annoying fault of fly-back lines appearing as set runs for a time. All the valves have been renewed except the two EL33s, one of these, I believe, being the frame output. Both run very hot is this in order ? Furthermore, there are two EA50 valves that have not been replaced.

Tube has been fitted with isolating trans. Both brightness control and contrast appear to be in order, but set at minimum lines consistently appear. I trust you can help me.—F. H. (Peckham).

This is probably due to the picture tube having altered characteristics or impaired vacuum. The fact that you are employing an isolating transformer indicates that the tube is, in fact, defective. Unfortunately, masking one fault often causes another.

COSSOR 926

I cannot get a black and white picture when I advance the contrast control; the picture is grey and white, and when control is retarded the picture is clearer but dark, but since the Crystal Palace transmitter has been working the definition is slightly better. Could you please tell me if you think it is the tube at fault or the valves in the vision ?—G. S. (Streatham).

Without making tests it is impossible for us to give you the information required, but if the general brightness of the raster is normal on advancing the brightness control with the aerial removed and the contrast turned right down, then the trouble may lie in the vision I.F. strip or video amplifier stage. If the raster is weak, however, and the picture tends to turn peak white or negative when the controls are adjusted for a bright picture, then the tube is probably failing.

MURPHY V240C

I wrote to you several months ago concerning a fault on my Murphy V240C set.

You advised me to change the frame output valve (20P3). The fault was that the picture shrank back at the bottom of the raster by about $\frac{1}{2}$ in. after the set had really warmed up. I replaced the valve as suggested, and an immediate improvement resulted, but after about a week or so the fault came back again. I have since tried the original 20P3 in a friend's set, and it has given him no trouble at all.

Could the trouble be that the resistance of the frame scan coils is altering due to the rise in temperature as the set warms up ?---R. J. T. (Ashton-under-Lyne).

A slight alteration in frame scan amplitude occurs on almost all sets due to an increase of resistance of the frame scan coils as the set warms up. Unfortunately, there is little that can be done to alleviate the effect. If it is excessive, however, a definite fault in the frame timebase circuits should be suspected. The 20P3 valve is a frequent offender, and while it may cause the symptom on one type of set, it may work perfectly in another set of different characterresponds closely to the mains voltage tapping corresponds closely to the mains voltage in your area.

BUSH TV53

My Bush TV53 has been back to the dealer four times in the first three months of its life. The trouble is loss of picture (no raster). The first three visits to the dealer no faults were found. The fourth visit to the dealer the EY51 was replaced. The fault has returned again (two months later) and I would appreciate your view on the trouble.

The service sheet for this model states that early models had EY51/fitted, and later models EY86. Is there any connection between my trouble and this modification? What modification is required to the set to replace the EY51 with an EY86, other than the base connections ?—C. M. W. (Guisborough).

We do not think that the installation of an EY86 will solve the problem. In the majority of cases we have found that the intermittent collapse of EHT is due to a cathode-to-control grid short in the MW36-24 picture tube. We would, therefore, recommend you to call in your dealer and, if necessary, have the tube replaced within its guarantee period.

DEFIANT 1252

When set has been switched on and running for approximately five minutes or so, the brightness reduces, sometimes quickly, sometimes gradually. It can be restored with contrast sometimes, but on others, the picture becomes flat and brightness has to be increased. Increasing R.F. gain also has this effect (flatness). The picture still, even after these adjustments, has lost the crispness it had to start with.

Frame and line fill the tube. There may be a tendency to increase slightly. Three broad, whitish lines, apparent on whites only, on left half of the picture (line ringing?). Sound rather low.

Aerial, home made, in loft. T-match for best picture, T-match well towards centre. Is this in order ? ----N, L. (Saltburn).

We would suggest you first replace the 10F1 video amplifier valve which is in the centre of the chassis. If matters do not improve, inspect the underside of the receiver. On or near a tag strip on the rectifier side of the mentioned 10F1 is the vision detector crystal diode. This is a CG6-C. Quite often a defect in this crystal will produce the effect complained of. When replacing, note polarity, i.e., red end. RX159, 160/220 mc/s, with 1/VR91, 1/VR65, 1/CV66, 12/6; I.F. Amplifer 178 (for this), 16.5 mc/s, with valves, 15/6 (postage 2/6 each). R3355; new improved type, 37/6 (carr. 7/6). Condensers, Bak. tubular, 0.1/1.2 kV; 5/800 v.; 25/800 v.; 9d. each: 0.3/2.5 kV; 0.6/3.5 kVw; 25/1.5 kVw, 1/- each. Responser, RDFT, new, 160/220 mc/s, 12 valves, 15/- (carr. 7/6) or ZC3931, 9 valves, 15/- (carr. 7/6). Relays, 6v. 2 break 1/6. R1355 I.F. Strips; only, complete new with valves, 25/-; less valves, 12/6 (post 2/6). R.F. Units, Types 26 or 27, 27/6 (postage 2/6); RF24, RF25, soiled, 10/6. Motors, synch 3,000 r.p.m., 10 VA, 100 v. 50 c., new, 11/-, I.F.T.'s 10/13 mc/s, canned, new, 1/3. Power Pack, new, 200/260 v.; A.C. input, outputs 250 v. D.C., 80 mA., 6.3v., 3A and 24 v. 1A, D.C., 40/- (carr. 2/9). Receivers. miniature, 100/145 mc/s. Valves: 3/EF91, 2/EL94; I.F. 9.72 mc/s, new, 37/6; less valves, 7/6 (post 2/0). List and enquiries. S.A.E., please ! Terms, c.w.o. Postage extra. Immediate despatch. Closed week prior to Aug. Bank Holiday. W. A. BENSON (PT), 308, Rathbone Rd., Liverpool, 13. (STO 1604.)

TIME BASE, complete. 6in. tube, power pack, good order, £5/10/-; also 4-element Wenvoe Aerial. £4. 72: Barnfield Rd., Paignton, Devon. (Phone: 56144.)

DiRECT T/V REPLACEMENTS offer the most complete Handbook of T/V Components and Rewinds, price 17. T/V Components for all kit sets in stock. "Nuray" heater booster isolator for 2-volt C.R.T.s. just plugs in, 27/6, plus 2/- packing and postage, 134-136, Lewisham Way, S.E.14. (TIDeway 3696-2330.)

ALL DISTRICTS.—Television Technicians as Technical Agents. Write, TELEPATROL LTD., West St., Epsom. Surrey.

LOUDSPEAKERS repaired promptly. MODEL LOUDSPEAKER SERVICE, Bullington Rd., Oxford.

ALL DISTRICTS. An opportunity exists for Television Technicians to establish a business of their own. The business can be commenced in first instance in spare-time, showing an all the year round increasing income. Write, giving particulars of age, training, test equipment, experience, to TELEPATROL LTD., Federation House. Epsom.

TELEVISION INTERFERENCE. Receiver Filters, High-Pass E.5037, 30/-; Low-Pass E.5031, 30/-; Composite Band J/II, 49/6; Transmitter Filter E.5043-80dB, 1kW. £6. LABGEAR (CAMBRIDGE) LTD. Willow Place, Cambridge.



BBC & ITV

Manufactured specially to suit fringe and ultra-fringe conditions. Band I models in use 140 miles north of Kirk O'Shotts (check our position), and in many other distant locations and difficult areas. Complete in crackled steel case with builtin powerpack for 200-250 v. A.C.

Complete in crackled steel case with builtn powerpack for 200-250 v. A.C. **£5/5/-** P. & P. 2/-.

State channel used, or send 6d, stamp for illustrated details and some interesting fringe data.

ELECTRO - ACOUSTIC LABS.

N-ROSS-SHIRE-SCOTLAND

RATES: 4/- per line or part thereof, average five words to line, minimum 2 lines, Box No. 1/- extra. Advertisements must be prepaid and addressed to Advertisement Manager, "Practical Television," Tower House, Southampton St., Strånd, London, W.C.2.

T/V IN PERFECT WORKING ORDER from £14, carriage paid; all makes, many.sets suitable use anywhere. Impossible to show complete stocks here. Send s.a.e, for lists of latest bargains. 10in. Marconi £14, sin. Ekco £15, 12in. Ekco £22/10/-, 12in, Ferguson £24. THIS IS A GENUINE OFFER-NOT A "CATCH," 100'S SOLD EVERY WEEK. Callers welcomed, HIGH STREET RADIO, 284-6, High Street, Croydon, Surrey. (Phone: CROydon 9015.)

SERVICE SHEETS for hire, Radio, T.V. Components, Valves, etc., supplied, Send stamp for list. M. FOY, 6. Wykebeck Gardens, Leeds, 9.

b. Wykeberk Gardens, Eccus, S. MAKING YOUR OWN? Telescopes, Enlargers, Bincoulars, Microscopes, Projectors, or, in fact, anything that needs lenses. Then get our booklets "How to Use Ex-Gov. Lenses & Prisms," Nos. 1 & 2, price 2/6 ea. Also our stereo book, "3-D Without Viewers," price 7/6. Comprehensive list of lenses, optical, radio and scientific gear free for s.a.e. H. W. ENGLISH, Rayleigh Road, Hutton, Brentwood, Essex.

SUPER-TONIC SUN-RAY LAMPS. Ultra-violet Infra-red combined. Superb therapeutic quality, controlled output, automatic exposure. All mains. Listed £7/10/-, our price 80/-. S.A.E. illustrated brochure. Dept. 16, SCIENTIFIC PRODUCTS, Cleveleys, Lancs.

ENGRAVING.—Amateurs and trade surplus can be undertaken by getting in touch with A. G. ENGRAVING, now at 292. Earlsfield Road, London, S.W.18. (Tel.: BAT 9897.) (Engravers to well-known makers of Electronic Equipment used by the Aircraft industry, A.W.R.E., etc.)



TELEVISION COMPONENTS in stock for the P.T. SUPER-VISOR, TELE-KING, VIEWMASTER, E.E.; TELEVISOR and BAND III and wide angle modifications Frice lists available on request to :

J. T. FILMER, Maypole Estate. Bexley, Kent. Tel.; Bexleyheath 7267 SERVICE SHEETS, T.V. and Radio, over 2,000 models, sale or hire. Valves and Components, S.A.E. with enquiries. W. J. GILBERT, 24, Frithville Gardens, London, W.12.

R.F. UNITS, Types 27 or 26, 25/-; 25 or 24, 10/-; brand new with valves; post 2/6. E.W.S. CO., 69, Church Rd., Moseley, Birmingham.

SURPLUS R 3118, 14 metres for I.T.A., 50/-; R 1147B, B.C. 453B, 30/-; CRT's, 5/-; Magnifiers, 12/6. Many other bargains. Callers. 30, Parkhill Rd., E. Croydon, after 6 o'clock.

BUILDING A CONVERTER ? Here is your Fine Tuner. Ideal all types converter. Special air-spaced 7pf condenser corrects for drift and tunes sound and picture "spot on." Price 2/6, plus 6d, post. HOME RADIO, 187, London Road, Mitcham, Surrey.

VIEWMASTER BAND 3 SWITCH, platforms and screens to "P.T." specification; 25/9, p.p.d. E.K.E., 47, Arksey Lane, Bentley, Doncaster.

WANTED

WANTED, Valves 6F13. 6F15. 6U4, EY51, 5Z4, ECL80, KT61, 25A6, etc.; prompt cash. WM. CARVIS LTD., 103. North Street, Leeds, 7.

ALL TYPES of new radio valves wanted, small or large quantities; cash payment. R. H. S. LTD. (T), 155, Swan Arcade, Bradford, 1.

EDUCATIONAL

BUILD YOUR OWN TV and learn about its operation, maintenance and servicing. Qualified engineer-tutor available while you are learning and building. Free brochure from E.M.I. INSTITUTES, Dept. P.T.58, London; W.4. (Associated with H.M.V.)

I.P.R.E. Data for constructing .TV Aerial-strength Meter, 7/6; 5,500 Alignment Peaks for superhets, 5/9; sample copy "Practical Radio Engineer." 2/-. Membership-examination particulars, 1/-. Syllabus of seven postal courses free and post free. SECRETARY, I.P.R.E., 20, Fairfield Road, London, N.8.

Road, London, N.8. FREE ! Brochure giving details of Home Study Training in Radio, Television, and all branches of Electronics. Courses for the Hobby Enthusiast or for those aiming at the A.M.Brit.I.R.E., City and Guilds, R.T.E.B. and other professional examinations. Train with the college operated by Britain's largest Electronics organisation. Moderate fees. Write to E.M.I. INSTITUTES, Dept. P.T.28, London, W.4.





E.

	K/-			ILL	L V-1.			_
THE VALVE SPECIALISTS								
entley Acoustic Corp. Ltd.								
ĽI		;y Al	iuu	211C	μU	11 p. 1	.IU.	
38,	CI	HALC	ют	R0/	۱D,	N.W	.1	
				se 90				
	rade	goods		No se			ects.	
4 3 5	8/6 6/-	6U7 6V6G 6V6GT	7/-	9003	0/1 5/0 5/0	HL2 HL12C HL23 HL41 HL411 KBC3 KT33 KT33 KT33 KT33 KT33 KT33 KT33 KT	3/- 7/6 10/6	ļ
6	- B /F	levs .	7/6	AC/HI	ען ען און ען און און און און און און און און און או	HL41 HL41	7/6	
4 1)5	_11/- 7/6 5/-	6Z5 7AN7	12/6 12/6	AC6Pe AC/P4	n 6/6 8/-	KBC3	12/6	
N3 5	5/- 5/- 11/-	7AN7 7B7 7C5	8/6 8/-	AC/VI AP4	2112/0 2/0	3 KF35 3 KL35	2 8/+ 9/- 9/-	
5 5	9/- 7/6	7C5 7C6 7H7 7Q7	8/- 8/-	ATP4 AZ31	3/6 10/6	3 KT2 3 KT330	5/- 10/-	
4.53	7/6 7/6 12/6		(2/6 9/6	B309 B319	9/- 12/0	KTW0 KTW6	2 10 /- 1 7/- 2 7/-	
26 -	5/-	- 7Y4	8/6 8/6	BL63 CK523 CK525 CV85	7/6 6/6	5 KTZ41 163	6/8 6/- 12/6	
13C 2	7/6	S 10(2)	12/6	CK525 CV85 D1	6/6 12/6	LN309 LZ319 MH4	12/6 12/6	
4.5.7	8/6	10D1 10F1 12A6	11/-	D63 DAF96	3/6 5/- 5 9/6	MHL4 MHL4 MS4B		
, 6 5	2/6	12A5 12A5 12AH7 12AT7 12AU7 12AU7 12AX7 12BA6	15/- 12/6	IDCC90	8/6		15/- 8/6	
1 4	7/6	12AT7		DH77	8/6	OC3 OD3	8/ 6 8/6 7/6	
4 1	8/•	12AX7	10/6	DK96 DL2 DL35	9/6	OM6 P2 PABC2	110/6	ĺ
4 8	10/- 8/-	12BE6 12E1	10/- 30/-	DL35 DL96	15/- 11/- 9/8	PABC8 PCC84 PCC85	10/- 12/6	ĺ
ţ	10/- 8/6	12BA6 12BE6 12E1 12H6 12J5G7 12J7	-/30 -/- 3/-	DLS10 E1148	9/6 10/6 2/-	PCF80 PCF82 PCL83	$12^{/-}_{12}$	
4 B7	8/6 8/-	12J7 12K7	6/- 9/6 9/6	EA50 EABC8	2/- 2/- 2/-	Pen25	12/6	l
88 07 35 37	11/- 8/-	1257 12K7 12U5G 128A7 128C7 128C7 128G7 128H7	7/6 8/6	EAF42	10/- 12/8	Pen46 PL81	7/- 12/6 - 10/- 12/6	I
N5 37	6/6 12/6	128C7 128C7	7/6 5/6	EB34 EB41	₽/- 8/-	PL81 PL82 PL83 PL83	10/- 12/6	l
18 K5			5/6 5/-	EB91 EBC3	6/6 12/6	PM12 PM12M	6/6	l
K8 1.5	10/- 6/6	128H7 128J7 128K7 128K7 128Q7 128R7	6/- 8/6	EAF42 EB34 EB41 EB91 EBC3 EBC33 EBC41 EBF80 EC53	7/8 10/-	PM2B PY80	12/6 10/-	
25 28 26	7/6	12807 12887 138PA 138PA 1487 16A5 17Z3 19H1 19¥3 20L1	7/6	EBF80 EC52	11/- 7/6	PM12 PM12M PM2B PY80 PY81 PY82 PY83 QP22B OP25	10/- 10/-	
4	10/6	14R7	10/6	EC52 EC5 ECF80	15/-	QP22B QP25 Q8150/	10/- 12/6	ļ.
46 3(1	7/6	1723	10/-	ECC32 ECC33 ECC35	8 6 5/5 8/6	Q8150/	6/6 15 10/6	
5M 56	5/- 8 -	19¥3 20L1	10/- 19/6	ECC40 ECC81 ECC82			7/6 8/6 8/6	
46 16	12 6	20P3	12/6	ECC82	10/6	SP2(7) SP4(7) SP61	8/6 3/6	
V.c.	10/-	25X5 27	8/6 2/6	ECC83 ECC84 ECC85	10/6 12/6 10/ 6/-	SP61 SU2150	270	
N7 X6 X7	10/-1	28D7	7/- 7/8	ECC91 ECF82 ECH35 ECH42	6/- 15/-	TDD2A TH233		
	10/- 7/6 6/6		7/6 12/6	ECH35 ECH42	15/- 11/6 10/6	TP22	10/- 10/6 12/- 7/6	
16	8/ 0/8	30L1 35L6	12/6 9/-	ECH42 ECH81 ECL80	10/6 10/- 11/-	C22	7/6 10/-	
i AG	6/6 7/6	35Z4 35Z5	8/6 8/6	ECL80 EF6 EF9	11/- 10/6 12/6	U31 U50 -	10/- 9/- 8/-	
GT	10/8	35/51 41MP 41MTL			10/6	U52 U78	8/- 7/6 12/6	
7	96	45Z5	7/6 12/6	EF37A EF39 EF40	6/6 17/-	U251 UAF42	13/6	
3	10/6	50C5 50L6	10/- 8/8	EF41 EF42	11/-	UBC41 UCH42	10/- 11/- 10/6	
in M	6/6 2/6	57 58 61BI 61MP	8/6 8/6	EF40 EF41 EF42 EF50(A EF50(E EF54 EF80 EF85) 8/-	UF41 UF42 UL41	10/6 13/- 11/-	
G GT	5/5 5/8	61MP	10/6	EF80 EF85	10/-	UL41 UL46 UY41 V1507	11/- 10/6	
G	6/- 6/-	61B1 61MP 618PT 62TH 62V1 72 76	10/-	EF85 EF86 EF89 EF91	30.0	373 00.0		
G.	7/8 8/-	72 76	7/=	EF92	12/6 10/- 9/- 7/6 6/6 10/6	V1507 VLS492 VMP4(4 VMS4B VP2(7) VP4(7)	10/6	
67 161	8/-	77	3/- 3/6	EL32 EL41	6/6 10/6	VP2(7) VP4(7)	8/6 8/6	
(}	9/- 7/6	80 83			13/- 15/-	VP23 VP41	6/6 7/6	
	7/6 8/6	80 83 150B2 210LF 240QP	12/6 3/-	EL81 EL84 EL91	15/- 11/- 6/6	VP41 VP133 VR53	5/-	
GT	9/- 8/6	210LF 240QP 807 808 866A 885 056	2/6	EM34 EY51	10/-	X 66	6/- 10/6	
7 7 7	8/- 8/-	808 866A			$\frac{12}{-10}$	XFW10 XFY12 XH(1.5	8/6 1	
7	6/- 8/-	885 956	10/6	EZ41 EZ80	11/-	X8G11.5	4/	
7 7 7	8/-	956 1203 5763	10/8	E 185 EZ40 EZ41 EZ80 FC13 H30 H63 HK90	12/6 5/- 12/6	¥63 ¥65	7/6 10/6	
7	8/6 8/-	7193 7475	2/6 7/6	HK90	10/-	Z77 Z719	9/- 10/6	
STAL DIODES 0A71, GEX34, CG6E, M1, 0E, all 7/- each.								
have	4 12	all make		nerente	. Po	et 6d o	nah	

PRACTICAL TELEVISION

All boxed. Full maker's guarantee. Post 6d. each. Insurance (optional) 6d. per order. Shop hours 3,30 to 5,30, 8ak. I p.u. Why, not 'phone or wire that urgent order for immediate despatch C.O.D. 7 List and conditions of raile S.A.E.



GT. YARMOUTH Phones: 4794 and 3009 Grams : Spencer-West, Great Yormouth July, 1956

PRACTICAL TELEVISION



LABGEAR INTERFERENCE SUPPRESSOR


THE well-known Labgear range of interference suppressors and filters has been expanded and several of the earlier models superseded by improved designs.

The TV receiver filters plug into the TV receiver in between the aerial socket and aerial feeder. Three models are available.

Model E.5031, for the suppression of V.H.F. break-through has a cut-off at 70 Mc/s and negligible insertion loss over Band I.

Model E.5037 is a combined high-pass and I.F. filter. It is inserted in the aerial feeder lead and has a cut-off at 40 Mc/s. Negligible insertion loss on Bands I, II and III and provides complete protection against I.F. break-through. Very effective for removing patterning caused by R.F. heating, diathermy equipment, etc. This model has superseded earlier models' E.5027 and E.5028.

Model E.5038; this is the latest composite Band I/III filter, and is illustrated below. It employs a



. Labgear. Interference Filter, Type E.5038


printed circuit arrangement, and simply plugs in series with the aerial lead to the TV set and allows only Band I and Band III signals to pass; interference arriving at all other frequencies is effectively suppressed. Owing to the complexity of this model, there is slightly higher insertion loss than that obtained using either model E.5031 or E.5037. However, this is not serious except under extreme fringe conditions where the signal is very weak. Labgear filters require no form of adjustment whatsoever by the user and can be installed in seconds. —Labgear (Cambridge), Ltd., Willow Place, Cambridge.

SPENCER-WEST PATTERNING REMOVAL UNIT

WHEN employing an aerial type Band III Converter unit, patterning results when the receiver has a residual Band I signal present. This residual signal can be due to a number of causes, the chief one being that due to direct pick-up on the circuitry of the receiver. Other

causes are pick-up on the lead between the converter and the receiver, and "break-through" through the switching and other circuits of the converter unit. It is not a simple matter to avoid these residual signals particularly where

they are due to direct "pick-up" on the receiver. The Spencer-West type 54 and 54A patterning removal units provide a solution to the problem in the following manner: A signal equal in amplitude and 180 deg. out of phase with the interfering signal is fed into the aerial socket of the receiver. This signal is



The Spencer-West Pattern Remover

obtained from the Band I aerial and is then derived from a network which with two controls permit the required neutralising signal to be readily adjusted. The unit will remove completely the interfering signal, the only essential requirement being that the Band I aerial should be a properly installed one. Two types are available, the type 54 is for use at the receiver and provision is made for securing an isolated connection to the chassis of the receiver, thereby complying with the regulations applicable to A:C./D.C. type chassis. The type 54A is intended for use with converters whose output consists of a co-axial socket. Both the types 54 and 54A are priced at 25s. retail.— Spencer-West, Ltd., Quay Works, Gt. Yarmouth, Norfolk.

"VIEW MASTER " BAND III TUNER

MESSRS. DENCO are now supplying three kits-Modification Coil Set, Tuner Coil Set, and Switch and Fine Tuner Set—for the modification of this popular set. The coil set costs 20s. and includes all the parts as described in our December, 1955, issue, whilst the Tuner Coil set with screens, etc., costs 30s. A separate packet of switch parts—platforms, copper, spring wire, etc., costs 27s.—Denco (Clacton), Ltd., 357/9, Old Road, Clacton-on-Sea, Essex.




Published on the 22nd of each month by GEORGE NEWNES, LIMITED Tower House, Southampton Street, Strand, London, W.C.2, and printed in England by W. SPEAIGHT & SONS, Exmoor Street, London, W.IO. Sole Agents for Austral'a and New Zealand : GORDON & GOTCH (Asia), LTD. South Africa: CENTRAL NEWS AGENCY, LTD. Subscription rate including tostage, for one year : Inland 175, 6d., Abroad 165, 6d. (Canada 165.), Registered at the General Post Office for the Canadian Magazine Post

PRACTICAL TELEVISION

July, 1956







July, 1956

PRACTICAL TELEVISION


iii.


TELEVISION TUBES

COSSOR l2in. £6.10.0 l4in EMITRON l2in. £6.10.0 l4in	£7.10.0 17in. £10.0.0 £7.10.0 17in. £10.0.0 £7.10.0 17in. £10.0.0 £7.10.0 17in. £10.0.0							
MAZDA. 12in. only £6.10.0. 4 Weeks Delivery. All Tubes plus 12/6 carriage and insurance.								
SIX MONTHS' GUARANTEE								
JIA MONTHS GUARANTEE								
Converter M.I. Midlands area, high gain, own power supply, built in crossover unit £9.9.0 Converter M.2. Midland fringe area, own power supply £9.18.0 Crossover Box. Low loss								
ARTHURS HAVE IT!LARGE STOCKS OF VALVES AND C.R.T.S.AVO Model 7Avo Model 7Avo Model 8Avo Model 7Avo Model 8Avo Model 8Avo Model 8Avo Model 8Avo Model 9Avo Model 9Avo Model 1022Avo Matel 1022Avo Matel 1022Avo Model 1022Avo Matel 1022 <th><section-header><text><text><text><text><text></text></text></text></text></text></section-header></th>	<section-header><text><text><text><text><text></text></text></text></text></text></section-header>							

PRACTICAL TELEVISION

July, 1956





iv